

2005 FORD ECONOLINE E450 SUPER DUTY CUTAWAY VAN

Cutaway | 10 Cylinders | Gas

1FDXE45S95HA58808

Country of Assembly: United States

Last Reported Odometer: 28,852 KM

NO REPORTED ACCIDENTS*

LIEN CHECK



No Lien Records Found



No Accident/Damage Records Found



Last Registered In:
Alberta (Normal)



2 Service Records Found



U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information that was reported and available to CARFAX Canada as of December 14, 2021 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report + Lien Check (BC)

Lien Check

No lien records found in **Alberta**.

How We Check for Liens

CARFAX Canada uses the VIN to search government records in each Canadian province and territory (excluding Northwest Territories) where the vehicle is currently registered and where it has historically been registered. We do not check for liens or title in any U.S. state.

If a VIN has no registration records in Canada, we cannot check for liens. We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty equipment.

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.

CARFAX Canada Canadian Lien Guarantee



If for some reason our lien check fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian (\$5,000.00), whichever is lower.

Accident/Damage


There are no accidents/damage reported on this vehicle.

Registration

This vehicle has been registered in the province of **Alberta** in **Canada** with **Normal** branding.

We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*

Service Records

DATE	ODOMETER	SOURCE	DETAILS
 2005 Jan 28		Tim Martin Buick GMC Plymouth, Indiana, United States	Vehicle serviced Vehicle serviced
2021 Jul 14	28,852 KM	Thrifty Muffler Edmonton, Alberta, Canada	Vehicle serviced

Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact FORD or visit [Ford's website](#).




Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
 2005 Jan 28		Tim Martin Buick GMC Plymouth, Indiana, United States	Service Record	Vehicle serviced
2005 May 24		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2006 Jun 27		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed
2007 Apr 16		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed
2009 Aug 18		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed
2010 May 6		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed
2012 Apr 20		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed
2014 May 1		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Apr 21		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Apr 24		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Mar 23		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Jul 14	28,852 KM	Thrifty Muffler Edmonton, Alberta, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/Limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

Conditions of Use

© Copyright 2005 - 2022 CARFAX Canada ULC. All rights reserved.



Coastal Ford Burnaby

A division of Coastal Ford Sales Limited

5750 Lougheed HWY

Burnaby, BC V5B 2Z9

Phone: 604-294-6525

www.coastalfordburnaby.com



SO # 12S2663

SERVICE ORDER CUSTOMER COPY

Status
Printed 03/11/2022 12:14:47 PM

User cfbquand Page 1

Customer No 297338C
Attn: Cypress Auto Brokers
CYPRESS AUTO BROKERS
11919 MAPLE MEADOWS WAY
MAPLE RIDGE, BC V2X 3M7

Home (604) 465-3313 **Bus** (604) 465-3313
Cell (604) 465-3313 **Today**
Email

Fleet Type
Term CASH

Advisor Raff Pucci **Promised** 03/09/2022 5:00 PM **Tag** 2206
Shop S1 **Opened** 03/09/2022 12:20 PM **Location** w1 fence
Priority 880 **Cashiered** **PO #**

License No	Odometer In	Odometer Out	InServ Date	Stock No
	31576	31576	05/25/2005	
Year	Make	Model	Model No	Colour
2005	FORD	ECONOLINE CUTAWAY	E45	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FDXE45S95HA58808			05/25/2005	
Engine Size	6.8L SOHC EFI TRITON V10 ENGINE			Fleet #

Request	Description	Job	CSR	Status
2.2	ALL GAS ENGINE MOTOR HOME OR CUBE VAN MAINT SERVICE TO INCLUDE OIL FILTER . UP TO 7 LITRES OF OIL. TOP UP FLUIDS. MULTI POINT & BRAKE INSPECTION W ITH WRITTEN REPORT. TIRE ROTATION IF APPLICABLE \$ 325.00 PLUS LEVIES AND TAXES * EXCLUDES SYNTHETIC OIL	1	2597	Original

Labour	Description	Type	Amount
2.2	ALL GAS ENGINE MOTOR HOME OR CUBE VAN MAINT SERVICE TO INCLUDE OIL FILTER . UP TO 7 LITRES OF OIL. TOP UP FLUIDS. MULTI POINT & BRAKE INSPECTION W ITH WRITTEN REPORT. TIRE ROTATION IF APPLICABLE \$ 325.00 PLUS LEVIES AND TAXES * EXCLUDES SYNTHETIC OIL	C	285.00

Part	Description	Shp	Type	Price	Amount
FL 820 S	FILTER ASY - OIL	1	CSL	12.00	12.00
ENFILTR	EHC FILTER	1	CSL	0.90	0.90
CXO 5W20 BSP	MOTORCRAFT SAE 5W-20	6	CSL	4.00	24.00
ENOILR	EHC OIL	6	CSL	0.30	1.80
Technician	6ES -			Parts Total	38.70
Cause	service motorhome			Labour Total	285.00
Correction	perform service 2.5			Request Sub-total	323.70

Request	Description	Job	CSR	Status	
VRC	Ford Canada Vehicle Report QC550	2	2597	Approved	
				Parts Total	0.00
				Labour Total	0.00
				Request Sub-total	0.00

Request	Description	Job	CSR	Status	
44.01	REPLACE FRONT WIPER BLADES	3	2597	Approved	
Labour	Description	Type	Amount		
44.01	REPLACE FRONT WIPER BLADES	C	0.00		
Part	Description	Shp	Type	Price	Amount
WW 2002 PF	BLADE ASY - WIPER	2	CSL	21.22	42.44
Technician	6ES -			Parts Total	42.44
Cause	wiper blades required			Labour Total	0.00
Correction	replace wiper blades 0.2			Request Sub-total	42.44

Payment is required on invoice. No statement will be issued. **No refunds or exchanges on electrical, glass or special order parts.**
I agree that until payment in full of the within account, I hereby acknowledge the existence of a mechanic's lien in favour of the within dealer on the vehicle described herein in respect of the material supplied and services rendered under this work order for the full amount charged therefor. I further acknowledge that the said lien shall continue in force at all times, whether the vehicle is in my possession or possession of the dealer until the within account is paid in full. While the vehicle is in my possession it shall at all times be subject to repossession on the demand by the dealer until the within account is paid in full.

Indebtedness is hereby acknowledged in the sum of \$ _____ being all or the balance owing for repairs, parts and accessories described on this Invoice. **Terms:** Net 30 days, interest of 2% per month (26.8% per annum) charged on all overdue accounts.

Customer Signature X _____ Date: _____

Thank you for your business!

Coastal Ford Burnaby

A division of Coastal Ford Sales Limited

5750 Lougheed HWY

Burnaby, BC V5B 2Z9

Phone: 604-294-6525

www.coastalfordburnaby.com



SO # 12S2663

SERVICE ORDER CUSTOMER COPY

User cfbquand Page 2

Status
Printed 03/11/2022 12:14:47 PM

Customer No 297338C

Attn: Cypress Auto Brokers
CYPRESS AUTO BROKERS
11919 MAPLE MEADOWS WAY
MAPLE RIDGE, BC V2X 3M7

Home (604) 465-3313 **Bus** (604) 465-3313
Cell (604) 465-3313 **Today**
Email

Fleet Type
Term CASH

Advisor Raff Pucci	Promised 03/09/2022 5:00 PM	Tag 2206
Shop S1	Opened 03/09/2022 12:20 PM	Location w1 fence
Priority 880	Cashiered	PO #

License No	Odometer In	Odometer Out	InServ Date	Stock No
	31576	31576	05/25/2005	
Year	Make	Model	Model No	Colour
2005	FORD	ECONOLINE CUTAWAY	E45	
Vehicle ID No	Selling Dealer	Extended Warranty	Delivery Date	
1FDXE45S95HA58808			05/25/2005	
Engine Size	Fleet #			
6.8L SOHC EFI TRITON V10 ENGINE				

Labour	285.00
Parts	81.14
Supplies	37.05
SUB-TOTAL	403.19
GST	20.16
PST	0.00
TOTAL INVOICE	423.35

Payment is required on invoice. No statement will be issued. **No refunds or exchanges on electrical, glass or special order parts.**
I agree that until payment in full of the within account, I hereby acknowledge the existence of a mechanic's lien in favour of the within dealer on the vehicle described herein in respect of the material supplied and services rendered under this work order for the full amount charged therefor. I further acknowledge that the said lien shall continue in force at all times, whether the vehicle is in my possession or possession of the dealer until the within account is paid in full. While the vehicle is in my possession it shall at all times be subject to repossession on the demand by the dealer until the within account is paid in full.

Indebtedness is hereby acknowledged in the sum of \$_____ being all or the balance owing for repairs, parts and accessories described on this Invoice. **Terms:** Net 30 days, interest of 2% per month (26.8% per annum) charged on all overdue accounts.

Customer Signature X_____ Date: _____

Thank you for your business!

VEHICLE REPORT CARD



FORD SERVICE

MULTI-POINT INSPECTION AS RECOMMENDED BY FORD MOTOR COMPANY

Date: 03/09/2022 4:47:17 PM RO #: 12S2663

Name: CYPRESS AUTO BROKERS

Email: _____

Year/Make/Model: 2005 FORD ECONOLINE CUTAWAY

VIN: 1FDXE45S95HA58808 Plate #: _____

Odometer: 31576

- Owner's Guide checked and updated Reset oil life monitor
 Checked and completed open field service actions (recalls)

Ford Extended Service Plan: YES NO

Owner Advantage Rewards #: _____ Service Balance: _____

LEGEND May contribute to vehicle efficiency and promote a greener environment
 Checked and OK at this time Requires future attention Requires immediate attention

SCHEDULED MAINTENANCE ITEMS DUE*			
DUE	SERVICED	DUE	SERVICED
<input checked="" type="checkbox"/> THE WORKS	<input checked="" type="checkbox"/>	<input type="checkbox"/> Engine Air Filter	<input type="checkbox"/>
<input checked="" type="checkbox"/> Oil Change & Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/> Engine Coolant	<input type="checkbox"/>
<input type="checkbox"/> Tire Rotation - n/a in QC	<input type="checkbox"/>	<input type="checkbox"/> Transmission Fluid &/or Filter	<input type="checkbox"/>
<input type="checkbox"/> Multi-Point Inspection	<input checked="" type="checkbox"/>	<input type="checkbox"/> Cabin Air Filter	<input type="checkbox"/>
<input type="checkbox"/> Fuel Filter	<input type="checkbox"/>	<input type="checkbox"/> Spark Plugs	<input type="checkbox"/>
<input type="checkbox"/> _____ km Scheduled Maintenance			


*This is only a partial list of vehicle maintenance items and is NOT all-inclusive. Please consult your Owner's Manual for vehicle-specific maintenance requirements.

FLUID LEVELS		SERVICED
<input checked="" type="checkbox"/> Oil and/or fluid leaks		<input type="checkbox"/>

OK FILL	OK FILL	OK FILL
<input checked="" type="checkbox"/> Engine Oil	<input checked="" type="checkbox"/> Power Steering	<input checked="" type="checkbox"/> Transmission (if equipped with dipstick)
<input checked="" type="checkbox"/> Brake Reservoir	<input checked="" type="checkbox"/> Window Washer	<input checked="" type="checkbox"/> Coolant Recovery Reservoir

WIPER BLADES		SERVICED
<input type="checkbox"/> Wiper Test Performed	<input checked="" type="checkbox"/> Wiper Blades	<input type="checkbox"/>

BATTERY		SERVICED
State of Health	Battery Condition <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Factory spec cold cranking amps: <u>850</u>	Actual cold cranking amps: <u>900</u>	



SYSTEMS / COMPONENTS		SERVICED
LIGHTS / WINDSHIELD		
<input checked="" type="checkbox"/> Operation of horn, interior lights, exterior lamps, turn signals, hazard and brake lamps		<input type="checkbox"/>
<input checked="" type="checkbox"/> Windshield for cracks, chips and pitting		<input type="checkbox"/>
BELTS / HOSES / MOUNTS		
<input checked="" type="checkbox"/> HVAC system and hoses / lines for leaks and/or damage		<input type="checkbox"/>
<input checked="" type="checkbox"/> Engine cooling system, radiator, hoses and clamps		<input type="checkbox"/>
<input checked="" type="checkbox"/> Accessory drive belt(s)		<input type="checkbox"/>
BRAKE SYSTEM		
<input checked="" type="checkbox"/> Brake system (including lines, hoses and parking brake)		<input type="checkbox"/>
STEERING / SUSPENSION		
<input checked="" type="checkbox"/> Shocks / struts and other suspension components for leaks and/or damage		<input type="checkbox"/>
<input checked="" type="checkbox"/> Steering, steering linkages and ball joints (visual)		<input type="checkbox"/>
EXHAUST SYSTEM		
<input checked="" type="checkbox"/> Exhaust system (leaks, damage, loose parts)		<input type="checkbox"/>
TRANSMISSION / DRIVE AXLE		
<input type="checkbox"/> Clutch operations (if equipped)		<input type="checkbox"/>
<input type="checkbox"/> Constant velocity (CV) drive axle boots (if equipped)		<input type="checkbox"/>
<input checked="" type="checkbox"/> Drive shaft, transmission, u-joint and shift linkage (if equipped) and lubricate (as needed)		<input type="checkbox"/>

TIRE / BRAKE WEAR			
TIRE WEAR INDICATES		BRAKE WEAR INDICATES	
<input type="checkbox"/> Alignment check needed	<input type="checkbox"/> Wheel balance needed	<input type="checkbox"/> Brake measurements not taken this service visit	
LEFT FRONT	RIGHT FRONT	LEFT FRONT	SERVICED
<input checked="" type="checkbox"/> Tire Tread Depth: <u>13</u> /32" Tire Age: _____	<input checked="" type="checkbox"/> Tire Tread Depth: <u>11</u> /32" Tire Age: _____	<input checked="" type="checkbox"/> Brake Lining: <u>12</u> mm	<input type="checkbox"/>
<input checked="" type="checkbox"/> Tire Wear Pattern / Damage	<input checked="" type="checkbox"/> Tire Wear Pattern / Damage	LEFT REAR	
<input checked="" type="checkbox"/> Tire Pressure set to factory-recommended PSI	<input type="checkbox"/> Tire Pressure set to factory-recommended PSI	<input checked="" type="checkbox"/> Brake Lining: <u>12</u> mm	<input type="checkbox"/>
LEFT REAR	RIGHT REAR	RIGHT FRONT	
<input checked="" type="checkbox"/> Tire Tread Depth: <u>12</u> /32" Tire Age: _____	<input checked="" type="checkbox"/> Tire Tread Depth: <u>11</u> /32" Tire Age: _____	<input checked="" type="checkbox"/> Brake Lining: <u>12</u> mm	<input type="checkbox"/>
<input checked="" type="checkbox"/> Tire Wear Pattern / Damage	<input checked="" type="checkbox"/> Tire Wear Pattern / Damage	RIGHT REAR	
<input type="checkbox"/> Tire Pressure set to factory-recommended PSI	<input checked="" type="checkbox"/> Tire Pressure set to factory-recommended PSI	<input checked="" type="checkbox"/> Brake Lining: <u>12</u> mm	<input type="checkbox"/>
SPARE TIRE		Your Next Maintenance Appointment	
<input checked="" type="checkbox"/> Tire Pressure set to factory-recommended PSI Tire Age: _____	<input type="checkbox"/> Customer Declined Ford-Recommended Maintenance	Next Maintenance Service - Description	

Tires should be replaced after six years regardless of treadwear, including the spare, even if it has not been used.

Service Advisor: Raff Pucci Technician: Emanuel Sarantidis

COMMENTS: requires wiper blades

Your Next Maintenance Appointment		
Next Maintenance Service - Description		
Next Appointment Date (MM/DD/YY)	Price	Time



PROPANE SYSTEM RE-CERTIFICATION CHECKLIST

Payment Card Industry Data Security Standards prevent the use of credit card information sent through email or fax. A Client Service Representative will contact you within three business days to complete any payment process required.

Note: Any personal information collected is handled in accordance with the British Columbia Freedom and Protection of Privacy Act. If you have questions about the collection, use, or disclosure of this information, contact the Records, Information and Privacy Analyst for the Technical Safety BC at 1-866-566-7233.

A. Inspection (please print)

Vehicle owner's name: Ambassador RV Cypress Auto Broker
Decal number: 498891
Suite No.: Street no.: 7973 11919 Street name: River Maple Meadows Street type: Road way
City: Delta Maple Ridge Province: BC Postal Code: V4G 1B4 V2X 9G9
Vehicle make: Forest River Vehicle type: Class C Serial number: FRF 013379

Propane Cylinder and Tanks:

- OK Rej. Date stamp
Condition and paint
Securely mounted
Vented enclosure
Location

Fridge Installation and Venting:

- OK Rej. Model: RM2652
Sealed from coach interior
Vented to coach exterior
Installed to approved standards
Operates to approved standards
Proper flame characteristics
Fittings leak tested while operating

Oven, Range Installation and Venting:

- OK Rej. Model: CLY1631B0H
Adequate ventilation as per code
Installed to approved standards
Operates to approved standards
Proper flame characteristics
Fittings leak tested while operating

Regulators (replacement must be 2-stage):

- OK Rej. Securely fastened
Vented properly
Protective covering
11" w.c. working pressure with 70% load
13" w.c. lock-up (5 minute minimum duration)

Furnace Installation and Venting:

- OK Rej. Model: SF25F
Direct-vented and sealed from coach-interior
Installed to approved standards
Operates to approved standards
Proper flame characteristics
Fittings leak tested while operating

Propane Gas Lights:

- OK Rej. Model:
Adequate ventilation and clearances to combustibles
Installed to approved standards
Proper flame characteristics
Fittings leak tested while operating

Hoses and Lines:

- OK Rej. Hoses condition
Excess flow restrictor
Bulkhead hose condition
Lines secured, protected and undamaged
Exterior flare nuts
Single approved appliance connections
No interior line fittings
Line and hose leak pressure test 8" w.c for 3 min. (no drop allowable)

Water Heater Installation and Venting:

- OK Rej. Model: SW60
Direct vented and sealed from coach-interior
Installed to approved standards
Operates to approved standards
Proper flame characteristics
Fittings leak tested while operating

Catalytic Heaters (canvas walled unit only):

- OK Rej.
Installed to approved standards
Operates to approved standards
Proper flame characteristics
Fittings leak tested while operating

Warning Labels:

- OK Rej.
All warning labels as required by code

Note: All combustion air and combustion vent outlets shall meet or exceed, the clearances required by code from fuel fill points, openings, windows and doors.

I, the undersigned, verify the gas system for the vehicle listed above is: [X] Acceptable [] Rejected for re-certification in compliance with the BC Safety Standards Act and Regulations.

Operating permit holder name: Paul's Mobile RV Service

Suite no.: Street no.: 30125 Street name: Spallin Street type: Ave
City: Abbotsford Province: BC Postal Code: V4X 2A5
Operating permit number: 502 Fitter's name: Daniel Brama Fitter's number: 24982
Signature: Date: Jan 17 2021

Technical Safety BC is working towards going paperless! Participate by signing up for email correspondence.

