

## 2009 FORD ESCAPE XLT

Sport utility vehicle | 6 Cylinders | Gas


1FMCU03G39KA40869

Country of Assembly: United States

Last Reported Odometer: 55,640 KM



Accident/Damage Records Found



Last Registered In:  
**British Columbia (Normal)**



1 Service Record Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)



**This vehicle history report is based on information that was reported and available to CARFAX Canada as of March 14, 2022** (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# Vehicle History Report (BC)



## Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2010 Apr 24	British Columbia, Canada	
	Claim: COLLISION	\$0.00



## Registration

This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

*We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2014 Jul 31	55,640 KM	Magnuson Ford Abbotsford, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>PCM reprogrammed</li></ul>



## Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact FORD or visit [Ford's website](#).



## Stolen Vehicle Check

This vehicle is not actively declared stolen.



## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
------	----------	--------	-------------	---------

2008 Nov 8		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2009 Oct 3		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2009 Dec 19		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2010 Jan 2		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2010 Mar 6		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2010 Apr 24		Insurance Records British Columbia, Canada	COLLISION	
2011 Mar 5		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2012 Mar 3		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2013 Mar 9		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Mar 8		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Jul 31	55,640 KM	Magnuson Ford Abbotsford, British Columbia, Canada	Service Record	Vehicle serviced
2015 Mar 7		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Mar 5		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Oct 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Mar 10		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Mar 10		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Mar 5		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Mar 9		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or



# Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)

#### ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/Limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

Conditions of Use

© Copyright 2005 - 2022 CARFAX Canada ULC. All rights reserved.





UNIT #8 - 20071 113B AVENUE

MAPLE RIDGE, BC V2X 0Z2

O: 604 460 7142

C: 604 721 1432

RIDGEMOTORSAUTOREPAIR@GMAIL.COM

**MULTI-POINT INSPECTION**

Name: CYROSS AUTO BECKER Year/Make/Model: 2009 FORD ESCAPE KMs: 108791

RO#: 2815 VIN: 1FMCU03G39KA40869 License: \_\_\_\_\_

CHECKED AND OK

FUTURE ATTENTION

IMMEDIATE ATTENTION

INTERIOR/EXTERIOR	
NOTE ANY EXISTING BODY DAMAGE	
Lights (Head, Brake, Turn, Parking)	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Windshield / Glass	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Wipers	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Horn / Interior Lights	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

TIRES		
TREAD DEPTH		
<input checked="" type="checkbox"/> 7/32" or greater	<input type="checkbox"/> 3/32" to 6/32"	<input type="checkbox"/> 2/32" or less
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 11/32"	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 11/32"	
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 11/32"	RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 11/32"	
	Wear Pattern/ Damage	Air Pressure
	LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> <input type="checkbox"/>
	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	BEFORE SHOULD BE
	LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
	RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
		LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
		RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
		Based on Mileage and Wear:
		<input type="checkbox"/> Alignment
		<input type="checkbox"/> Balance
		<input type="checkbox"/> Rotation
		<input type="checkbox"/> New Tire

BATTERY	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

BRAKES	
BRAKE PADS / SHOES	
<input checked="" type="checkbox"/> Over 5 mm (Disk) or 2 mm (Drum)	
<input type="checkbox"/> 3-5 mm (Disk) or 1.01-2 mm (Drum)	
<input type="checkbox"/> Less than 3 mm (Disk) or 1 mm (Drum)	
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

UNDERHOOD	
Oil Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Transmission Fluid	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Power Steering / Brake Fluid	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Coolant / Antifreeze	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Air Filter	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Cabin Filter	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Belts	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

COMMENTS
FRONT PADS 10mm
REAR SHOES 4mm

UNDER VEHICLE	
Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Suspension & Steering	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Driveline (Axles / CV Shaft)	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Rear Differential Fluid Level & Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Exhaust System / Shocks & Struts	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

INSPECTOR: JLM DATE: 3/18/2022

Ridge Motors Auto Repair and Tires  
 Unit 8 - 20071 113B Avenue  
 Maple Ridge, BC V2X 0Z2  
 (604) 460-7142

# Invoice

Date	Invoice #
3/17/2022	2815

GST/HST No. 758148118

<b>Invoice To</b>
Cypress Auto Brokers 11919 Maple Meadowa Way Maple Ridge BC V2X3M7

<b>Vehicle Description</b>
2009Ford Escape

ODO IN	ODO OUT	Plate	VIN
108781			1fmcu03g39ka40869

Quantity	Item	Description	Price Each	Amount	Tax
2	I_Inspection_Gen...		80.00	80.00	G
	P_Misc	front link ends	28.47	56.94	G
0.7	L_Misc_Suspension	replace front link ends	65.00	45.50	G
		GST on sales	5.00%	9.12	
<b>Sales Tax Total</b>				\$9.12	
<b>Total</b>				\$191.56	

I hereby authorize you and your employees to carry out the repair work described above and to purchase on my account any parts and materials necessary to carry out the repair work subject to the estimate described above. I hereby authorize you and your employees to operate the vehicle listed above in connect with the repair work, including operation for the purposes of testing, inspection or delivery. I HERBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repair work authorized hereby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repair work.

By signing below I acknowledge and agree to the terms and conditions above

Customer Signature \_\_\_\_\_