


2016

4X4TVBW25G9112229
Country of Assembly: n/a
Last Reported Odometer: n/a

NO REPORTED ACCIDENTS




No Accident/Damage Records Found



Last Registered In:
British Columbia (Normal)



0 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information that was reported and available to CARFAX Canada as of January 18, 2022 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report (BC)



Accident/Damage

✓ There are no accidents/damage reported on this vehicle.



Registration

✓ This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Open Recalls

✓ No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact .



Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Jun 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2017 Oct 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/Limitation.html>.
ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)

© Copyright 2005 - 2022 CARFAX Canada ULC. All rights reserved.



PROPANE SYSTEM RE-CERTIFICATION CHECKLIST

Payment Card Industry Data Security Standards prevent the use of credit card information sent through email or fax. A Client Service Representative will contact you within three business days to complete any payment process required.

Note: Any personal information collected is handled in accordance with the British Columbia *Freedom and Protection of Privacy Act*. If you have questions about the collection, use, or disclosure of this information, contact the Records, Information and Privacy Analyst for the Technical Safety BC at 1-866-566-7233.

A. Inspection (please print)

Vehicle owner's name: <u>Cypress Auto Brokers</u>			Decal number: <u>499490</u>		
Suite No.:	Street no.: <u>11919</u>	Street name: <u>Maple Meadows Way</u>	Street type:		
City: <u>Maple Ridge</u>		Province: <u>BC</u>	Postal Code: <u>V2X 9G9</u>		
Vehicle make: <u>Forest River</u>	Vehicle type: <u>Trailer</u>	Serial number: <u>ORUBT207 R0</u>			

<u>Propane Cylinder and Tanks:</u>		<u>Fridge Installation and Venting:</u>		<u>Oven, Range Installation and Venting:</u>	
OK	Rej.	OK	Rej.	OK	Rej.
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Date stamp		Model: <u>DM2652</u>		Model: <u>SRNA3L BSE</u>	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Condition and paint		Sealed from coach interior		Adequate ventilation as per code	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Securely mounted		Vented to coach exterior		Installed to approved standards	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Vented enclosure		Installed to approved standards		Operates to approved standards	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Location		Operates to approved standards		Proper flame characteristics	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		Proper flame characteristics		Fittings leak tested while operating	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		Fittings leak tested while operating			

<u>Regulators (replacement must be 2-stage):</u>		<u>Furnace Installation and Venting:</u>		<u>Propane Gas Lights:</u>	
OK	Rej.	OK	Rej.	OK	Rej.
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Securely fastened		Model: <u>SF30Q</u>		Model: _____	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Vented properly		Direct-vented and sealed from coach-interior		Adequate ventilation and clearances to combustibles	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Protective covering		Installed to approved standards		Installed to approved standards	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11" w.c. working pressure with 70% load		Operates to approved standards		Proper flame characteristics	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13.5" w.c. lock-up (5 minute minimum duration)		Proper flame characteristics		Fittings leak tested while operating	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		Fittings leak tested while operating			


<u>Hoses and Lines:</u>		<u>Water Heater Installation and Venting:</u>		<u>Catalytic Heaters (canvas walled unit only):</u>	
OK	Rej.	OK	Rej.	OK	Rej.
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Hoses condition		Model: <u>SW606</u>		Installed to approved standards	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Excess flow restrictor		Direct vented and sealed from coach-interior		Operates to approved standards	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Bulkhead hose condition		Installed to approved standards		Proper flame characteristics	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Lines secured, protected and undamaged		Operates to approved standards		Fittings leak tested while operating	
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Exterior flare nuts		Proper flame characteristics			
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>		
Single approved appliance connections		Fittings leak tested while operating			
<input type="checkbox"/>	<input type="checkbox"/>				
No interior line fittings					
<input type="checkbox"/>	<input type="checkbox"/>				
Line and hose leak pressure test 8" w.c for 3 min. (no drop allowable)					

Warning Labels:

OK	Rej.
<input type="checkbox"/>	<input type="checkbox"/>
All warning labels as required by code	

Note: All combustion air and combustion vent outlets shall meet or exceed, the clearances required by code from fuel fill points, openings, windows and doors.

I, the undersigned, verify the gas system for the vehicle listed above is: Acceptable Rejected for re-certification in compliance with the BC Safety Standards Act and Regulations.

Operating permit holder name: <u>Paul's Mobile RV Service</u>			
Suite no.:	Street no.: <u>30125</u>	Street name: <u>Spallin</u>	Street type: <u>Avenue</u>
City: <u>Abbotsford</u>		Province: <u>BC</u>	Postal Code: <u>V4X 2A5</u>
Operating permit number: <u>502</u>		Fitter's name: <u>Daniel Brama</u>	Fitter's number: <u>24982</u>
Signature: 		Date: <u>2 March 3 2022</u>	

Paul's Mobile RV Service
 30125 Spallin Ave Abbotsford
 604 534 5833 604 202 0199

DATE **March 3 2022**
 TAX REG. NO.
 N° DE TAXE

SOLD TO VENDU A **Cypress Auto Brokers** SHIP TO EXPÉDIER A **Vibe Extreme L1#**
 ADDRESS ADRESSE **Decal# 499490**

CUSTOMER'S ORDER / COMMANDE DU CLIENT
 SOLD BY / VENDU PAR
 TERMS CONDITIONS
 FOB FAB
 VIA

INVOICE
 FACTURE

QUANTITY QUANTITÉ	DESCRIPTION	PRICE PRIX	UNIT UNITÉ	AMOUNT MONTANT
	Service call and gas cert. by,			135 00
	replace door lock labour			38 00
	has Decal			50 00
	Bauer Door lock with keys			49 00
				221 00
	* Needs power cable		TVH/HST TPS/GST	11 05
			PST/TVP	
			TOTAL	232 05

STAPLES 51B

