

2017 RAM 1500 ST

Pickup | 8 Cylinders | Gas

3C6JR7DTXHG552238

Country of Assembly: Mexico

Last Reported Odometer: 37,935 KM

ONE
OWNER*NO REPORTED
ACCIDENTS*


No Accident/Damage Records
Found



Last Registered In:
British Columbia (Normal)



7 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information that was reported and available to CARFAX Canada as of March 29, 2022 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report (BC)

Accident/Damage

There are no accidents/damage reported on this vehicle.

Registration

This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.
We checked for: *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*

Service Records

DATE	ODOMETER	SOURCE	DETAILS
2017 Jan 6		Coquitlam Chrysler Coquitlam, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none">Pre-delivery inspection completedFluids checked
2017 Mar 7		Coquitlam Chrysler Coquitlam, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none">Catalytic converter replaced
2018 Jul 27	12,917 KM	Coquitlam Chrysler Coquitlam, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none">Oil and filter changedTires rotatedPCM reprogrammedTire repaired
2019 Jun 27	19,582 KM	Pioneer Chrysler Mission, British Columbia, Canada	Vehicle serviced
2019 Dec 2		Service Facility	Vehicle serviced <ul style="list-style-type: none">Tire(s) changedOil and filter changed
2020 Jun 25	28,880 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none">Air filter replacedAir filter checkedTires rotatedOil and filter changed
2021 Aug 27	37,935 KM	Service Facility	Vehicle serviced

Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact RAM or visit [Ram's website](#).

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 Jan 6		Coquitlam Chrysler Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced
2017 Jan 7		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Lease
2017 Mar 7		Coquitlam Chrysler Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced
2017 Sep 2		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2018 Jul 22		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2018 Jul 27	12,917 KM	Coquitlam Chrysler Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced
2019 Jun 27	19,582 KM	Pioneer Chrysler Mission, British Columbia, Canada	Service Record	Vehicle serviced
2019 Jul 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2019 Dec 2		Service Facility	Service Record	Vehicle serviced
2020 Jun 25	28,880 KM	Service Facility	Service Record	Vehicle serviced
2020 Sep 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2021 Jul 25		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2021 Aug 27	37,935 KM	Service Facility	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage

merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

Conditions of Use

© Copyright 2005 - 2022 CARFAX Canada ULC. All rights reserved.



3C6JR7DTXHG552238



UNIT #8 - 20071 113B AVENUE
 MAPLE RIDGE, BC V2X 0Z2
 O: 604 460 7142
 C: 604 721 1432
 RIDGEMOTORSAUTOREPAIR@GMAIL.COM

Cyprus **MULTI-POINT INSPECTION**
 Name: *Auto Brokers* Year/Make/Model: *2017 RAM 1500* KMs: *41633*
 RO#: *2887* VIN: *3C6JR7DTX1G552238* License: _____

☒ CHECKED AND OK ☐ FUTURE ATTENTION ☐ IMMEDIATE ATTENTION

INTERIOR/EXTERIOR	
NOTE ANY EXISTING BODY DAMAGE	
Lights (Head, Brake, Turn, Parking)	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Windshield / Glass	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Wipers	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Horn / Interior Lights	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

BATTERY	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

UNDERHOOD	
Oil Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Transmission Fluid	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Power Steering / Brake Fluid	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Coolant / Antifreeze	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Air Filter	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Cabin Filter	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Belts	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

UNDER VEHICLE	
Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Suspension & Steering	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Driveline (Axles / CV Shaft)	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Rear Differential Fluid Level & Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Exhaust System / Shocks & Struts	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

TIRES													
TREAD DEPTH													
<input checked="" type="checkbox"/> 7/32" or greater <input type="checkbox"/> 3/32" to 6/32" <input type="checkbox"/> 2/32" or less													
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 6/32"	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 7/32"												
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 5/32"	RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 5/32"												
	<table border="1"> <thead> <tr> <th colspan="2">Wear Pattern/ Damage</th> </tr> </thead> <tbody> <tr> <td>LF</td> <td><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/></td> </tr> <tr> <td>RF</td> <td><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/></td> </tr> <tr> <td>LR</td> <td><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/></td> </tr> <tr> <td>RR</td> <td><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/></td> </tr> </tbody> </table>	Wear Pattern/ Damage		LF	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	RF	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	LR	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	RR	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Wear Pattern/ Damage													
LF	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>												
RF	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>												
LR	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>												
RR	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>												
<table border="1"> <thead> <tr> <th colspan="2">Air Pressure</th> </tr> </thead> <tbody> <tr> <td>BEFORE</td> <td>SHOULD BE</td> </tr> <tr> <td>LF</td> <td>40</td> </tr> <tr> <td>RF</td> <td>40</td> </tr> <tr> <td>LR</td> <td>40</td> </tr> <tr> <td>RR</td> <td>40</td> </tr> </tbody> </table>		Air Pressure		BEFORE	SHOULD BE	LF	40	RF	40	LR	40	RR	40
Air Pressure													
BEFORE	SHOULD BE												
LF	40												
RF	40												
LR	40												
RR	40												
Based on Mileage and Wear: <input type="checkbox"/> Alignment <input type="checkbox"/> Balance <input type="checkbox"/> Rotation <input type="checkbox"/> New Tire													

BRAKES									
BRAKE PADS / SHOES									
<input checked="" type="checkbox"/> Over 5 mm (Disk) or 2 mm (Drum)									
<input type="checkbox"/> 3-5 mm (Disk) or 1.01-2 mm (Drum)									
<input type="checkbox"/> Less than 3 mm (Disk) or 1 mm (Drum)									
<table border="1"> <tbody> <tr> <td>LF</td> <td><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/></td> </tr> <tr> <td>RF</td> <td><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/></td> </tr> <tr> <td>LR</td> <td><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/></td> </tr> <tr> <td>RR</td> <td><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/></td> </tr> </tbody> </table>	LF	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	RF	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	LR	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	RR	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
LF	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>								
RF	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>								
LR	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>								
RR	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>								

COMMENTS	
F. BRAKE	8mm
R. PADS	7mm

INSPECTOR: *Jim* DATE: *4/13/2022*

Ridge Motors Auto Repair and Tires
Unit 8 - 20071 113B Avenue
Maple Ridge, BC V2X 0Z2
(604) 460-7142

Invoice

Date	Invoice #
4/12/2022	2887

GST/HST No. 758148118

Invoice To
Cypress Auto Brokers 11919 Maple Meadow Way Maple Ridge BC V2X3M7

Vehicle Description
2017 Dodge Ram 1500 5.7

ODO IN	ODO OUT	Plate	VIN
41633			3c6jr7dtxhg552238

Quantity	Item	Description	Price Each	Amount	Tax
	I_Inspection_Gen...	GST on sales	80.00 5.00%	80.00 4.00	G
Sales Tax Total				\$4.00	
Total				\$84.00	

I hereby authorize you and your employees to carry out the repair work described above and to purchase on my account any parts and materials necessary to carry out the repair work subject to the estimate described above. I hereby authorize you and your employees to operate the vehicle listed above in connection with the repair work, including operation for the purposes of testing, inspection or delivery. I HERBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repair work authorized hereby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repair work.

By signing below I acknowledge and agree to the terms and conditions above

Customer Signature _____