

2018 RAM 1500 ST

Pickup | 8 Cylinders | Gas
3C6JR7DT3JG171515
Country of Assembly: Mexico
Last Reported Odometer: 33,283 KM

ONE OWNER* **NO REPORTED ACCIDENTS***



No Accident/Damage Records Found



Last Registered In:
British Columbia (Normal)




5 Service Records Found



No U.S. History Found



3 Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information that was reported and available to CARFAX Canada as of February 09, 2022 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report (BC)



Accident/Damage

There are no accidents/damage reported on this vehicle.



Registration

This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2017 Dec 29		Coquitlam Chrysler Coquitlam, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none">Pre-delivery inspection completedWindshield washer checked
2019 Nov 21	16,380 KM	Jiffy Lube #1084 Surrey, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none">Fluids checkedVehicle washed/detailedOil and filter changedAir filter checkedAir filter replacedWiper(s) replaced
2020 May 7	21,684 KM	Jiffy Lube #1084 Surrey, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none">Fluids checkedVehicle washed/detailedOil and filter changed
2020 Oct 1	27,829 KM	Jiffy Lube #1084 Surrey, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none">Fluids checkedVehicle washed/detailedOil and filter changedCabin air filter replaced/cleanedA/C system checked
2021 Mar 19	33,283 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none">Battery/charging system checked



Open Recalls

Recall #: U11 | BRAKE TRANSMISSION SHIFT INTERLOCK Recall Date: 2018 Feb 15

Recall Description

The Brake Transmission Shift Interlock (BTSI) locking pin may become stuck in the open position. A BTSI locking pin stuck in the open position may allow the transmission to be shifted out of PARK and to or from any gear position without depression of the brake pedal and/or without the key in the ignition, if a key is applicable.

Remedy

Inspect the Brake Transmission Shift Interlock (BTSI) operation and replace if necessary. The Body Control Module (BCM) software will also be updated.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit [Ram's website](#).

Recall #: U61 | REPROGRAM POWERTRAIN CONTROL MODULE Recall Date: 2018 Jun 26

Recall Description

The fault handling strategy of the Engine Control Module (ECM) or PCM software in the affected vehicles does not remove positive torque requests from the engine controller if the CAN-C bus stops communicating while the cruise control is requesting positive torque.

Remedy

Inspect the software level of the ECM/PCM and, if necessary, perform a software flash on the ECM/PCM of affected vehicles to improve the fault handling so that if the CAN-C bus does stop communicating any active torque requests will be cleared

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit [Ram's website](#).

Recall #: V44 | 2013-2018 D TRUCK TAILGATE LATCH Recall Date: 2019 May 16

Recall Description

The tailgate actuator limiter tab within the power lock actuator control assembly may fracture allowing the lock rod control bracket to over-travel which may pull the lock rods and release the latches, potentially resulting in the tailgate inadvertently falling open at any time.

Remedy

FCA US will conduct a Voluntary Safety Recall on all affected vehicles. The remedy for this item will limit the locking actuator travel and not allow the pivot arm from overtraveling and pulling on the locking/unlocking rods

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact RAM or visit [Ram's website](#).



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 Dec 29		Coquitlam Chrysler Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced
2017 Dec 30		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Lease
2018 Feb 15		RAM	Recall	Manufacturer Recall Issued Recall # U11
2018 Jun 26		RAM	Recall	Manufacturer Recall Issued Recall # U61
2018 Jul 22		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2019 May 16		RAM	Recall	Manufacturer Recall Issued Recall # V44
2019 Jul 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2019 Nov 21	16,380 KM	Jiffy Lube #1084 Surrey, British Columbia, Canada	Service Record	Vehicle serviced
2020 May 7	21,684 KM	Jiffy Lube #1084 Surrey, British Columbia, Canada	Service Record	Vehicle serviced
2020 Sep 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2020 Oct 1	27,829 KM	Jiffy Lube #1084 Surrey, British Columbia, Canada	Service Record	Vehicle serviced
2021 Mar 19	33,283 KM	Service Facility	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

CARFAX Canada One Owner™ Badge

The CARFAX Canada One Owner™ badge that is based on the registration information reported to CARFAX Canada. The badge is available for personal and commercial vehicles that have only been registered in the provinces of British Columbia, Alberta, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEI.

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

[Conditions of Use](#)



UNIT #8 - 20071 113B AVENUE
 MAPLE RIDGE, BC V2X 0Z2
 O: 604 460 7142
 C: 604 721 1432
 RIDGEMOTORSAUTOREPAIR@GMAIL.COM

Cypress

MULTI-POINT INSPECTION

Name: AUTO BROKER Year/Make/Model: 2018 RAM 1500 KMs: 36 139

RO#: 2897 VIN: 3C6JR7DT3JG171515 License: _____

CHECKED AND OK FUTURE ATTENTION IMMEDIATE ATTENTION

INTERIOR/EXTERIOR	
NOTE ANY EXISTING BODY DAMAGE	
Lights (Head, Brake, Turn, Parking)	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Windshield / Glass	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Wipers	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Horn / Interior Lights	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

TIRES			
TREAD DEPTH			
<input checked="" type="checkbox"/> 7/32" or greater	<input type="checkbox"/> 3/32" to 6/32"	<input type="checkbox"/> 2/32" or less	
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 8/32"	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 7/32"		
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 5/32"	RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 5/32"		
	Wear Pattern/Damage	Air Pressure	Based on Mileage and Wear:
	LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input checked="" type="checkbox"/> (!)	<input type="checkbox"/> Alignment
	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	BEFORE SHOULD BE	<input type="checkbox"/> Balance
	LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	LF 35 35	<input type="checkbox"/> Rotation
RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	RF 35 35	LR 35 35	<input type="checkbox"/> New Tire

BATTERY	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

BRAKES	
BRAKE PADS / SHOES	
<input checked="" type="checkbox"/> Over 5 mm (Disk) or 2 mm (Drum)	
<input type="checkbox"/> 3-5 mm (Disk) or 1.01-2 mm (Drum)	
<input type="checkbox"/> Less than 3 mm (Disk) or 1 mm (Drum)	
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

UNDERHOOD	
Oil Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Transmission Fluid	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Power Steering / Brake Fluid	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Coolant / Antifreeze	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Air Filter	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Cabin Filter	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Belts	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

COMMENTS	
FRONT PADS	8mm
REAR PADS	8mm

INSPECTOR: JIM DATE: 4/27/2022

Invoice

Ridge Motors Auto Repair and Tires
 Unit 8 - 20071 113B Avenue
 Maple Ridge, BC V2X 0Z2
 (604) 460-7142

Date	Invoice #
4/19/2022	2897

GST/HST No. 758148118

Invoice To
Cypress Auto Brokers 11919 Maple Meadowa Way Maple Ridge BC V2X3M7

Vehicle Description
2018 Ram 1500

ODO IN	ODO OUT	Plate	VIN
36139			3c6jr7dt3jg171515

Quantity	Item	Description	Price Each	Amount	Tax
	I_Inspection_Gen...	GST on sales	80.00 5.00%	80.00 4.00	G
Sales Tax Total				\$4.00	
Total				\$84.00	

I hereby authorize you and your employees to carry out the repair work described above and to purchase on my account any parts and materials necessary to carry out the repair work subject to the estimate described above. I hereby authorize you and your employees to operate the vehicle listed above in connect with the repair work, including operation for the purposes of testing, inspection or delivery. I HERBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repair work authorized hereby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repair work.

By signing below I acknowledge and agree to the terms and conditions above

Customer Signature _____



JIFFY LUBE #1087

20284 Dewdney Trunk Rd
 Maple Ridge, BC V2X 3E1
 (604) 465-0181

DATE	4/20/2022 2:19 PM
TRANSACTION NO	22042000020009
INVOICE NO	01087-20009
VEHICLE ID	BC-CYP

Customer Information	Service History
Cypress Auto Brokers 11919 Maple Meadows Way MAPLE RIDGE, BC V2X 3M7 (604) 465-3313	DATE KILOMETERS SERVICES 4/20/22 36141 CYP OF
Vehicle Information	
2018 DODGE/RAM 1500 PICKUP 8cyl 5.7L FI VIN 3C6JR7DT3JG171515 ALT ID	KILOMETERS 36141

Employees	Service Comments
UPPER FLEET LOWER ISAAC COURTESY HARGUN CASHIER	THANK YOU FOR YOUR BUSINESS!!!

Service Checklist	Description	Qty.	Price
1. CHASSIS LUBRICATION SEALED	CYP OIL PACKAGE	1.00	39.99
2. REAR DIFFERENTIAL FULL	OF2222 OIL FILTER	1.00	0.00
3. TRANS/TRANSAXLE FLUID FULL	PENNZOIL 5W20 OIL	6.60	5.99
4. LIGHT CHECK CHECKED OK	FREE WASHER FLUID TOP UP	1.00	0.00
5. WIPER BLADES CUST. OK'D	SUBTOTAL		\$45.98
6. AIR FILTER CHECKED	(AIR)		-0.00
7. CABIN AIR FILTER NO CHECK	SALE		\$45.98
8. FUEL FILTER NA			
9. POWER STEERING FLUID N/A	GST TAX		2.30
10. BRAKE FLUID LEVEL OK	PST TAX (Exempt 10144575)		0.00
11. BATTERY CHECKED OK	TOTAL		\$48.28
12. RADIATOR FLUID FULL	VISA 7313 AUTH: 07111L		48.28
13. WINDSHIELD WASH FLUID ADDED	CHANGE		\$0.00
14. TRANSFER CASE FLUID FULL			
15. FRT DIFFERENTIAL FLUID FULL			
16. CV BOOTS CHECKED OK			
17. SHOCKS/STRUTS APPEARS O.K			
18. TIRES TPM			
19. U JOINTS CHECKED OK			
20. BELTS AND HOSES CHECK OK			

Warranty Statement

This Jiffy Lube centre warrants all workmanship against failure for 7 days from the date of service. This warranty does not apply when the customer tampers with or alters the centre's products or alters the manufacturer's original equipment or when corrective action is taken without prior written approval from this Jiffy Lube service centre. The customer must have the limited warranty certificate and must retain a sample of the product(s) involved. Oil Level Shown Oil Filter Tight Drain Plug Tight Rear Diff Chk Plug Front Diff Chk Plug Transfer Case Chk Plug Transmission Chk Plug

y*OPEN SUN - SAT 9-6. ANY QUESTIONS CALL 604-465-0181
 APPROPRIATE, WARRANTY-APPROVED PRODUCT MAY HAVE BEEN SUBSTITUTED.

Recommend next service on 09/17/2022 or 41141 km.

X

Cardholder acknowledges receipt of goods and/or services in the amount shown hereon and agrees to perform the obligations set forth in the Cardholder's agreement with the issuer.