


# 2005 FORD ECONOLINE E450 SUPER DUTY CUTAWAY VAN

Cutaway | 10 Cylinders | Gas  
1FDXE45S85HA63966  
Country of Assembly: United States  
Last Reported Odometer: 27,198 KM



Accident/Damage Records Found



Last Registered In:  
British Columbia (Normal)



3 Service Records Found



U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



Import Record Found

Questions? We're here to help.  
Visit us at [support.carfax.ca](https://support.carfax.ca)




This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of May 27, 2022 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# Vehicle History Report (BC)




## Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
 2010 Jul 3	Ontario, Canada	
	Claim: Unknown	\$3,127.00




## Registration



This vehicle has been registered in the following locations in **Canada** (listed oldest to newest):


- In the province of **Ontario** with **Normal** branding.
- In the province of **British Columbia** with **Normal** branding.

**We checked for:** *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*





This vehicle has been registered in the state of **Georgia** in the **United States**. No major title problems were reported.

**We checked for:** *Salvage, Junk, Rebuilt, Fire, Flood, Hail and Lemon.*




## Service Records

DATE	ODOMETER	SOURCE	DETAILS
 2010 Mar 20		Gator Ford Seffner, Florida, United States	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Maintenance inspection completed</li><li>Brakes checked</li><li>Oil and filter changed</li><li>Battery/charging system checked</li><li>Tire condition and pressure checked</li></ul>
2010 Apr 14		D & D Auto Service Ltd. Kingston, Ontario, Canada	<b>Vehicle serviced</b>
2011 May 25	27,198 KM	D & D Auto Service Ltd. Kingston, Ontario, Canada	<b>Vehicle serviced</b>




## Open Recalls

 No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact FORD or visit [Ford's website](#).









# Stolen Vehicle Check

 This vehicle is not actively declared stolen.



## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
 2005 Aug 11		Motor Vehicle Dept. Georgia, United States	DMV Record Adjustment	Title issued or updated Loan or lien reported New Owner reported
 2007 Oct 29		Motor Vehicle Dept. Georgia, United States	DMV Record Adjustment	Title issued or updated New Owner reported
2008 Mar 28		Motor Vehicle Dept. RV, Canada	Registration Records	Registered/Renewed
 2008 Mar 28		Motor Vehicle Dept. Canada	Import Record	<b>From:</b> United States <b>To:</b> Canada  This vehicle has been imported into Canada from the US. For more information than is set out below, please contact RIV ( <a href="http://www.riv.ca">www.riv.ca</a> ).  Imported Into Canada As: <b>Normal</b> Case/Dossier: <b>H371784</b> Import Date: <b>3/28/2008</b> Entered Customs: <b>3/28/2008</b> Inspection Date: <b>6/9/2008</b>
2008 Jun 10		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
2009 Apr 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2009 Jul 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed
 2010 Mar 20		Gator Ford Seffner, Florida, United States	Service Record	Vehicle serviced
2010 Apr 14		D & D Auto Service Ltd. Kingston, Ontario, Canada	Service Record	Vehicle serviced



2010 Apr 28		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Commercial
2010 Jul 3		Ontario, Canada	Unknown	
2011 May 25		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2011 May 25	27,198 KM	D & D Auto Service Ltd. Kingston, Ontario, Canada	Service Record	Vehicle serviced
2012 May 5		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2012 Aug 25		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2012 Sep 29		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2012 Nov 17		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2013 Mar 30		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2013 Sep 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2013 Nov 2		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Mar 29		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Apr 4		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Apr 2		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Apr 15		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Oct 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Apr 15		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 May 20		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or



	British Columbia, Canada		Renewed
2018 Sep 2	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Oct 7	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Nov 18	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Mar 17	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 May 5	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Jun 13	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Oct 17	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Apr 16	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Jun 6	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Jun 13	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2021 Oct 24	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed



Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)

**ICBC Disclaimer**  
The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this









## PROPANE SYSTEM RE-CERTIFICATION CHECKLIST

Payment Card Industry Data Security Standards prevent the use of credit card information sent through email or fax. A Client Service Representative will contact you within three business days to complete any payment process required.

**Note:** Any personal information collected is handled in accordance with the British Columbia *Freedom and Protection of Privacy Act*. If you have questions about the collection, use, or disclosure of this information, contact the Records, Information and Privacy Analyst for the Technical Safety BC at 1-866-566-7233.

### A. Inspection (please print)

Vehicle owner's name: <u>Cypress Auto Brokers</u>		Decal number: <u>499484</u>	
Suite No.:	Street no.: <u>11919</u>	Street name: <u>Maple Meadows</u>	Street type: <u>way</u>
City: <u>Maple Ridge</u>		Province: <u>BC</u>	Postal Code: <u>V2X 3M7</u>
Vehicle make: <u>Dutchmen</u>	Vehicle type: <u>Class C</u>	Serial number: <u>1FDXE 45585HA 63966</u>	
<b>Propane Cylinder and Tanks:</b>		<b>Fridge Installation and Venting:</b>	
OK <input checked="" type="checkbox"/> Rej. <input type="checkbox"/>	Model: <u>N611</u>	OK <input checked="" type="checkbox"/> Rej. <input type="checkbox"/>	Model: <u>CU 33BP</u>
<input checked="" type="checkbox"/> Date stamp	<input checked="" type="checkbox"/> Sealed from coach interior	<input checked="" type="checkbox"/> Adequate ventilation as per code	
<input checked="" type="checkbox"/> Condition and paint	<input checked="" type="checkbox"/> Vented to coach exterior	<input checked="" type="checkbox"/> Installed to approved standards	
<input checked="" type="checkbox"/> Securely mounted	<input checked="" type="checkbox"/> Operates to approved standards	<input checked="" type="checkbox"/> Operates to approved standards	
<input checked="" type="checkbox"/> Vented enclosure	<input checked="" type="checkbox"/> Proper flame characteristics	<input checked="" type="checkbox"/> Proper flame characteristics	
<input checked="" type="checkbox"/> Location	<input checked="" type="checkbox"/> Fittings leak tested while operating	<input checked="" type="checkbox"/> Fittings leak tested while operating	
<b>Regulators (replacement must be 2-stage):</b>		<b>Furnace Installation and Venting:</b>	
OK <input checked="" type="checkbox"/> Rej. <input type="checkbox"/>	Model: <u>8535-1U</u>	OK <input checked="" type="checkbox"/> Rej. <input type="checkbox"/>	Model: <u>                    </u>
<input checked="" type="checkbox"/> Securely fastened	<input checked="" type="checkbox"/> Direct-vented and sealed from coach-interior	<input checked="" type="checkbox"/> Adequate ventilation and clearances to combustibles	
<input checked="" type="checkbox"/> Vented properly	<input checked="" type="checkbox"/> Installed to approved standards	<input type="checkbox"/> Installed to approved standards	
<input checked="" type="checkbox"/> Protective covering	<input checked="" type="checkbox"/> Operates to approved standards	<input type="checkbox"/> Proper flame characteristics	
<input checked="" type="checkbox"/> 11" w.c. working pressure with 70% load	<input checked="" type="checkbox"/> Proper flame characteristics	<input type="checkbox"/> Fittings leak tested while operating	
<input checked="" type="checkbox"/> <u>15</u> " w.c. lock-up (5 minute minimum duration)	<input checked="" type="checkbox"/> Fittings leak tested while operating		
<b>Hoses and Lines:</b>		<b>Propane Gas Lights:</b>	
OK <input checked="" type="checkbox"/> Rej. <input type="checkbox"/>	Model: <u>86A-8E</u>	OK <input checked="" type="checkbox"/> Rej. <input type="checkbox"/>	Model: <u>                    </u>
<input checked="" type="checkbox"/> Hoses condition	<input checked="" type="checkbox"/> Direct vented and sealed from coach-interior	<input checked="" type="checkbox"/> Adequate ventilation and clearances to combustibles	
<input checked="" type="checkbox"/> Excess flow restrictor	<input checked="" type="checkbox"/> Installed to approved standards	<input type="checkbox"/> Installed to approved standards	
<input checked="" type="checkbox"/> Bulkhead hose condition	<input checked="" type="checkbox"/> Operates to approved standards	<input type="checkbox"/> Proper flame characteristics	
<input checked="" type="checkbox"/> Lines secured, protected and undamaged	<input checked="" type="checkbox"/> Proper flame characteristics	<input type="checkbox"/> Fittings leak tested while operating	
<input checked="" type="checkbox"/> Exterior flare nuts	<input checked="" type="checkbox"/> Fittings leak tested while operating		
<input checked="" type="checkbox"/> Single approved appliance connections		<b>Catalytic Heaters (canvas walled unit only):</b>	
<input checked="" type="checkbox"/> No interior line fittings		OK <input checked="" type="checkbox"/> Rej. <input type="checkbox"/>	Model: <u>                    </u>
<input checked="" type="checkbox"/> Line and hose leak pressure test 8" w.c for 3 min. (no drop allowable)		<input checked="" type="checkbox"/> Installed to approved standards	
		<input checked="" type="checkbox"/> Operates to approved standards	
		<input checked="" type="checkbox"/> Proper flame characteristics	
		<input checked="" type="checkbox"/> Fittings leak tested while operating	
		<b>Warning Labels:</b>	
		OK <input checked="" type="checkbox"/> Rej. <input type="checkbox"/>	All warning labels as required by code

Note: All combustion air and combustion vent outlets shall meet or exceed, the clearances required by code from fuel fill points, openings, windows and doors.

I, the undersigned, verify the gas system for the vehicle listed above is: ☒ Acceptable ☐ Rejected for re-certification in compliance with the BC Safety Standards Act and Regulations.

Operating permit holder name: <u>Paul's Mobile RV</u>			
Suite no.:	Street no.: <u>30125</u>	Street name: <u>Spallin</u>	Street type: <u>Ave</u>
City: <u>Abbotsford</u>		Province: <u>BC</u>	Postal Code: <u>V4X 2A5</u>
Operating permit number: <u>802</u>	Fitter's name: <u>Daniel Brama</u>		Fitter's number: <u>24982</u>
Signature: <u>                    </u>			Date: <u>Dec 7 2021</u>

Technical Safety BC is working towards going paperless! Participate by signing up for email correspondence.



Coastal Ford Burnaby

A division of Coastal Ford Sales Limited  
5750 Lougheed HWY  
Burnaby, BC V5B 2Z9  
Phone: 604-294-6525  
www.coastalfordburnaby.com

SO # 12S2981

Status  
Printed 04/12/2022 6:09:30 PM

SERVICE ORDER  
CUSTOMER COPY

User cfbquand Page 2



<b>Customer No</b> 280265C Attn: Cypress Autobrokers Ltd CYPRESS AUTOBROKERS LTD 1835 MARINE DR NORTH VANCOUVER, BC V3J 2S5  <b>Home</b> (604) 719-7615 <b>Bus</b> <b>Cell</b> <b>Today</b> <b>Email</b>  <b>Fleet Type</b> <b>Term</b> CASH	<b>Advisor</b> Raff Pucci <b>Shop</b> S1 <b>Priority</b> 10598 <b>Promised</b> 03/21/2022 5:00 PM <b>Opened</b> 03/17/2022 5:10 PM <b>Cashiered</b> <b>Tag</b> 2277 <b>Location</b> w1 sales far <b>PO #</b>	<b>License No</b> <b>Year</b> 2005 <b>Make</b> FORD <b>Vehicle ID No</b> 1FDXE45S85HA63966 <b>Engine Size</b> 6.8L SOHC EFI TRITON V10 ENGINE <b>Odometer In</b> 43162 <b>Model</b> ECONOLINE CUTAWAY <b>Selling Dealer</b> <b>Odometer Out</b> 0 <b>Model No</b> E45 <b>Extended Warranty</b> <b>InServ Date</b> 06/30/2005 <b>Stock No</b> <b>Colour</b> <b>Delivery Date</b> 06/30/2005 <b>Fleet #</b>
---	--	--

VALVEDILL	VALVEDILL	1	CSL	2.92	2.92	2.92
Technician	6ES -	Parts Total				2.92
Cause	left rear inner tire flat	Labour Total				44.95
Correction	remove and t leak test found Schrader valve leaking, dismount from rim inspect tire for damage and install new Schrader valve stem ,road test and retorque all wheels flat repair 0.5 road test and re torque all wheels 0.5	Request Sub-total				47.87

Request	Description	Job	CSR	Status
13	Check Engine Light On	4	2597	Approved
Labour	Description	Type	Amount	
13	Check Engine Light On \$165.00	C	0.00	
Technician	6ES -	Parts Total		0.00
Cause	scan test retrieve code p0191 fuel rail psi sensor fault ,check oasis no tsbs ssms ,refer to pced ,and one of the causes could be low fuel truck has very low fuel	Labour Total		0.00
		Request Sub-total		0.00
Correction	install fuel clear code road test and re run self test pass at this time ,advise customer if check engine light comes back on will require further diagnoses n/c			

Request	Description	Job	CSR	Status
POVRC	Pre-Owned Vehicle Report Card	5	2597	Approved
		Parts Total		0.00
		Labour Total		0.00
		Request Sub-total		0.00

Labour	562.45
Parts	791.94
Supplies	5.00
Sublet/Tow	76.38
SUB-TOTAL	1,435.77
GST	71.79
PST	0.00
TOTAL INVOICE	1,507.56

Payment is required on invoice. No statement will be issued. No refunds or exchanges on electrical, glass or special order parts.  
I agree that until payment in full of the within account, I hereby acknowledge the existence of a mechanic's lien in favour of the within dealer on the vehicle described herein in respect of the material supplied and services rendered under this work order for the full amount charged therefor. I further acknowledge that the said lien shall continue in force at all times, whether the vehicle is in my possession or possession of the dealer until the within account is paid in full. While the vehicle is in my possession it shall at all times be subject to repossession on the demand by the dealer until the within account is paid in full.

Indebtedness is hereby acknowledged in the sum of \$\_\_\_\_\_ being all or the balance owing for repairs, parts and accessories described on this Invoice. **Terms:** Net 30 days; interest of 2% per month (26.8% per annum) charged on all overdue accounts.

Customer Signature X\_\_\_\_\_ Date: \_\_\_\_\_

Thank you for your business!



# Coastal Ford Burnaby

A division of Coastal Ford Sales Limited

5750 Lougheed HWY

Burnaby, BC V5B 2Z9

Phone: 604-294-6525

www.coastalfordburnaby.com

SO # 12S2981

Status  
Printed 04/12/2022 6:09:30 PM

## SERVICE ORDER CUSTOMER COPY

User cfbquand Page 1



<b>Customer No</b> 280265C Attn: Cypress Autobrokers Ltd CYPRESS AUTOBROKERS LTD 1835 MARINE DR NORTH VANCOUVER, BC V3J 2S5  <b>Home</b> (604) 719-7615 <b>Bus</b> <b>Cell</b> <b>Today</b> <b>Email</b>  <b>Fleet Type</b> <b>Term</b> CASH	<b>Advisor</b> Raff Pucci <b>Shop</b> S1 <b>Priority</b> 10598  <b>Promised</b> 03/21/2022 5:00 PM <b>Opened</b> 03/17/2022 5:10 PM <b>Cashiered</b>  <b>Tag</b> 2277 <b>Location</b> w1 sales far <b>PO #</b>	<b>License No</b> <b>Year</b> 2005 <b>Make</b> FORD <b>Vehicle ID No</b> 1FDXE45S85HA63966 <b>Engine Size</b> 6.8L SOHC EFI TRITON V10 ENGINE <b>Odometer In</b> 43162 <b>Model</b> ECONOLINE CUTAWAY <b>Selling Dealer</b> <b>Odometer Out</b> 0 <b>Model No</b> E45 <b>Extended Warranty</b> <b>Stock No</b> <b>Colour</b> <b>Delivery Date</b> 06/30/2005 <b>Fleet #</b>
---	--	---

Request	Description	Job	CSR	Status
29.01	DEALER PRE-OWNED VEHICLE INSPECTION. INCLUDES RETRIEVE KEYLESS ENTRY CODE (IF EQUIP)	1	2597	Original
Labour	Description	Type	Amount	
29.01	DEALER PRE-OWNED VEHICLE INSPECTION. INCLUDES RETRIEVE KEYLESS ENTRY CODE (IF EQUIP)	C	150.00	
Sublet	Description	Type	CSR	Amount
	fuel	CSUB	2597	76.38
Technician	6ES -			0.00
Cause	perform motor home pre owned inspection			226.38
Correction	inspection 2.0			226.38
Request Sub-total				226.38

Request	Description	Job	CSR	Status
53.06	RELIN AND MACHINE FRONT BRAKES	2	2597	Approved
Labour	Description	Type	Amount	
53.06	RELIN AND MACHINE REAR BRAKES (FULL FLOAT E/F4450/550) \$367.50 PLUS PAR TSAS PER CURRENT MITCHELL LABOUR TIMES@ 105.00/ HOUR	C	367.50	

Part	Description	Shp	Type	Retail	Price	Amount
BR 48 C	M/C PADS	1	CSL20	144.98	105.00	105.00
BRR 309	ROTOR & HUB	2	CSO	220.48	163.32	326.64
BRS 93	GRS SEAL	2	CSL	37.59	37.59	75.18
NBRC 46 RM	CALIPER ASY - BRAKE	1	CSO20	158.75	127.00	127.00
NBRC 47 BRM	CALIPER ASY - BRAKE	1	CSO20	158.75	127.00	127.00
EOAZ 2149 B	WASHER,COPPER	4	CSO	3.20	1.94	7.76
CPM 1 C	FLUID - BRAKE	2	CSO	11.24	10.22	20.44
Technician	6ES -					789.02
Cause	front brake rotors pitted front brake pads cracked front calipers \sticking					367.50
Correction	replace front brake rotors service wheel bearing and install new hub seals,replace front brake calipers and bleed hydraulics ,replace front brake pads lab 3.5					1,156.52
Request Sub-total						1,156.52

Request	Description	Job	CSR	Status		
52.00	REPAIR FLAT TIRE AND REBALANCE	3	2597	Approved		
Labour	Description	Type	Amount			
52.00	REPAIR FLAT TIRE AND REBALANCE \$42.95 PLUS PARTS	C	44.95			
Part	Description	Shp	Type	Retail	Price	Amount


Payment is required on invoice. No statement will be issued. No refunds or exchanges on electrical, glass or special order parts.  
I agree that until payment in full of the within account, I hereby acknowledge the existence of a mechanic's lien in favour of the within dealer on the vehicle described herein in respect of the material supplied and services rendered under this work order for the full amount charged therefor. I further acknowledge that the said lien shall continue in force at all times, whether the vehicle is in my possession or possession of the dealer until the within account is paid in full. While the vehicle is in my possession it shall at all times be subject to repossession on the demand by the dealer until the within account is paid in full.

Indebtedness is hereby acknowledged in the sum of \$\_\_\_\_\_ being all or the balance owing for repairs, parts and accessories described on this Invoice. Terms: Net 30 days, interest of 2% per month (26.8% per annum) charged on all overdue accounts.

Customer Signature X\_\_\_\_\_ Date: \_\_\_\_\_

Thank you for your business!







Burnaby: (604) 294-6525  
Vancouver: (604) 873-2363  
Squamish: (778) 284-7676

NAME CYPRESS AUTO BROKERS STOCK# \_\_\_\_\_  
DATE 03/17/2022 LICENCE PLATE# \_\_\_\_\_  
ODOMETER 43162 R.O.# 1852981  
YEAR: 2005 MAKE: Ford MODEL: Eco



 CHECKED AND OKAY

 REQUIRES FUTURE ATTENTION

**REQUIRES IMMEDIATE ATTENTION**










☐ CHECKED AND COMPLETED OPEN  
FIELD SERVICE ACTIONS (RECALLS)

FRONT LEFT		FRONT RIGHT		TIRES	
<div> <div></div> <div></div> <div></div> </div> Dome light		<div> <div></div> <div></div> <div></div> </div> Head lamp	<div> <div></div> <div></div> <div></div> </div> Signal light	Recommend: Rotation (xrtot)	
<div> <div></div> <div></div> <div></div> </div> Windshield		<div> <div></div> <div></div> <div></div> </div> Hazard light	<div> <div></div> <div></div> <div></div> </div> Windshield	Alignment (xalig)	
<div> <div></div> </div> Cracked		<div> <div></div> <div></div> <div></div> </div> Windshield	<div> <div></div> <div></div> <div></div> </div> Cracked	Replacement (xtire)	
<div> <div></div> </div> Chipped		<div> <div></div> <div></div> <div></div> </div> Sandblasted	<div> <div></div> <div></div> <div></div> </div> Cracked		
<div> <div></div> </div> Sandblasted OP CODE: xwsld		<div> <div></div> <div></div> <div></div> </div> Front washer system	<div> <div></div> <div></div> <div></div> </div> Sandblasted OP CODE: xwsld		
<div> <div></div> <div></div> <div></div> </div> Front washer system OP CODE: xwash		<div> <div></div> <div></div> <div></div> </div> Front wipers	<div> <div></div> <div></div> <div></div> </div> Front washer system OP CODE: xwash	<div> <div></div> <div></div> <div></div> </div> Front wipers OP CODE: xftwtp	
<div> <div></div> <div></div> <div></div> </div> Head lamp		<div> <div></div> <div></div> <div></div> </div> Tire tread'	<div> <div></div> <div></div> <div></div> </div> Tire tread'	<div> <div></div> <div></div> <div></div> </div> Tire pressure	
<div> <div></div> <div></div> <div></div> </div> Signal light		<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	
<div> <div></div> <div></div> <div></div> </div> Hazard light		<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	
<div> <div></div> <div></div> <div></div> </div> Tire tread'		<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	
<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure		
<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure		
<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure		
<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure		
<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure		
<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure		
<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure		
<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure		
<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure	<div> <div></div> <div></div> <div></div> </div> Tire pressure		
<div> <div></div></div>					

**TIRE INFORMATION MUST BE SUPPLIED ON ALL CHECK SHEETS**

Tire Size: 225 / 75 R 16.  
Tire Brand: MICHELIN LTX

## UNDER HOOD

-  Horn
-  Interior hood light
-  Air conditioning hoses
-  Fluid levels
-  Drive belt(s)
-  Air filter
-  Pollen filter
-  Radiator, hoses/clamps and coolant condition
-  Heater hoses/clamps

OP CODE

xachs

xdrvb

xairf

xradh

# xhtrh

## BATTERY PERFORMANCE

● Good    ● Recharge  
● Bad

Cold cranking amps: 730  
 Factory Specs. 850 Actual

xbatt

## UNDER VEHICLE

- Steering components
- Suspension components
- Exhaust system
- Shocks
  - leakage
  - damage
- Struts
  - leakage
  - damage
- Half shaft boots
- Oil leaks
- Fuel leaks

xstrg

xsusp

xexht

xshck

xstrt

xcvbt  
:llXOLIK  
ufuq

xiuei

**PLEASE PRINT CLEARLY**

## SERVICE ADVISOR

TECHNICIAN

\*Engine, transmission and drive axle must be the same original equipment specified for the vehicle and meet all applicable Federal Regulations to be eligible for ESP coverage

VEHICLES NOT ELIGIBLE FOR ESP COVERAGE

Police, taxi, delivery/shuttle/commuter, ambulances, tow trucks, vehicles equipped with snowplows, stripped chassis, commercial cutaways and recreational vehicles, Flexible Fuel Vehicles, and vehicles beyond 5,000 kg (11,000 lbs) GVW.

**ADDITIONAL SERVICES REQUIRED:**

Vehicle Identification Number 1FDXE4S585HA63966

5 Digit Dealer Code

This is to certify that the above vehicle has been inspected and any necessary repairs have been made to qualify this vehicle for the used car Extended Service Contract. To the best of my knowledge, this vehicle qualifies for the used car Extended Service Contract coverage. Pre-existing conditions or repairs made on or before the enrollment date are not eligible for reimbursement.

Dealer Signature \_\_\_\_\_ Date \_\_\_\_\_

MM / DD / YY