

Vehicle History Report + Lien Check (BC) #: 40141192

Report Date: June 15, 2022 | 05:38 PM EST

Report Status: Complete

Reference:

2016 NISSAN VERSA NOTE S

Hatchback | 4 Cylinders | Gas 3N1CE2CP8GL354772 Country of Assembly: Mexico Last Reported Odometer: 128,983 KM



LIEN CHECK





Glass Records found



Last Registered In:
British Columbia (Normal)



16 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of June 15, 2022 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report + Lien Check (BC)



Lien Check

No lien records found in British Columbia.

How We Check for Liens

CARFAX Canada uses the VIN to search government records in each Canadian province and territory (excluding Northwest Territories) where the vehicle is currently registered and where it has historically been registered. We do not check for liens or title in any U.S. state.

If a VIN has no registration records in Canada, we cannot check for liens. We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty equipment.

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.

CARFAX Canada Canadian Lien Guarantee

If for some reason our lien check fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a

maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian (\$5,000.00), whichever is lower.



Accident/Damage



There are no police reported accidents, estimates, or claims reported on this vehicle, however, we found other damage records that are outlined below.

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
② 2018 Jun 22	British Columbia, Canada	
	Glass Record	\$915.33



Registration


This vehicle has been registered in the province of British Columbia in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2015 Nov 8		Mertin Nissan Chilliwack, British Columbia, Canada	Pre-delivery inspection completed
2016 Aug 3	7,429 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Vehicle serviced • Vehicle washed/detailed • Oil and filter changed
2016 Nov 16	15,998 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Vehicle serviced Oil and filter changed Tires rotated
2017 Mar 14	25,288 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Vehicle serviced Oil and filter changed Tires rotated
2017 Jun 20	37,033 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Vehicle serviced • Tires rotated
2017 Sep 6	44,972 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Vehicle serviced
2018 Jan 5	55,728 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Vehicle serviced • Brake fluid flushed/changed
2018 Apr 10	64,010 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Vehicle serviced
2018 Jun 7	67,739 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Vehicle serviced
2018 Jul 23	72,792 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Vehicle serviced • Tires rotated
2018 Sep 21	75,296 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Vehicle serviced
2018 Dec 19	82,831 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Vehicle serviced
2019 Apr 15	92,222 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Vehicle serviced Oil pan gasket replaced Oil and filter changed
2019 Jul 17	100,758 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Vehicle serviced • Oil and filter changed
2019 Dec 6	111,803 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Vehicle serviced • Brake fluid flushed/changed
2020 May 21	121,198 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Vehicle serviced • Wiper(s) replaced • Tire(s) replaced



No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact NISSAN or visit Nissan's website.



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 Nov 8		Mertin Nissan	Service Record	Vehicle serviced
		Chilliwack, British Columbia,		
		Canada		
2016 Apr 23		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or
25 E		British Columbia, Canada		Renewed
				First Owner Reported
				Previous Use: Lease
2016 Jul 2		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or
		British Columbia, Canada		Renewed
				Previous Use: Lease
2016 Aug 3	7,429 KM	Mertin Nissan	Service Record	Vehicle serviced
3	real country of	Chilliwack, British Columbia,		
		Canada		
2016 Nov 16	15,998 KM	Mertin Nissan	Service Record	Vehicle serviced
		Chilliwack, British Columbia,		
		Canada		
2017 Mar 14	25,288 KM	Mertin Nissan	Service Record	Vehicle serviced
		Chilliwack, British Columbia,		
		Canada		
2017 Jun 20	37,033 KM	Mertin Nissan	Service Record	Vehicle serviced
		Chilliwack, British Columbia,		
		Canada		
2017 Jul 1		Motor Vehicle Dept.	Canadian Renewal	Registration Issued or
		British Columbia, Canada		Renewed
				Previous Use: Lease
2017 Sep 6	44,972 KM	Mertin Nissan	Service Record	Vehicle serviced
		Chilliwack, British Columbia,		

		Canada		
017 Oct 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
018 Jan 5	55,728 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Service Record	Vehicle serviced
2018 Apr 10	64,010 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Service Record	Vehicle serviced
2018 Jun 7	67,739 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Service Record	Vehicle serviced
2018 Jun 22		Insurance Records British Columbia, Canada	Glass Record	\$915.33
2018 Jul 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2018 Jul 23	72,792 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Service Record	Vehicle serviced
2018 Sep 21	75,296 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Service Record	Vehicle serviced
2018 Dec 19	82,831 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Service Record	Vehicle serviced
2019 Apr 15	92,222 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Service Record	Vehicle serviced
2019 Jun 30		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2019 Jul 17	100,758 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Service Record	Vehicle serviced
2019 Dec 6	111,803 KM	Mertin Nissan Chilliwack, British Columbia, Canada	Service Record	Vehicle serviced
2020 May 21	121,198 KM	Mertin Nissan Chilliwack, British Columbia,	Service Record	Vehicle serviced

2020 Jun 29		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2022 Mar 24		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Lease
2022 Jun 10	128,983 KM	Independent Source Chilliwack, British Columbia, Canada	Odometer reading	



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at http://apps.kcbc.com/registration/ychr/Limitation.html.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.





Rear Differential Fluid Level & Condition

Exhaust System / Shocks & Struts

UNIT #8 - 20071 1138 AVENUE MAPLE RIDGE, BC V2X 0Z2

0: 604 460 7142

C: 604 721 1432

RIDGEMOTORSAUTOREPAIR@GMAIL.COM

/ JORGS MULTI-POINT	INSPECTION
Name: Auto Broke Wear/Make/Model: 20	016 NISSAN VELSA KMS: 12909
RO#:3025 VIN: 3NICE2CPS	311354772 Llcense:
CHECKED AND OK FUTURE ATTEN	바이지 마이 나를 모르겠다면 하나 나는 사람들이 살아 보다.
INTERIOR/EXTERIOR	TIRES
NOTE ANY EXISTING BODY DAMAGE	TREAD DEPTH
	7/32" or greater 3/32" to 6/32" 2/32" or less LF
	Wear Pattern/ Damage Air Pressure Mileage and Wear:
Lights (Head, Brake, Turn, Parking)	LF BEFORE SHOULD BE Alignment
Windshield / Glass	RF LF 30 Balance
Wipers	LR LR Rotation
Horn / Interior Lights	RR RR New Tire
BATTERY	BRAKES
Mighty and the second s	Over 5 mm (Disk) or 2 mm (Disk) or 1.01-2 mm (Drum)
UNDERHOOD	Less than 3 mm (Disk) or 1 mm (Drum)
Oil Condition	— or r lilli (bluil)
Transmission Fluid	LF 🔼 🔃
Power Steering / Brake Fluid	RF 🗾 📗
Coolant / Antifreeze	LR 🗾
Air Filter	RR 🗾 🗌
Cabin Filter	
Belts	COMMENTS
UNDER VEHICLE	COMMENTS
Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	Flog PAUS GMM
Suspension & Steering	POBL SHOW YMA
Driveline (Axles / CV Shaft)	7.00

INSPECTOR: DATE: 6/22/2022

Ridge Motors Auto Repair and Tires Unit 8 - 20071 113B Avenue Maple Ridge, BC V2X 0Z2 (604) 460-7142

GST/HST No.

758148118

Date	Invoice #
6/22/2022	3025

Invoice

The second secon		113
Invoice To		
Cypress Auto Brokers	St. Land Land	
11919 Maple Meadowa Way		
Maple Ridge BC		ne A
V2X3M7		

Vehicle Description	
2016 Nissan Versa	
1	

ODO IN	ODO OUT	Plate	VIN
129098		9	3n1ce2cp86l354772

Quantity	Item	Description	Price Each	Amount	Та
	I_Inspection_Gen	GST on sales	80.00 5.00%	80.00 4.00	G
		10			
				£4.00	
			Sales Tax Total	\$4.00	
			Total	\$84.00	

I herby authorize you and your employees to carry out the repair work described above and to purchase on my account any parts and materials necessary to carry out the repair work subject to the estimate described above. I herby authorize you and your employees to operate the vehicle listed above in connect with the repair work, including operation for the purposes of testing, inspection or delivery. I HERBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repair work authorized herby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repair work.

By signing below I acknowledge and agree to the terms and conditions above

Customer	Signature		



JIFFY LUBE #1087

20284 Dewdney Trunk Rd Maple Ridge, BC V2X 3E1 (604) 465-0181 Page 1 of 1

DATE 6/22/2022 2:39 PM

TRANSACTION NO 22062200021119
INVOICE NO 01087-21119
VEHICLE ID BC-CYP

Customer Information	Service History		
Cypress Auto Brokers	DATE KILOMETERS SERVICES 6/22/22 129104 CYP OF		
MAPLE RIDGE, BC V2X 3M7 (604) 465-3313			
Vehicle Information			
2016 NISSAN/DATSUN VERSA 4cyl 1.6L FI VIN 0 KILOMETERS 129104 ALT ID			
Employees	Service Comments		
UPPER LOWER COURTESY CASHIER FLEET ISAAC PREM			-
Service Checklist	Description	Qty. P	rice
. CHASSIS LUBRICATION SEALED	CYP OIL PACKAGE	1.00 3	9.99
2. REAR DIFFERENTIAL NO CHECKS	OF4622 OIL FILTER	1.00	0.00
B. TRANS/TRANSAXLE FLUID FULL	PENNZOIL 5W30 OIL	3.50	0.00
1. LIGHT CHECK CHECKED OK	FREE WASHER FLUID TOP UP		0.00
5. WIPER BLADES CUST. OK'D			9.99
5. AIR FILTER CHECKED 7. CABIN AIR FILTER N\A	SUBTOTAL	The state of the s	
B. FUEL FILTER NA	SALE	\$39	9.99
P. POWER STEERING FLUID NO CHECKS			
10. BRAKE FLUID LEVEL OK	GST TAX		2.00
11. BATTERY CHECKED OK	PST TAX (Exempt 10144575) 0.		0.00
12. RADIATOR FLUID FULL	TOTAL		L.99
13. WINDSHIELD WASH FLUID ADDED	VISA 1 AUTH: 1		1.99
14. TRANSFER CASE FLUID N/A	VISA 1 ASTILL		
15. FRT DIFFERENTIAL FLUID N/A	CHANGE	\$(0.00
16. CV BOOTS CHECKED OK	CHANGE		
17. SHOCKS/STRUTS APPEARS O.K			
18. TIRES TPM 19. U JOINTS N/A			
20.BELTS AND HOSES CHECK OK			
	nty Statement		
This liffy I ube centre warrants all workmanship against fail	ure for 7 days from the date of service. The	nis warranty does no	t
This Jiffy Lube centre warrants all workmanship against fail apply when the customer tampers with or alters the centre when corrective action is taken without prior written approximited warranty certificate and must retain a sample of the Plug Tight Rear Diff Chk Plug Front Diff Chk Plug Tra	ure for 7 days from the date of service. The products or alters the manufacturer's or val from this Jiffy Lube service centre. The product(s) involved. Oil Level Shown	iginal equipment or customer must hav Oil Filter Tight D	,
when corrective action is taken without prior written approximated warranty certificate and must retain a sample of the	val from this Jiffy Lube service centre. The product(s) involved. Oil Level Shown	customer must hav Oil Filter Tight D	e
y*OPEN SUN - SAT 9-6. ANY QUESTIONS CALL 604-465-0183 APPROPRIATE, WARRANTY-APPROVED PRODUCT MAY HAV BEEN SUBSTITUTED.	1 E X		
Recommend next service on 11/19/2022 or 134104 kg	Cardholder acknowledges receipt of goods and/or services in the amount shown hereon and agrees to perform the obligations set forth in the Cardholder's agreement with the issuer.		