



Vehicle History Report (BC) #: 41318390

Report Date: August 22, 2022 | 05:38 PM EST

Report Status: Complete

Reference:


## 2004 GMC SAVANA G2500

Van cargo | 8 Cylinders | Gas


1GTGG25V741102406

Country of Assembly: United States

Last Reported Odometer: 189,157 KM




Accident/Damage Records Found



Last Registered In:  
**British Columbia (Normal)**



**11 Service Records Found**



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

**Questions? We're here to help.**

Visit us at [support.carfax.ca](https://support.carfax.ca)



**This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of August 22, 2022** (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# Vehicle History Report (BC)



## Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2006 Jul 28	British Columbia, Canada	
	Estimate: LEFT REAR CORNER   Estimate Date: n/a	\$1,558.84
	Claim: COLLISION LEFT REAR CORNER	\$1,379.51
2010 Feb 10	British Columbia, Canada	
	Claim: VANDALISM	\$508.66

## Other Damage Records

RECORD DATE	DETAILS	AMOUNT
2004 Dec 14	British Columbia, Canada	
	Glass Record	\$637.88



## Registration

This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

**We checked for:** Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2003 Jul 18		Carter GM Northshore North Vancouver, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Pre-delivery inspection completed</li></ul>
2004 Feb 6	15,267 KM	Service Facility	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Maintenance inspection completed</li><li>Oil and filter changed</li><li>Mirror(s) checked</li><li>Vehicle washed/detailed</li></ul>

2004 Sep 21		Carter GM Northshore North Vancouver, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>A/C and heating system checked</li> <li>Exterior lights checked</li> </ul>
2012 Sep 16	154,400 KM	PENNZOIL 10 MINUTE OIL CHANGE Maple Ridge, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> </ul>
2013 Mar 26	159,393 KM	PENNZOIL 10 MINUTE OIL CHANGE Maple Ridge, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> </ul>
2015 Jul 20	169,599 KM	PENNZOIL 10 MINUTE OIL CHANGE Maple Ridge, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> </ul>
2016 Mar 17	173,975 KM	PENNZOIL 10 MINUTE OIL CHANGE Maple Ridge, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> </ul>
2017 Apr 22	179,489 KM	PENNZOIL 10 MINUTE OIL CHANGE Maple Ridge, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> </ul>
2018 Aug 7	184,778 KM	Express Care Maple Ridge, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Recommended maintenance performed</li> <li>Oil and filter changed</li> </ul>
2019 Mar 13	185,590 KM	Mister Transmission # 126 Maple Ridge, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Fluids checked</li> <li>Transmission serviced</li> </ul>
2020 Jun 29	189,157 KM	Express Care Maple Ridge, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Recommended maintenance performed</li> <li>Oil and filter changed</li> </ul>



## Open Recalls

- No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact GMC or visit [GM's website](#).



## Stolen Vehicle Check

- This vehicle is not actively declared stolen.



## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2003 Jul 18		Carter GM Northshore North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2003 Jul 30		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2004 Feb 6	15,267 KM	Service Facility	Service Record	Vehicle serviced
2004 Mar 1	12,441 KM	Independent Source Chilliwack, British Columbia, Canada	Odometer reading	
2004 Sep 21		Carter GM Northshore North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2004 Dec 14		Insurance Records British Columbia, Canada	Glass Record	\$637.88
2005 May 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2006 May 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2006 Jul 28		Insurance Records British Columbia, Canada	COLLISION	LEFT REAR CORNER
2006 Jul 28		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a LEFT REAR CORNER
2008 May 3		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2009 May 2		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2010 Feb 10		Insurance Records British Columbia, Canada	VANDALISM	
2010 May 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2011 Apr 30		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2012 May 5		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2012 Sep 16	154,400 KM	PENNZOIL 10 MINUTE OIL CHANGE	Service Record	Vehicle serviced

		Maple Ridge, British Columbia, Canada		
2013 Mar 26	159,393 KM	PENNZOIL 10 MINUTE OIL CHANGE Maple Ridge, British Columbia, Canada	Service Record	Vehicle serviced
2013 May 4		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2013 Nov 2		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2014 Nov 15		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Feb 14		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Jun 20		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2015 Jul 20	169,599 KM	PENNZOIL 10 MINUTE OIL CHANGE Maple Ridge, British Columbia, Canada	Service Record	Vehicle serviced
2015 Oct 17		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2016 Jan 16		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Mar 17	173,975 KM	PENNZOIL 10 MINUTE OIL CHANGE Maple Ridge, British Columbia, Canada	Service Record	Vehicle serviced
2016 Aug 13		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Dec 24		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Apr 22		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Apr 22	179,489 KM	PENNZOIL 10 MINUTE OIL CHANGE Maple Ridge, British Columbia, Canada	Service Record	Vehicle serviced
2017 Jul 15		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed

2017 Nov 11		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Feb 17		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Aug 7	184,778 KM	Express Care Maple Ridge, British Columbia, Canada	Service Record	Vehicle serviced
2018 Oct 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Feb 17		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Mar 13	185,590 KM	Mister Transmission # 126 Maple Ridge, British Columbia, Canada	Service Record	Vehicle serviced
2019 May 19		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Nov 24		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Jun 7		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Jun 29	189,157 KM	Express Care Maple Ridge, British Columbia, Canada	Service Record	Vehicle serviced
2022 Aug 10		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported



Questions? We're here to help.

Visit us at [support.carfax.ca](http://support.carfax.ca)

#### ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/Limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability.

merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

© Copyright 2005 - 2022 CARFAX Canada ULC. All rights reserved.



1GTGG25V74110240E



UNIT #8 - 20071 113B AVENUE  
 MAPLE RIDGE, BC V2X 0Z2  
 O: 604 460 7142  
 C: 604 721 1432  
 RIDGEMOTORSAUTOREPAIR@GMAIL.COM

CYPRESS MULTI-POINT INSPECTION

Name: Auto Repair Year/Make/Model: 2004 Chevy SAUVANIK KMs: 191534

RO#: 3143 VIN: 1GT6625V741102406 License: \_\_\_\_\_

■ CHECKED AND OK      ■ FUTURE ATTENTION      ■ IMMEDIATE ATTENTION

INTERIOR/EXTERIOR	
NOTE ANY EXISTING BODY DAMAGE	
Lights (Head, Brake, Turn, Parking)	<span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>
Windshield / Glass	<span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>
Wipers	<span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>
Horn / Interior Lights	<span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>

TIRES			
TREAD DEPTH			
<span style="color: green;">■</span> 7/32" or greater	<span style="color: yellow;">■</span> 3/32" to 6/32"	<span style="color: red;">■</span> 2/32" or less	
LF <span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>	6/32"	RF <span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>	6/32"
LR <span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>	7/32"	RR <span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>	7/32"
	Wear Pattern / Damage	Air Pressure	Based on Mileage and Wear:
	LF <span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>	<span style="color: red;">■</span>	<input type="checkbox"/> Alignment
	RF <span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>	BEFORE SHOULD BE	<input type="checkbox"/> Balance
	LR <span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>	60 60	<input type="checkbox"/> Rotation
RR <span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>	60 60	<input type="checkbox"/> New Tire	

BATTERY	
<span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>	

BRAKES	
BRAKE PADS / SHOES	
<span style="color: green;">■</span> Over 5 mm (Disk) or 2 mm (Drum)	
<span style="color: yellow;">■</span> 3-5 mm (Disk) or 1.01-2 mm (Drum)	
<span style="color: red;">■</span> Less than 3 mm (Disk) or 1 mm (Drum)	
LF <span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>	
RF <span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>	
LR <span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>	
RR <span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>	

UNDERHOOD	
Oil Condition	<span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>
Transmission Fluid	<span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>
Power Steering / Brake Fluid	<span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>
Coolant / Antifreeze	<span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>
Air Filter	<span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>
Cabin Filter	<span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>
Belts	<span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>

UNDER VEHICLE	
Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	<span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>
Suspension & Steering	<span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>
Driveline (Axles / CV Shaft)	<span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>
Rear Differential Fluid Level & Condition	<span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>
Exhaust System / Shocks & Struts	<span style="color: green;">■</span> <input checked="" type="checkbox"/> <span style="color: yellow;">■</span> <input type="checkbox"/> <span style="color: red;">■</span> <input type="checkbox"/>

COMMENTS	
<p><u>FRONT PADS 10mm</u></p> <p><u>REAR PADS 7mm</u></p>	

INSPECTOR: JLM DATE: 8/17/2022



# Invoice

Ridge Motors Auto Repair and Tires  
 Unit 8 - 20071 113B Avenue  
 Maple Ridge, BC V2X 0Z2  
 (604) 460-7142

Date	Invoice #
8/17/2022	3143

GST/HST No. 758148118

Invoice To
Cypress Auto Brokers 11919 Maple Meadowa Way Maple Ridge BC V2X3M7

Vehicle Description
2004 GMC Savana

ODO IN	ODO OUT	Plate	VIN
191534			1gtgg25v741102406

Quantity	Item	Description	Price Each	Amount	Tax
2.5	I_Inspection_Gen...		80.00	80.00	G
	L_Misc_Exterior	replace bumper	65.00	162.50	G
	P_Misc	hardware	20.00	20.00	G
	P_Filter	air filter	25.99	25.99	G
	S_Misc_Shop_M...		5.00	5.00	G
		GST on sales	5.00%	14.67	
<b>Sales Tax Total</b>				\$14.67	
<b>Total</b>				\$308.16	

I hereby authorize you and your employees to carry out the repair work described above and to purchase on my account any parts and materials necessary to carry out the repair work subject to the estimate described above. I hereby authorize you and your employees to operate the vehicle listed above in connect with the repair work, including operation for the purposes of testing, inspection or delivery. I HERBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repair work authorized hereby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repair work.

By signing below I acknowledge and agree to the terms and conditions above

Customer Signature \_\_\_\_\_



**JIFFY LUBE #1087**

20284 Dewdney Trunk Rd  
Maple Ridge, BC V2X 3E1  
(604) 465-0181

DATE 8/23/2022 11:10 AM  
TRANSACTION NO 22082300022338  
INVOICE NO 01087-22338  
VEHICLE ID BC-CYP

Customer Information	Service History						
Cypress Auto Brokers 11919 Maple Meadows Way MAPLE RIDGE, BC V2X 3M7 (604) 465-3313	<table border="1"> <thead> <tr> <th>DATE</th> <th>KILOMETERS</th> <th>SERVICES</th> </tr> </thead> <tbody> <tr> <td>8/23/22</td> <td>191540</td> <td>CYP OF PSS RDS</td> </tr> </tbody> </table>	DATE	KILOMETERS	SERVICES	8/23/22	191540	CYP OF PSS RDS
DATE	KILOMETERS	SERVICES					
8/23/22	191540	CYP OF PSS RDS					
Vehicle Information							
2004 GMC TRUCKS SAVANA 2500 8cyl 4.8L FI VIN 1GTGG25V741102406 ALT ID KILOMETERS 191540							

Employees	Service Comments								
<table border="1"> <thead> <tr> <th>UPPER</th> <th>LOWER</th> <th>COURTESY</th> <th>CASHIER</th> </tr> </thead> <tbody> <tr> <td>HARGUN</td> <td>PREM</td> <td>HARGUN</td> <td></td> </tr> </tbody> </table>	UPPER	LOWER	COURTESY	CASHIER	HARGUN	PREM	HARGUN		THANK YOU FOR YOUR BUSINESS!!!
UPPER	LOWER	COURTESY	CASHIER						
HARGUN	PREM	HARGUN							

Service Checklist	Description	Qty.	Price
1. CHASSIS LUBRICATION	SEALED	CYP OIL PACKAGE	1.00 39.99
2. REAR DIFFERENTIAL	REPLACED	OIL FILTER # PZ 48	1.00 0.00
3. TRANS/TRANSAXLE FLUID	FULL	PENNZOIL 5W30 OIL	5.70 0.00
4. LIGHT CHECK	CHECKED OK	FREE WASHER FLUID TOP UP	1.00 0.00
5. WIPER BLADES	CUST. OK'D	POWERSTEERING SERVICE	1.00 59.99
6. AIR FILTER	CHECKED	REAR DIFF. SERVICE	1.00 79.99
7. CABIN AIR FILTER	NO CHECK	REG 80W90 GEAR OIL	3.00 0.00
8. FUEL FILTER	NA		
9. POWER STEERING FLUID	SERVICED	<b>SUBTOTAL</b>	<b>\$179.97</b>
10. BRAKE FLUID	LEVEL OK	\$10 off any service (\$10OFF)	-10.00
11. BATTERY	CHECKED OK	Employee Offer \$10 (EO \$10)	-10.00
12. RADIATOR FLUID	FULL	Employee Offer \$12 (EO \$12)	-12.00
13. WINDSHIELD WASH FLUID	ADDED	(AIR)	-0.00
14. TRANSFER CASE FLUID	N/A		
15. FRT DIFFERENTIAL FLUID	N/A	<b>SALE</b>	<b>\$147.97</b>
16. CV BOOTS	CHECKED OK	GST TAX	7.40
17. SHOCKS/STRUTS	APPEARS O.K	PST TAX (Exempt 10144575)	0.00
18. TIRES	TPM	<b>TOTAL</b>	<b>\$155.37</b>
19. U JOINTS	N/A	VISA 3115 AUTH: 008018i	155.37
20. BELTS AND HOSES	CHECK OK	<b>CHANGE</b>	<b>\$0.00</b>

**Warranty Statement**

This Jiffy Lube centre warrants all workmanship against failure for 7 days from the date of service. This warranty does not apply when the customer tampers with or alters the centre's products or alters the manufacturer's original equipment or when corrective action is taken without prior written approval from this Jiffy Lube service centre. The customer must have the limited warranty certificate and must retain a sample of the product(s) involved.  Oil Level Shown  Oil Filter Tight  Drain Plug Tight  Rear Diff Chk Plug  Front Diff Chk Plug  Transfer Case Chk Plug  Transmission Chk Plug

\*OPEN SUN - SAT 9-6. ANY QUESTIONS CALL 604-465-0181  
APPROPRIATE, WARRANTY-APPROVED PRODUCT MAY HAVE BEEN SUBSTITUTED.  
  
**Recommend next service on 02/19/2023 or 196540 km.**

**X**

Cardholder acknowledges receipt of goods and/or services in the amount shown hereon and agrees to perform the obligations set forth in the Cardholder's agreement with the issuer.