




2012 DODGE RAM VAN

Van cargo | 6 Cylinders | Flexible
2C4JDGAG6CR420398
Country of Assembly: Canada
Last Reported Odometer: 72,456 KM




Accident/Damage Records Found



Last Registered In:
British Columbia (Normal)



11 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of September 06, 2022 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.**

Vehicle History Report (BC)



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2021 May 17	British Columbia, Canada	
	Estimate: RIGHT SIDE Estimate Date: n/a	\$1,690.01
	Claim: VANDALISM RIGHT SIDE	\$1,524.47
2021 Dec 1	British Columbia, Canada	
	Claim: COLLISION	\$0.00



Registration

This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records


DATE	ODOMETER	SOURCE	DETAILS
2013 Jul 15	13,137 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none">Oil and filter changed
2013 Dec 16	18,588 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none">Tires rotatedOil and filter changed
2014 Jun 24	24,903 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none">Air filter replacedWipers/washers checkedWiper(s) replacedA/C system checkedCabin air filter replaced/cleanedOil and filter changedFront brake rotor(s) resurfacedFront brake pads replacedBrake rotor(s) resurfaced
2014 Dec 11	31,084 KM	Service Facility	Vehicle serviced <ul style="list-style-type: none">Front brake rotor(s) replacedFront brake pads replacedOil and filter changed

2015 Jun 25	38,481 KM	Service Facility	Vehicle serviced
			<ul style="list-style-type: none"> Oil and filter changed Brake rotor(s) resurfaced Rear brake pads replaced Front brake pads replaced
2015 Dec 29	45,242 KM	Service Facility	Vehicle serviced
			<ul style="list-style-type: none"> Oil and filter changed Tire(s) replaced Tire condition and pressure checked Thrust angle alignment performed
2016 Aug 16	55,775 KM	Service Facility	Vehicle serviced
			<ul style="list-style-type: none"> Air filter replaced Wiper(s) replaced Fluids checked Cabin air filter replaced/cleaned A/C system checked Rear brake rotor(s) replaced Front brake rotor(s) replaced Oil and filter changed
2017 Jan 6	60,975 KM	Coquitlam Chrysler Coquitlam, British Columbia, Canada	Vehicle serviced
			<ul style="list-style-type: none"> Front axle(s) replaced/repared
2017 Jan 9		Service Facility	Vehicle serviced
			<ul style="list-style-type: none"> Oil and filter changed
2017 Jun 7	67,066 KM	Service Facility	Vehicle serviced
			<ul style="list-style-type: none"> Oil and filter changed Tire repaired Tire(s) mounted Front brake rotor(s) replaced Front brake pads replaced Rear brake pads replaced
2019 Jan 4		Kal Tire - New Westminster New Westminster, British Columbia, Canada	Vehicle serviced
			<ul style="list-style-type: none"> One tire mounted One tire balanced Four wheel alignment performed

Open Recalls

 No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact DODGE or visit [Dodge's website](#).

Stolen Vehicle Check

 This vehicle is not actively declared stolen.

Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2012 Sep 22		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Lease
2013 Jul 15	13,137 KM	Service Facility	Service Record	Vehicle serviced
2013 Sep 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2013 Dec 16	18,588 KM	Service Facility	Service Record	Vehicle serviced
2014 Jun 24	24,903 KM	Service Facility	Service Record	Vehicle serviced
2014 Oct 4		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2014 Dec 11	31,084 KM	Service Facility	Service Record	Vehicle serviced
2015 Jun 25	38,481 KM	Service Facility	Service Record	Vehicle serviced
2015 Oct 3		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2015 Dec 29	45,242 KM	Service Facility	Service Record	Vehicle serviced
2016 Aug 16	55,775 KM	Service Facility	Service Record	Vehicle serviced
2016 Oct 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2017 Jan 6	60,975 KM	Coquitlam Chrysler Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced
2017 Jan 9		Service Facility	Service Record	Vehicle serviced
2017 Jun 7	67,066 KM	Service Facility	Service Record	Vehicle serviced
2017 Sep 30		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2017 Dec 7	72,456 KM	Auto Auction	Auction Announcement	Vehicle sold
2017 Dec 9		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported

2018 Jan 20	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2018 Apr 28	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Jan 4	Kal Tire - New Westminster New Westminster, British Columbia, Canada	Service Record	Vehicle serviced
2019 Jan 13	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2019 Feb 24	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2020 Jan 13	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2021 May 17	Insurance Records British Columbia, Canada	VANDALISM	RIGHT SIDE
2021 May 17	Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a RIGHT SIDE
2021 Aug 29	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2021 Dec 1	Insurance Records British Columbia, Canada	COLLISION	
2022 Sep 1	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/Limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

Conditions of Use

© Copyright 2005 - 2022 CARFAX Canada ULC. All rights reserved.



2C4JDGAG6CR420398



UNIT #8 - 20071 113B AVENUE
 MAPLE RIDGE, BC V2X 0Z2
 O: 604 460 7142
 C: 604 721 1432
 RIDGEMOTORSAUTOREPAIR@GMAIL.COM

CYPRUS MULTI-POINT INSPECTION

Name: AUTO REPAIR Year/Make/Model: 2012 RAM CV KMs: 130515

RO#: 3227 VIN: 2C4JD6A66CR420398 License: _____

■ CHECKED AND OK ■ FUTURE ATTENTION ■ IMMEDIATE ATTENTION

INTERIOR/EXTERIOR	
NOTE ANY EXISTING BODY DAMAGE	
Lights (Head, Brake, Turn, Parking)	■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>
Windshield / Glass	■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>
Wipers	■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>
Horn / Interior Lights	■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>

TIRES	
TREAD DEPTH	
■ 7/32" or greater	■ 3/32" to 6/32" ■ 2/32" or less
LF ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>	RF ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>
LR ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>	RR ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>
	Wear Pattern / Damage LF ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> RF ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> LR ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> RR ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>
	Air Pressure <input checked="" type="checkbox"/> (!) BEFORE SHOULD BE LF <input type="text" value="32"/> <input type="text" value="32"/> RF <input type="text" value="32"/> <input type="text" value="32"/> LR <input type="text" value="32"/> <input type="text" value="32"/> RR <input type="text" value="32"/> <input type="text" value="32"/>
	Based on Mileage and Wear: <input type="checkbox"/> Alignment <input type="checkbox"/> Balance <input type="checkbox"/> Rotation <input type="checkbox"/> New Tire

BATTERY	
■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>	

UNDERHOOD	
Oil Condition	■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>
Transmission Fluid	■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>
Power Steering / Brake Fluid	■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>
Coolant / Antifreeze	■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>
Air Filter	■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>
Cabin Filter	■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>
Belts	■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>

UNDER VEHICLE	
Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>
Suspension & Steering	■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>
Driveline (Axles / CV Shaft)	■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>
Rear Differential Fluid Level & Condition	■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>
Exhaust System / Shocks & Struts	■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>

BRAKES	
BRAKE PADS / SHOES	
■ Over 5 mm (Disk) or 2 mm (Drum)	
■ 3-5 mm (Disk) or 1.01-2 mm (Drum)	
■ Less than 3 mm (Disk) or 1 mm (Drum)	
LF ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> RF ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> LR ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> RR ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/> ■ <input checked="" type="checkbox"/>	

COMMENTS	
<u>FRONT PADS 11mm</u>	
<u>REAR PADS 10mm</u>	

INSPECTOR: JLM DATE: 9/28/2022

Ridge Motors Auto Repair and Tires
 Unit 8 - 20071 113B Avenue
 Maple Ridge, BC V2X 0Z2
 (604) 460-7142

Invoice

Date	Invoice #
9/28/2022	3227

GST/HST No. 758148118

Invoice To
Cypress Auto Brokers 11919 Maple Meadowa Way Maple Ridge BC V2X3M7

Vehicle Description
2012 Ram CV

ODO IN	ODO OUT	Plate	VIN
130515			2c4jdgag6cr420398

Quantity	Item	Description	Price Each	Amount	Tax
2	I_Inspection_Gen...		80.00	80.00	G
2	L_BrakesPadsRot...		65.00	130.00	G
2	P_Calipers_Front		95.63	191.26	G
2	P_Rotors_Front		73.46	146.92	G
1	P_Pads_Front		55.88	55.88	G
1.5	L_Brakes_Pads_L...		65.00	97.50	G
0.8	L_Misc_Brakes	replace left rear park brake cable	65.00	52.00	G
1	P_Misc_Brakes	park brake cable left rear	61.86	61.86	G
2	P_Rotors_Rear		51.95	103.90	G
1	P_Pads_Rear		49.88	49.88	G
1.8	L_Misc_Transmis...	replace both transmission cooler lines	65.00	117.00	G
	P_Misc	transmission cooler lines	101.23	101.23	G
	P_Misc	rear wiper arm and blade	120.00	120.00	G
		GST on sales	5.00%	65.37	
Sales Tax Total				\$65.37	
Total				\$1,372.80	

I herby authorize you and your employees to carry out the repair work described above and to purchase on my account any parts and materials necessary to carry out the repair work subject to the estimate described above. I herby authorize you and your employees to operate the vehicle listed above in connect with the repair work, including operation for the purposes of testing, inspection or delivery. I HERBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repair work authorized herby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repair work.

By signing below I acknowledge and agree to the terms and conditions above

Customer Signature _____

CUSTOMER #: 39438

569127



11911 West St. · Maple Ridge, BC V2X 3M6
Service Direct 604-465-8964
Main Phone 604-465-8931 · Fax 604-465-8930
service@mapleridgechrysler.com
www.mapleridgechrysler.com

CYPRESS AUTOBROKERS
11919 MAPLE MEADOWS WAY
MAPLE RIDGE, BC V2X 3M6
HOME:604-465-3313 CONT:604-465-3313
BUS: 604-719-7615 CELL:

INVOICE

DUPLICATE 1
PAGE 1

SERVICE ADVISOR: 119564 PADRAIC GARRETY

Table with columns: COLOUR, YEAR, MAKE/MODEL, VIN, LICENSE, ODOMETER IN/OUT, TAG. Includes details for a white Dodge Ram Cargo Van with VIN 2C4JDGAG6CR420398.

Table with columns: LINE, OPCODE, TECH, TYPE, HOURS, RETAIL, NET, TOTAL. Includes a note about a check and report for ABS and TRAC control message.

CAUSE: multiple warning lights on in cluster.tipm recently replaced.
EC Check & Report for Electrical Concern -
Excluding battery, alternator, and starter -
Authorizing up to one hour of diagnostics.

Table with columns: PARTS, LABOR, OTHER, TOTAL LINE A. Shows 0.00 labor and 449.75 other charges.

130549 multiple warning lights on in cluster.tipm recently replaced. scan and inspect for trac light and abs light and airbag lights on in dash.tipm was just replaced with what looks like used unit.perform vehicle reconfig and erase stored codes and road test.lights on dash off now.noticed on roadtest front signals inop.check power at fuses in tipm per wiring diagram.no power at fuses.report to advisor will need time to diag.new tipm 1300.00 portland stk.inspect replacement tipm and check tsb's and starcse files and diconnect tipm and inspect wiring to c4 connector.check dom on tipm and reconfigure wiring in c4 for front signals as per starcase s1608000099.reconnect tipm and verify signals operational now.rescan.no dtcs now.

B** PST# 10144575
NOTE PST

Table with columns: PARTS, LABOR, OTHER, TOTAL LINE B. Shows 0.00 labor and 0.00 other charges.

Enviro Compliance/Chemical/Cleaner/Disposal Fee

Table with columns: CASH, CHEQUE, DEBIT, AMEX, MASTERC, VISA, CHARGE. Shows a total of 60.63.

Table with columns: DESCRIPTION, TOTALS. Includes a signature line for the customer and a 'PLEASE PAY THIS AMOUNT' section.



JIFFY LUBE #1067

20284 Dewdney Trunk Rd
Maple Ridge, BC V2X 3E1
(604) 465-0181

DATE 10/3/2022 11:43 AM
TRANSACTION NO 22100300022598
INVOICE NO 01087-22598
VEHICLE ID BC-CYP

Customer Information

Cypress Auto Brokers
11919 Maple Meadows Way
MAPLE RIDGE, BC V2X 3M7 (604) 465-3313

Service History

DATE KILOMETERS SERVICES

10/3/22 130559 CYP OF PSS

wasworld maple ridge
WASH CODE: 011-718-855
Expires Oct 23, 2022

Vehicle Information

2012 DODGE/RAM CARGO VAN 6cyl 3.6L FI
VIN 2C4JDGAG6CR420398
ALT ID KILOMETERS 130559

Employees

UPPER LOWER COURTESY CASHIER
NAVI ROMAN HARGUN

Service Comments

THANK YOU FOR YOUR BUSINESS!!!

Service Checklist

- | | |
|----------------------------|------------|
| 1. CHASSIS LUBRICATION | ___ GREASE |
| 2. REAR DIFFERENTIAL | NO CHECKS |
| 3. TRANS/TRANSAXLE FLUID | FULL |
| 4. LIGHT CHECK | CHECKED OK |
| 5. WIPER BLADES | CUST. OK'D |
| 6. AIR FILTER | REC REPLCD |
| 7. CABIN AIR FILTER | REC REPLCD |
| 8. FUEL FILTER | NA |
| 9. POWER STEERING FLUID | FULL |
| 10. BRAKE FLUID | LEVEL OK |
| 11. BATTERY | NO CHECKS |
| 12. RADIATOR FLUID | FULL |
| 13. WINDSHIELD WASH FLUID | ADDED |
| 14. TRANSFER CASE FLUID | N/A |
| 15. FRT DIFFERENTIAL FLUID | N/A |
| 16. CV BOOTS | CHECKED OK |
| 17. SHOCKS/STRUTS | NA |
| 18. TIRES | F__ R__ |
| 19. U JOINTS | N/A |
| 20. BELTS AND HOSES | NA |

Description

Qty. Price

CYP OIL PACKAGE	1.00	39.99
CF6135 OIL FILTER	1.00	0.00
SPECIAL FILTER CHARGE	0.01	0.10
PENNZOIL 5W30 OIL	5.60	0.00
POWERSTEERING SERVICE	1.00	59.99
SUBTOTAL		\$100.08
\$10 OFF COUPON (10)		-10.00
\$5off (5)		-5.00
(AIR)		-0.00
SALE		\$85.08
GST TAX		4.25
PST TAX (Exempt 10144575)		0.00
TOTAL		\$89.33
VISA 3115 AUTH: 001559		89.33
CHANGE		\$0.00

Warranty Statement

This Jiffy Lube centre warrants all workmanship against failure for 7 days from the date of service. This warranty does not apply when the customer tampers with or alters the centre's products or alters the manufacturer's original equipment or when corrective action is taken without prior written approval from this Jiffy Lube service centre. The customer must have the limited warranty certificate and must retain a sample of the product(s) involved. ___ Oil Level Shown ___ Oil Filter Tight ___ Drain Plug Tight ___ Rear Diff Chk Plug ___ Front Diff Chk Plug ___ Transfer Case Chk Plug ___ Transmission Chk Plug

OPEN SUN-SAT 9-6. ANY QUESTIONS CALL 604-465-0181
APPROPRIATE, WARRANTY-APPROVED PRODUCT MAY HAVE BEEN SUBSTITUTED.

X

Cardholder acknowledges receipt of goods and/or services in the amount shown herein and agrees to perform the obligations set forth in the Cardholder's agreement with the issuer.

Recommend next service on 04/01/2023 or 135559 km.