



Vehicle History Report (BC) #: 41564765
Report Date: September 6, 2022 | 01:06 PM EST
Report Status: Complete

2013 VOLKSWAGEN JETTA

3VWDL7AJ3DM200542


Country of Assembly: n/a

Last Reported Odometer: 80,960 KM

NO REPORTED
ACCIDENTS



Glass Records found



Last Registered In:
British Columbia (Normal)



10 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of **September 06, 2022** (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

3VWDL7AJ3DM200542

Vehicle History Report (BC)



Accident/Damage



There are no police reported accidents, estimates, or claims reported on this vehicle, however, we found other damage records that are outlined below.

Other Damage Records

RECORD DATE	DETAILS	AMOUNT
2014 Mar 6	British Columbia, Canada	
	Glass Record	\$940.98



Registration



This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2013 May 23	19,541 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Vehicle serviced
2013 Sep 6	25,849 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none">Maintenance inspection completedOil and filter changedTire condition and pressure checkedBody lubricated
2013 Dec 24	34,586 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none">Maintenance inspection completedDrivability/performance checkedOil and filter changedTires rotatedGlove box latch replacedGlove box door replacedGlove box repaired/replacedInterior trim repaired
2014 Jun 10	42,419 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none">Battery replacedBattery servicedOil and filter changed

3WMDL7A13DM200542

DATE	ODOMETER	SOURCE	DETAILS
			<ul style="list-style-type: none"> Tire condition and pressure checked Body lubricated Cooling system checked Coolant reservoir replaced Glow plug controller replaced Drivability/performance checked
2015 Feb 13	49,948 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Drivability/performance checked Oil and filter changed Tires rotated Water separator serviced Vehicle washed/detailed
2015 Dec 28	58,830 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Tire condition and pressure checked Body lubricated Headlight bulb(s) replaced Engine/powertrain computer/module reprogrammed Fluids checked
2018 Aug 21	60,455 KM	Turner Volkswagen Kelowna, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed Antifreeze/coolant checked Battery/charging system checked Brakes checked Cabin air filter replaced/cleaned Oil and filter changed Brake fluid flushed/changed Windshield replaced Radio code retrieved Wipers/washers serviced Wiper(s) replaced Front brake pads replaced Rear brake pads replaced Horn replaced
2018 Nov 28		Turner Volkswagen Kelowna, British Columbia, Canada	Vehicle serviced
2018 Dec 14	60,461 KM	Turner Volkswagen Kelowna, British Columbia, Canada	Vehicle serviced
2021 Jan 15	80,960 KM	Turner Volkswagen Kelowna, British Columbia, Canada	Vehicle serviced



Open Recalls



No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact VOLKSWAGEN or visit [Volkswagen's website](#).



Stolen Vehicle Check



This vehicle is not actively declared stolen.

3VWDL7A|3DM200542



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2012 Nov 17		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Lease
2013 May 23	19,541 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Service Record	Vehicle serviced
2013 Sep 6	25,849 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Service Record	Vehicle serviced
2013 Nov 16		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2013 Dec 24	34,586 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Service Record	Vehicle serviced
2014 Mar 6		Insurance Records British Columbia, Canada	Glass Record	\$940.98
2014 Jun 10	42,419 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Service Record	Vehicle serviced
2014 Nov 15		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2015 Feb 13	49,948 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Service Record	Vehicle serviced
2015 Nov 14		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2015 Dec 28	58,830 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Service Record	Vehicle serviced
2016 Feb 13		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2018 Aug 12		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported

3WDL7AJ3DM200542

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Aug 21	60,455 KM	Turner Volkswagen Kelowna, British Columbia, Canada	Service Record	Vehicle serviced
2018 Nov 28		Turner Volkswagen Kelowna, British Columbia, Canada	Service Record	Vehicle serviced
2018 Dec 14	60,461 KM	Turner Volkswagen Kelowna, British Columbia, Canada	Service Record	Vehicle serviced
2018 Dec 23		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2019 Dec 22		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Mar 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 May 19		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Jan 15	80,960 KM	Turner Volkswagen Kelowna, British Columbia, Canada	Service Record	Vehicle serviced
2021 May 16		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2022 May 19		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/Limitation.html>.
ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability.

3WDL7AJ3DM200542

merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. Conditions of Use

© Copyright 2005 - 2022 CARFAX Canada ULC. All rights reserved.



3WDL7AJ3DM200542



UNIT #8 - 20071 113B AVENUE
 MAPLE RIDGE, BC V2X 0Z2
 O: 604 460 7142
 C: 604 721 1432
 RIDGEMOTORSAUTOREPAIR@GMAIL.COM

Cypress MULTI-POINT INSPECTION

Name: ANTO BROKER Year/Make/Model: 2013 VW JETTA KMs: 117812

RO#: 3273 VIN: 3VWD17A5BDM200542 License: _____

☒ CHECKED AND OK ☐ FUTURE ATTENTION ☐ IMMEDIATE ATTENTION

INTERIOR/EXTERIOR	
NOTE ANY EXISTING BODY DAMAGE	
Lights (Head, Brake, Turn, Parking)	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Windshield / Glass	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Wipers	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Horn / Interior Lights	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

BATTERY	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

UNDERHOOD	
Oil Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Transmission Fluid	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Power Steering / Brake Fluid	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Coolant / Antifreeze	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Air Filter	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Cabin Filter	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Belts	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

UNDER VEHICLE	
Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Suspension & Steering	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Driveline (Axles / CV Shaft)	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Rear Differential Fluid Level & Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Exhaust System / Shocks & Struts	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

TIRES	
TREAD DEPTH	
<input checked="" type="checkbox"/> 7/32" or greater <input type="checkbox"/> 3/32" to 6/32" <input type="checkbox"/> 2/32" or less	
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 10/32" RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 10/32" LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 10/32" RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 10/32"	Air Pressure BEFORE SHOULD BE LF 32 32 RF 32 32 LR 32 32 RR 32 32
Based on Mileage and Wear: <input type="checkbox"/> Alignment <input type="checkbox"/> Balance <input type="checkbox"/> Rotation <input type="checkbox"/> New Tire	

BRAKES	
BRAKE PADS / SHOES	
<input checked="" type="checkbox"/> Over 5 mm (Disk) or 2 mm (Drum) <input type="checkbox"/> 3-5 mm (Disk) or 1.01-2 mm (Drum) <input type="checkbox"/> Less than 3 mm (Disk) or 1 mm (Drum)	
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

COMMENTS	
front pads	8mm
rear pads	10mm

INSPECTOR: JIM DATE: 10/13/2022

Ridge Motors Auto Repair and Tires
Unit 8 - 20071 113B Avenue
Maple Ridge, BC V2X 0Z2
(604) 460-7142

Invoice

Date	Invoice #
10/13/2022	3273

GST/HST No. 758148118

Invoice To

Cypress Auto Brokers
11919 Maple Meadow Way
Maple Ridge BC
V2X3M7

Vehicle Description

2013 VW Jetta

ODO IN	ODO OUT	Plate	VIN
117812			3vwdl7aj3dm200542

Quantity	Item	Description	Price Each	Amount	Tax
	I_Inspection_Gen...		80.00	80.00	G
	L_Misc_Tire	includes mounting and balancing	80.00	80.00	G
	S_Misc_Shop_M...	wheel weights	4.00	4.00	G
		GST on sales	5.00%	8.20	
			Sales Tax Total	\$8.20	
			Total	\$172.20	

I herby authorize you and your employees to carry out the repair work described above and to purchase on my account any parts and materials necessary to carry out the repair work subject to the estimate described above. I herby authorize you and your employees to operate the vehicle listed above in connect with the repair work, including operation for the purposes of testing, inspection or delivery. I HERBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repair work authorized herby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repair work.

By signing below I acknowledge and agree to the terms and conditions above

Customer Signature _____