



2017 KIA SPORTAGE LX

Sport utility vehicle | 4 Cylinders | Gas

KNDPMCAC1H7275053

Country of Assembly: Korea (South)

Last Reported Odometer: 133,002 KM


LIEN CHECK



No Lien Records Found



Accident/Damage Records Found



Last Registered In:
British Columbia (Normal)




2 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of October 20, 2022 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report + Lien Check (BC)

Lien Check

No lien records found in **British Columbia**.

How We Check for Liens

CARFAX Canada uses the VIN to search government records in each Canadian province and territory (excluding Northwest Territories) where the vehicle is currently registered and where it has historically been registered. We do not check for liens or title in any U.S. state.

If a VIN has no registration records in Canada, we cannot check for liens. We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty equipment.

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.

CARFAX Canada Canadian Lien Guarantee



If for some reason our lien check fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian (\$5,000.00), whichever is lower.

Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2017 Sep 17	British Columbia, Canada	
	Estimate: RIGHT FRONT CORNER Estimate Date: n/a	\$2,202.93
	Claim: COLLISION RIGHT FRONT CORNER	\$2,202.93
2019 Jul 29	British Columbia, Canada	
	Estimate: RIGHT REAR CORNER Estimate Date: n/a	\$1,143.10
	Claim: COLLISION RIGHT REAR CORNER	\$1,143.10
2021 Jun 23	British Columbia, Canada	
	Estimate: RIGHT FRONT CORNER Estimate Date: n/a	\$1,780.38
	Claim: COLLISION RIGHT FRONT CORNER	\$1,780.38

Registration

This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2018 Jul 27	30,000 KM	Jiffy Lube # 1087 Maple Ridge, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Fluids checked
2022 May 17		West Coast Ford Lincoln Maple Ridge, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed Maintenance inspection completed Tire condition and pressure checked Brakes checked



Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact KIA or visit [Kia's website](#).



Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 Jun 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2017 Aug 26		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Sep 17		Insurance Records British Columbia, Canada	COLLISION	RIGHT FRONT CORNER
2017 Sep 17		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a RIGHT FRONT CORNER
2017 Oct 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Apr 12	20,872 KM	Kia PITT MEADOWS, British Columbia, Canada	Odometer reading	
2018 Jul 27	30,000 KM	Jiffy Lube # 1087 Maple Ridge, British Columbia, Canada	Service Record	Vehicle serviced

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Sep 2		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Sep 26	34,610 KM	Kia PITT MEADOWS, British Columbia, Canada	Odometer reading	
2019 May 29	50,368 KM	Kia PITT MEADOWS, British Columbia, Canada	Odometer reading	
2019 Jul 29		Insurance Records British Columbia, Canada	COLLISION	RIGHT REAR CORNER
2019 Jul 29		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a RIGHT REAR CORNER
2019 Jul 29	56,220 KM	Kia PITT MEADOWS, British Columbia, Canada	Odometer reading	
2019 Sep 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Jul 21	82,457 KM	Kia PITT MEADOWS, British Columbia, Canada	Odometer reading	
2020 Sep 4		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Jun 22	110,990 KM	Kia PITT MEADOWS, British Columbia, Canada	Odometer reading	
2021 Jun 23		Insurance Records British Columbia, Canada	COLLISION	RIGHT FRONT CORNER
2021 Jun 23		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a RIGHT FRONT CORNER
2021 Aug 22		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2022 May 11		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2022 May 12	133,002 KM	West Coast Ford Lincoln Maple Ridge, British Columbia, Canada	Odometer reading	
2022 May 17		West Coast Ford Lincoln Maple Ridge, British Columbia, Canada	Service Record	Vehicle serviced

KNDPMCAC1H7Z5053



West Coast Motors Ltd. d.b.a. WEST COAST FORD LINCOLN

20370 Lougheed Hwy., Maple Ridge, B.C. V2X 2P8
Tel: 604-465-5434 Fax: 604-465-5764
westcoastfordlincoln.com

O U T INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.
DATE _____ SIGNATURE _____

ALL ITEMS ARE SUBJECT TO G.S.T.

CUSTOMER NO. 995	ADVISOR JOSEF REBAIKIN	TAG NO. 2716 5053	INVOICE DATE 05/17/22	INVOICE NO. FCCS196935
WEST COAST FORD LINCOLN 20370 LOUGHEED HWY MAPLE RIDGE, BC V2X 2P8	LABOUR RATE 159.95	LICENSE NO. 133,002	COLOUR NOT KNOWN/	STOCK NO. UT275053
	YEAR/MAKE/MODEL 17/KIA/SPORTAGE/AWD 4DR LX	KILOMETRES	DELIVERY DATE	DELIVERY KMS. 133,002
	VEHICLE I.D. NO. K N D P M C A C 1 H 7 2 7 5 0 5 3		SELLING DEALER NO.	PRODUCTION DATE
	F.T.E. NO.	P.O. NO.	R.O. DATE 05/13/22	IN SERVICE DATE
RESIDENCE PHONE 604-465-5434	BUSINESS PHONE 604-465-5434	COMMENTS F# 2.4L I4 GAS	MO: 133575	

JOB# 1 CHARGES-----
LABOR-----
J# 1 44FCZZ03 USED VEHICLE INSP. TECH(S):3352 INTERNAL
COMPLAINT: ROAD TEST VEHICLE, COMPLETE USED VEHICLE INSPECTION ON VEHICLE AND REPORT FINDINGS.
CORRECTION: COMPLETED USED VEHICLE INSPECTION. CHANGED ENGINE OIL AND FILTER. TOPPED UP FLUID LEVELS AND COMPLETED INSPECTION

SUBLET	PO#	VEND	INV#	INV.DATE	DESCRIPTION	
	113605	87372		05/17/22	USED CAR INSPECTION	INTERNAL
	113605	87372		05/17/22	REPALCE LOW/HIGH BEAM BULBS	INTERNAL
	113605	87372		05/17/22	SHOP SUPPLIES	INTERNAL
TOTAL - SUBLET						0.00

JOB# 1 TOTALS-----
JOB# 1 JOURNAL PREFIX FCCS JOB# 1 TOTAL 0.00

JOB# 2 CHARGES-----
LABOR-----
J# 2 44FCZZ130 OWNERS MANUAL TECH(S):3352 INTERNAL
COMPLAINT: CHECK FOR OWNERS MANUAL AND ADVISE
CORRECTION: OWNERS MANUAL IN VEHICLE

JOB# 2 TOTALS-----
JOB# 2 JOURNAL PREFIX FCCS JOB# 2 TOTAL 0.00

JOB# 3 CHARGES-----
LABOR-----
J# 3 44FCZZ135 2 KEYS TECH(S):3352 INTERNAL
COMPLAINT: CHECK FOR TWO KEYS AND FOBS AND REPORT
CORRECTION: TWO KEY FOBS SUPPLIED

JOB# 3 TOTALS-----
JOB# 3 JOURNAL PREFIX FCCS JOB# 3 TOTAL 0.00

JOB# 4 CHARGES-----
LABOR-----
J# 4 44FCZZ165 TIRE INFO TECH(S):3352 INTERNAL
COMPLAINT: RECORD TIRE BRAND, MAKE, MODEL, SIZE AND SPEED RATINGS
RECORD TREAD DEPTH MEASUREMENTS IN MM.
CORRECTION: SEE REPORT CARD

JOB# 4 TOTALS-----
JOB# 4 JOURNAL PREFIX FCCS JOB# 4 TOTAL 0.00

JOB# 5 CHARGES-----
LABOR-----
J# 5 44FCZZ170 BRAKE INSPECTION TECH(S):3352 INTERNAL
COMPLAINT: PERFORM BRAKE INSPECTION
CORRECTION: SEE REPORT CARD



Scan to Book your Next Service



Thank You for allowing us to care for your vehicle

ELC-S11 (9-99) Copyright © 1995 The Reynolds and Reynolds Company (Canada) Ltd. CC618142 Q (07/22)



West Coast Motors Ltd. d.b.a. WEST COAST FORD LINCOLN

20370 Lougheed Hwy., Maple Ridge, B.C. V2X 2P8
Tel: 604-465-5434 Fax: 604-465-5764
westcoastfordlincoln.com

O U T INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ _____ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.
DATE _____ SIGNATURE _____

ALL ITEMS ARE SUBJECT TO G.S.T.

CUSTOMER NO. 995	ADVISOR JOSEF REBALKIN	TAG NO. 2716 5053	INVOICE DATE 05/17/22	INVOICE NO. FCCS196935
WEST COAST FORD LINCOLN 20370 LOUGHEED HWY MAPLE RIDGE, BC V2X 2P8	LABOUR RATE 159.95	LICENSE NO. 17/KIA/SPORTAGE/AWD 4DR LX	COLOUR NOT KNOWN/	STOCK NO. UT275053
	YEAR/MAKE/MODEL 17/KIA/SPORTAGE/AWD 4DR LX	KILOMETRES 133,002	DELIVERY DATE	DELIVERY KMS. 133,002
	VEHICLE I.D. NO. K N D P M C A C 1 H 7 2 7 5 0 5 3		SELLING DEALER NO.	PRODUCTION DATE
	F.T.E. NO. 105629984	P.O. NO. 113605	R. O. DATE 05/13/22	IN SERVICE DATE
RESIDENCE PHONE 604-465-5434	BUSINESS PHONE 604-465-5434	COMMENTS E# 2.4L I4 GAS	MO: 133575	

JOB# 5 TOTALS-----
JOB# 5 JOURNAL PREFIX FCCS JOB# 5 TOTAL 0.00

JOB# 6 CHARGES-----

LABOR-----
J# 6 44FCZZ175 RECORD MILEAGE TECH(S):3352 INTERNAL
COMPLAINT: RECORD MILEAGE
CORRECTION: SEE REPORT CARD

JOB# 6 TOTALS-----
JOB# 6 JOURNAL PREFIX FCCS JOB# 6 TOTAL 0.00

JOB# 7 CHARGES-----

LABOR-----
J# 7 14FCZZ04 VEHICLE REPORT CARD TECH(S):3352 INTERNAL
COMPLAINT: PERFORM VEHICLE REPORT CARD MULTI POINT INSPECTION AND REPORT.
CORRECTION: COMPLETED MULTI POINT INSPECTION

JOB# 7 TOTALS-----
JOB# 7 JOURNAL PREFIX FCCS JOB# 7 TOTAL 0.00

COMMENTS-----
DELETED OPERATION(S)-----
44FCZZ115 INSTALL WHEEL LOCKS 44FCZZ120 NITROGEN FILL TIRES

TAX SUMMARY-----
GST 0.00 R-105629984 PST 0.00 1002-7495

TOTALS-----

* AMEX [] M/C [] VISA [] WCAG CARD [] *
* CASH [] CHARGE [] DBT/CARD [] REDEEMED [] *

TOTAL LABOR... 0.00
TOTAL PARTS... 0.00
TOTAL SUBLET... 0.00
TOTAL G.O.G... 0.00
TOTAL MISC CHG. 0.00
TOTAL MISC DISC 0.00
TOTAL TAX..... 0.00

***** THANK YOU FOR YOUR BUSINESS *****
YOU MAY RECIEVE A FORD/LINCOLN SUVERY IN THE NEXT FEW DAYS
IF FOR ANY REASONS YOU CANNOT GIVE 5 STARS PLEASE CONTACT
SARAH HUDON AT 604.465.5434 OR SARAH@WESTCOASTAUTOGROUP.COM
OR TOLL FREE AT 1.800.847.2992

TOTAL INVOICE \$ 0.00

** Please see reverse of invoice for privacy notice **

CUSTOMER SIGNATURE _____
***** DUPLICATE INVOICE *****

FORD PERFORMANCE RACING PARTS
Authorized Distributor

Scan to Book your Next Service

Thank You for allowing us to care for your vehicle

CC618142 Q (07/22) ELC-S11 (9-99) Copyright © 1995 The Reynolds and Reynolds Company (Canada) LTD.

West Coast Ford Report Card

Customer Name: WEST COAST FORD LINCOLN Vehicle Year/Model: 17 KIA SPORTAGE
 Phone: (H) (604) 465-5434 VIN: KNDPMCAC1H7275053
 Service Advisor: JOSEF REBALKIN Technician: DANIEL DESHARNAIS

Printed: 11/09/2022 13:53:24
 Odometer: 133002
 RO: 196935 Tag: 5053

INSPECTION RESULT - OK **WILL REQUIRE FURTHER ATTENTION** **REQUIRES IMMEDIATE ATTENTION**

Green Yellow Red Serviced

<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Fill windshield washer fluid	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Inspect wipers/washers including front and rear blades	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Inspect exterior lamps/lights/bulbs (operation/damage)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Warning lights	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Inspect dash lights/interior lights/horn operation	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Interior	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Inspect air cleaner element	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Inspect cabin air filter (if equipped)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Inspect drive belts and hoses	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Inspect battery terminals and cables	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Check brake fluid level and condition	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Check engine coolant level and condition	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Check power steering fluid level and condition	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Check transmission fluid level and condition (most models)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Under hood	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Inspect front /rear differential and transfer case (leaks)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Inspect exhaust system (leaks/damage/loose parts)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Inspect brake system components (leaks/wear/damage)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Inspect steering system (leaks/wear/damage)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Inspect cooling system (leaks/wear/damage)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Inspect heating and air conditioning operation	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Inspect front suspension	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Inspect rear suspension	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Inspect axles/driveshaft(s)/U-joints/CV joints/boots	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Inspect transmission for leaks	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Inspect engine (leaks/wear/damage)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Inspect fuel tank/lines/connections	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Time/mileage requirements	<input type="checkbox"/>

Brake Lining Measurements: LF: 8 mm RF: 8 mm LR: 8 mm RR: 8 mm

Tire Tread Measurements: LF: 5/32" RF: 5/32" LR: 8/32" RR: 8/32"

Tire Pressure Measurements: LF: 35psi RF: 35psi LR: 35psi RR: 35psi

Front / Rear Brake Linings

Green
 Yellow
 Red

Green
 Yellow
 Red

Green
 Yellow
 Red

Green
 Yellow
 Red

Inspection Not Taken

More than 6mm
3mm to 5mm
2mm or less

Check Tires / Tread Depth

Green
 Yellow
 Red

Green
 Yellow
 Red

Green
 Yellow
 Red

Green
 Yellow
 Red

7/32" or Greater
4/32" to 6/32"
3/32" or Less

Check Battery Performance

Good
 Fair
 Bad

Actual Cold Cranking Amps

Factory Cold Cranking Amps