

2015 VOLKSWAGEN GOLF TDI

Hatchback | 4 Cylinders | Diesel 3VWRA7AU4FM079187 Country of Assembly: Mexico Last Reported Odometer: 117,999 KM



LIEN CHECK





Accident/Damage Records Found



Last Registered In: Ontario (Normal)



5 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



Vehicle History Report + Lien Check (BC)

Lien Check

No lien records found in Ontario.

No lien records found in Québec.

How We Check for Liens

CARFAX Canada uses the VIN to search government records in each Canadian province and territory (excluding Northwest Territories) where the vehicle is currently registered and where it has historically been registered. We do not check for liens or title in any U.S. state.

If a VIN has no registration records in Canada, we cannot check for liens. We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.

CARFAX Canada Canadian Lien Guarantee



If for some reason our lien check fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian (\$5,000.00),

whichever is lower.



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
② 2017 Jan 16	Québec, Canada	
	Police Reported Accident: Accident reported	

Registration

- This vehicle has been registered in the following locations in Canada (listed oldest to newest):
 - · In the province of Québec with Normal branding.
 - · In the province of Ontario with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

Service Records

DATE	ODOMETER	SOURCE	DETAILS
2021 May 3	76,235 KM	Competition Motors Belleville, Ontario, Canada	Vehicle serviced Oil and filter changed
2021 Aug 27	93,261 KM	Boyer Ford Stirling Stirling, Ontario, Canada	Vehicle serviced
2021 Nov 3	99,606 KM	Belleville Volkswagen Belleville, Ontario, Canada	Vehicle serviced
2021 Dec 8	103,000 KM	The Great Canadian Oil Change Nanaimo, British Columbia, Canada	Vehicle serviced • Maintenance inspection completed • Fluids checked • Oil and filter changed
2022 Oct 30	117,999 KM	Jiffy Lube - Chilliwack Chilliwack, British Columbia, Canada	Vehicle serviced Oil and filter changed Fluids checked

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact VOLKSWAGEN or visit Volkswagen's website.

Stolen Vehicle Check

This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS	
2015 Aug 19		Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported	
2016 Apr 1	ar 1823 Sala Parlam kuru sala Salam sala menganan kuru salam pana kuru sala sala sala sala sala sala sala sal	Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed	**************************************
2017 Jan 16		Police Reported Accident Québec, Canada	Police Report	Accident Reported:	
2017 Jan 25	ti Parasitati di di masa minimata Silverne (n. 1. 114 n. 144 n	Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed	ika a manandi (1975-a minisa a sara)
2018 Jan 31		Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed	Observative - company reference reservative
2018 Feb 19		Motor Vehicle Dept. Québec, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported	
2018 Apr 24		VOLKSWAGEN	Recall	Manufacturer Recall Issued Recall # 23Y8	***************************************
2018 May 29	Administration of the control of the second	Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed	**************************************
2018 May 31		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal	THE BUILDING WAS CONTROL
2018 Aug 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal	and the second s
2019 Aug 30		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal	
2021 May 3	76,235 KM	Competition Motors Belleville, Ontario, Canada	Service Record	Vehicle serviced	
2021 May 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Personal	
2021 Aug 27	93,261 KM	Boyer Ford Stirling Stirling, Ontario, Canada	Service Record	Vehicle serviced	
2021 Nov 3	99,606 KM	Belleville Volkswagen Belleville, Ontario, Canada	Service Record	Vehicle serviced	
2021 Dec 8	103,000 KM	The Great Canadian Oil Change Nanaimo, British Columbia,	Service Record	Vehicle serviced	

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2022 Oct 30	117,999 KM	Jiffy Lube - Chilliwack Chilliwack, British Columbia, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disclaimer

mation supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage salvage vehicles which have been rebuilt, inspected, and relicensed wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at http://apps.icbc.com/registration.vchr/Limitation.html.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

CARFAX Canada Low Kilometres™ Badge

The CARFAX Canada Low Kilometres baging is based on the odometer information reported to CARFAX Canada. The CARFAX Canada Low Kilometres badge is based on the odometer information reported to CARFAX Canada and that have accumulated, as reported to CARFAX Canada via odometer records, less than 18,000 kilometres. per year from the beginning of September in the year prior to the vehicle's model year until the date that this report was generated.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no report approximation from external sources believed to be reliable, but no report approximation from external sources believed to be reliable, but no report approximation from external sources believed to be reliable, but no report approximation from external sources believed to be reliable, but no report approximation from external sources believed to be reliable, but no report approximation from external sources believed to be reliable, but no report approximation from external sources believed to be reliable, but no report approximation from external sources believed to be reliable, but no report approximation from external sources believed to be reliable, but no report approximation from external sources approximation from external so be amended from time to time by CARFAX Canada, Conditions of Use

© Copyright 2005 - 2022 CARFAX Canada ULC. All rights reserved.





Private Vehicle Inspection Report

Decal Number: **Decal Expiry Date:** Inspection Number: FV14717 2023-Nov-30 20325275

Inspection Result: PASS

Facility: C C AUTO REPAIRS / S6237 Inspector:

Inspection Type: Clubine, Laurence Dean JOH / 105003

Inspection Class: Inspection Reason: Class 1 - Light Vehicle with LGWV 5500

New to BC

Complete

Inspection Start Date/Time:

2022-Nov-21 04:21 PM

Inspection Complete Date/Time: 2022-Nov-21 05:22 PM

Vehicle Jurisdiction:

Work Order Number:

Ontario

29285

Brake Type:

Hydraulic

Owner/Lessee Name:

CYPRESS AUTO SALES, ARON

Registration Number:

3VWRA7AU4FM079187

Fuel Type: Odometer: Diesel 119905 KM Address:

11919 MAPLE MEADOWS WAY

Plate Number:

0

Hub Odometer:

City: Province/State: Maple Ridge British Columbia

Licenced GVW (kg):

2015

Body Style:

Model:

4-Door Vehicle

Postal Code/ZIP:

V2X9G9

Vehicle Year:

GOLF

Country:

Canada

Make:

VOLKSWAGON

	Result	Comment
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3H - Hydraulic Brakes	Passed	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Not Applicable	

Tire Tread Denth (mm)

Axies (front)	Outer Left	Inner left	Inner Right	Outer Right	Steering Axle?
1	4.65			5.6	· · · · · · · · · · · · · · · · · · ·
2	6.4			4.9	

Comment:

Axies (front)	Lining/Pad	Left	Right
1	Pad	6.2	6
2	Pad	5.1	5.2

Rotor Thickness	OF	Drum	Inside	Diameter	Measurement	(mm)
	_	-				

Axles (front)	Rotor/Drum	Left	Right
1	Rotor	25.45	25.40
2	Rotor	10.46	10.42
Comment:			

Inspection Comments:

Has this Vehicle been road tested?

This Inspection Report was submitted to CVSE on 2022-Nov-21 06:23 PM

When?

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

Before Inspection

Name of the person who did the road test:

LAURENCE CLUBINE

Inspector Name:

Clubine, Laurence Dean JOH

Signature:

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0013

11/21/2022 6:25:08 PM