




# 2011 CHEVROLET EXPRESS G2500

Van cargo | 8 Cylinders | Gas  
1GCWGFFA3B1152408  
Country of Assembly: United States  
Last Reported Odometer: 119,524 KM




No Accident/Damage Records Found



Last Registered In:  
**Ontario (Normal)**



**16 Service Records Found**



U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



Import Record Found

**Questions? We're here to help.**

Visit us at [support.carfax.ca](https://support.carfax.ca)



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of December 01, 2022 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.



# Vehicle History Report



## Accident/Damage

There are no accidents/damage reported on this vehicle.



## Registration

This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

**We checked for:** Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

This vehicle has been registered in the state of **Minnesota** in the **United States**. No major title problems were reported.

**We checked for:** Salvage, Junk, Rebuilt, Fire, Flood, Hail and Lemon.



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2012 Jun 7		City Buick Chevrolet Cadillac GMC North York, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Oil and filter changed</li><li>Wiper(s) replaced</li></ul>
2012 Jun 12		Active Green & Ross - Vic Pk Toronto, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Emissions inspection performed</li></ul>
2012 Jun 14	19,407 KM	City Buick Chevrolet Cadillac GMC North York, Ontario, Canada	<b>Vehicle serviced</b>
2012 Dec 7	27,517 KM	Humberview Chevrolet Buick GMC Etobicoke, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Maintenance inspection completed</li><li>Brakes replaced</li><li>Brakes checked</li><li>Oil and filter changed</li><li>Tires rotated</li><li>Brake calipers cleaned/serviced</li><li>Tire(s) balanced</li></ul>
2013 Aug 8	35,200 KM	Humberview Chevrolet Buick GMC Etobicoke, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Maintenance inspection completed</li><li>Trim checked</li><li>Brakes checked</li><li>Oil and filter changed</li><li>Tires rotated</li></ul>
2013 Sep 27	38,407 KM	Humberview Chevrolet Buick GMC Etobicoke, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Trim checked</li></ul>
2014 Mar 21	44,899 KM	Humberview Chevrolet Buick GMC	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Maintenance inspection completed</li></ul>



		Etobicoke, Ontario, Canada	<ul style="list-style-type: none"> <li>• Brakes replaced</li> <li>• Four wheel alignment performed</li> <li>• Brakes checked</li> <li>• Oil and filter changed</li> <li>• Tires rotated</li> <li>• Brake calipers cleaned/serviced</li> </ul>
2014 Jul 26	49,719 KM	Humberview Chevrolet Buick GMC Etobicoke, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Oil and filter changed</li> </ul>
2015 Apr 9	60,373 KM	Humberview Chevrolet Etobicoke, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Maintenance inspection completed</li> <li>• Oil and filter changed</li> <li>• Wiper(s) replaced</li> </ul>
2015 Nov 12	69,139 KM	Humberview Chevrolet Etobicoke, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Maintenance inspection completed</li> <li>• Brakes checked</li> <li>• Oil and filter changed</li> <li>• Tires rotated</li> </ul>
2016 Apr 7	73,755 KM	Humberview Chevrolet Etobicoke, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Maintenance inspection completed</li> <li>• Brakes checked</li> <li>• Oil and filter changed</li> <li>• Tires rotated</li> </ul> <b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Maintenance inspection completed</li> <li>• Brakes checked</li> <li>• Oil and filter changed</li> <li>• Tires rotated</li> </ul>
2017 Sep 21	85,970 KM	Jiffy Lube Etobicoke, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Oil and filter changed</li> </ul>
2022 Sep 17	116,993 KM	Mission Automotive Mission, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Front wheel bearing(s)/hub(s) replaced</li> </ul>
2022 Sep 26	117,152 KM	Mission Automotive Mission, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Brake cable replaced</li> <li>• Rear brake pads replaced</li> <li>• Parking brake shoes/pads replaced</li> </ul>
2022 Nov 21	119,524 KM	Pro Oil Change 121 Mission, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Oil and filter changed</li> </ul>
2022 Nov 29		Gerry's Automotive Abbotsford, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Maintenance inspection completed</li> <li>• Safety inspection performed</li> </ul>



## Open Recalls

ⓘ No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact CHEVROLET or visit [GM's website](#).








# Stolen Vehicle Check

This vehicle is not actively declared stolen.



## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
 2011 May 24		Motor Vehicle Dept. Minnesota, United States	DMV Record Adjustment	Title or registration issued First Owner Reported
2012 Feb 24	19,300 KM	Independent Source Toronto, Ontario, Canada	Odometer reading	
 2012 Mar 31		Motor Vehicle Dept. Minnesota, United States	DMV Record Adjustment	Registration Issued or Renewed
2012 Jun 4		Motor Vehicle Dept. RV, Canada	Registration Records	Registered/Renewed
 2012 Jun 4		Motor Vehicle Dept. Canada	Import Record	<p><b>From:</b> United States <b>To:</b> Canada</p> <p>This vehicle has been imported into Canada from the US. For more information than is set out below, please contact RIV (<a href="http://www.riv.ca">www.riv.ca</a>).</p> <p>Imported Into Canada As: <b>Normal</b> Case/Dossier: <b>M399065</b> Import Date: <b>6/4/2012</b> Entered Customs: <b>6/4/2012</b> Inspection Date: <b>6/13/2012</b></p>
2012 Jun 7		City Buick Chevrolet Cadillac GMC North York, Ontario, Canada	Service Record	Vehicle serviced
2012 Jun 12		Active Green & Ross - Vic Pk Toronto, Ontario, Canada	Service Record	Vehicle serviced
2012 Jun 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2012 Jun 14	19,407 KM	City Buick Chevrolet Cadillac GMC North York, Ontario, Canada	Service Record	Vehicle serviced



2012 Dec 7	27,517 KM	Humberview Chevrolet Buick GMC Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2013 Aug 8	35,200 KM	Humberview Chevrolet Buick GMC Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2013 Sep 27	38,407 KM	Humberview Chevrolet Buick GMC Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2014 Mar 21	44,899 KM	Humberview Chevrolet Buick GMC Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2014 May 29		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2014 Jul 26	49,719 KM	Humberview Chevrolet Buick GMC Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2015 Apr 9	60,373 KM	Humberview Chevrolet Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2015 May 14		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2015 Nov 12	69,139 KM	Humberview Chevrolet Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2016 Apr 7	73,755 KM	Humberview Chevrolet Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2017 Feb 6		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2017 Sep 21	85,970 KM	Jiffy Lube Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2018 Jan 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial
2019 Feb 5		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Commercial
2022 Aug 12		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported



Previous Use: Personal

2022 Sep 17	116,993 KM	Mission Automotive Mission, British Columbia, Canada	Service Record	Vehicle serviced
2022 Sep 26	117,152 KM	Mission Automotive Mission, British Columbia, Canada	Service Record	Vehicle serviced
2022 Nov 21	119,524 KM	Pro Oil Change 121 Mission, British Columbia, Canada	Service Record	Vehicle serviced
2022 Nov 29		Gerry's Automotive Abbotsford, British Columbia, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)

**CARFAX Canada Low Kilometres™ Badge**

The CARFAX Canada Low Kilometres™ badge is based on the odometer information reported to CARFAX Canada. The CARFAX Canada Low Kilometres™ badge is available for vehicles registered in Canada that have accumulated, as reported to CARFAX Canada via odometer records, less than 18,000 kilometres per year from the beginning of September in the year prior to the vehicle's model year until the date that this report was generated.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

Conditions of Use

© Copyright 2005 - 2022 CARFAX Canada ULC. All rights reserved.



1GCWGF3B1152408



# 2011 CHEVROLET EXPRESS G2500

Van cargo | 8 Cylinders | Gas  
1GCWGFFA3B1152408  
Country of Assembly: United States

## Lien Express

No lien records found in **Ontario**.

### How We Check for Liens

CARFAX Canada uses the VIN to search government records in the Canadian province or territory selected.

We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty equipment.

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.

### CARFAX Canada Canadian Lien Guarantee



If for some reason our lien check fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian (\$5,000.00), whichever is lower.



## Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

Conditions of Use





# Private Vehicle Inspection Report

Decal Number: FW17540  
 Decal Expiry Date: 2024-Jan-31  
 Inspection Number: 20366804

Inspection Result: **PASS**

Facility: WALNUT GROVE AUTO TECH / S5605      Inspection Type: Complete      Inspection Start Date/Time: 2023-Jan-05 09:00 AM  
 Inspector: Huber, Corey Allen / 203454      Inspection Class: Class 1 - Light Vehicle with LGWW 5500 kg or less      Inspection Complete Date/Time: 2023-Jan-05 11:06 AM  
 Work Order Number:      Inspection Reason: New to BC

Vehicle Jurisdiction: Ontario      Brake Type: Hydraulic      Owner/Lessee Name: Auto Sales, Cypress  
 Registration Number:      Fuel Type: Gasoline      Address: 11919 maple meadows way  
 VIN: 1GCVGFFA3B1152408      Odometer: 120401 KM      City: Maple Ridge  
 Plate Number:      Hub Odometer:      Province/State: British Columbia  
 Licenced GVW (kg): 3311      Body Style: 2-Door Vehicle      Postal Code/ZIP: V2X 3M7  
 Vehicle Year: 2011      Model: Express 3500      Country: Canada  
 Make: Chevrolet

	Result	Comment
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3H - Hydraulic Brakes	Passed	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

**Tire Tread Depth (mm)**

Axles (front)	Outer Left	Inner left	Inner Right	Outer Right	Steering Axle?
1	13			13	✓
2	7			7	
Comment:					

**Brake Lining/Pad Measurement (mm)**

Axles (front)	Lining/Pad	Left	Right
1	Pad	8	8
2	Pad	12	12
Comment:			

**Rotor Thickness or Drum Inside Diameter Measurement (mm)**

Axles (front)	Rotor/Drum	Left	Right
1	Rotor	37.93	37.97
2	Rotor	28.72	28.70
Comment:			

**Inspection Comments:**

Has this Vehicle been road tested? Yes      When? Before and After Inspection      Name of the person who did the road test: Corey

Inspector Name: Huber, Corey Allen

Signature:

This Inspection Report was submitted to CVSE on 2023-Jan-05 11:08 AM

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/MIP at the Commercial Vehicle Safety Enforcement

CVSE0013

1/5/2023 11:08:49 AM



# CC Auto Repairs

Complete Auto Repairs. Domestic & Import.

Unit 170 - 20170 Stewart Crescent,  
Maple Ridge, BC V2X 0T4

604-460-6506

INVOICE IN00025255

DATE 6 Jan 2023

11:TIME GST# 856233481RP0001

CYPRESS AUTO SALES  
11919 MEADOWS WAY  
MAPLE RIDGE, BC  
V2X 9G9  
Home (604) 465 3313 Bus (604) 719 7615

Lic:  
VIN:  
Make:  
Model:  
ENGINE:

WO #: W000029369  
Year:  
Unit:  
Odometer: 000000

Labour Description	Price	Tax	Parts Description	Price	Tax
LABOUR TO REPLACE RIGHT REAR SHOCK.....	\$67.50	1	REAR SHOCK.....	\$124.95	
		1	SUBLET FOR MVI.....	\$205.80	

Thank You!

Remarks Designated Inspection Facility  
WE APPRECIATE YOUR BUSINESS, THANK YOU AND PLEASE COME AGAIN.

Total Labour: \$67.50  
Total Parts: \$330.75  
Sales Tax: \$6.75  
\$0.00 + GST: \$20.25  
**TOTAL: \$425.25**

**TOTALS: cash, cheque, Interac, VISA, M.C.**

I HEREBY AUTHORIZE THE REPAIR WORK HEREIN SET FORTH TO BE DONE ALONG WITH THE NECESSARY MATERIAL AND AGREE THAT TO THE EXTENT REMITTED BY LAW, YOU ARE NOT RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN CASE OF FIRE, THEFT, OR ANY OTHER CAUSE BEYOND YOUR CONTROL, OR FOR ANY DELAYS CAUSED BY NOT AVAILABILITY OF PARTS OR DELAYS IN PARTS SHIPMENTS BY THE SUPPLIER OR TRANSPORTER, I HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND OR INSPECTION UNTIL PAYMENT IN FULL OF THE WITHIN ACCOUNT, I HEREBY ACKNOWLEDGE THE EXISTENCE OF A REPAIR LIEN IN FAVOUR OF THE WITHIN DEALER ON THE VEHICLE DESCRIBED HEREIN RESPECT OF THE MATERIAL SUPPLIED AND SERVICES RENDERED UNDER THIS WORK ORDER FOR THE FULL AMOUNT CHARGED THEREFORE. I FURTHER ACKNOWLEDGE THAT THE SAID LIEN SHALL CONTINUE IN FORCE AT ALL TIMES, WHETHER THE VEHICLE IS IN MY POSSESSION OR POSSESSION OF THE DEALER, UNTIL THE WITHIN ACCOUNT IS PAID IN FULL WHILE THE VEHICLE IS IN MY POSSESSION IT SHALL AT ALL TIMES BE SUBJECT TO REPOSSESSION ON DEMAND BY THE DEALER UNTIL THE WITHIN ACCOUNT IS PAID IN FULL

INDEBTNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ \_\_\_\_\_ BEING ALL OR THE BALANCE OWING FOR REPAIRS, PARTS & ACCESSORIES DESCRIBED IN THIS WORK ORDER.

DATE \_\_\_\_\_ SIGNATURE \_\_\_\_\_

Your vehicle was serviced by:  by Visa

**WE APPRECIATE YOUR BUSINESS**





UNIT #8 - 20071 113B AVENUE  
 MAPLE RIDGE, BC V2X 0Z2  
 O: 604 460 7142  
 C: 604 721 1432  
 RIDGEMOTORSAUTOREPAIR@GMAIL.COM

*Cypress* MULTI-POINT INSPECTION

Name: Auto Broker Year/Make/Model: 2013 Chevy Express 2500 KMs: 3449

RO#: 3449 VIN: 1GEWGFAA3B152408 License: \_\_\_\_\_

CHECKED AND OK       FUTURE ATTENTION       IMMEDIATE ATTENTION

INTERIOR/EXTERIOR	
NOTE ANY EXISTING BODY DAMAGE	
Lights (Head, Brake, Turn, Parking)	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Windshield / Glass	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Wipers	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Horn / Interior Lights	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

TIRES			
TREAD DEPTH			
<input checked="" type="checkbox"/> 7/32" or greater	<input type="checkbox"/> 3/32" to 6/32"	<input type="checkbox"/> 2/32" or less	
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 12/32"	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 12/32"		
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 12/32"	RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 12/32"		
	Wear Pattern / Damage	Air Pressure	Based on Mileage and Wear:
	LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> (!)	<input type="checkbox"/> Alignment
	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	BEFORE SHOULD BE	<input type="checkbox"/> Balance
	LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	LF 35 35	<input type="checkbox"/> Rotation
RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	LR 35 35	RR <input type="checkbox"/> <input type="checkbox"/>	<input type="checkbox"/> New Tire

BATTERY	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

BRAKES	
BRAKE PADS / SHOES	
<input checked="" type="checkbox"/> Over 5 mm (Disk) or 2 mm (Drum)	
<input type="checkbox"/> 3-5 mm (Disk) or 1.01-2 mm (Drum)	
<input type="checkbox"/> Less than 3 mm (Disk) or 1 mm (Drum)	
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

UNDERHOOD	
Oil Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Transmission Fluid	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Power Steering / Brake Fluid	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Coolant / Antifreeze	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Air Filter	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Cabin Filter	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Belts	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

UNDER VEHICLE	
Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Suspension & Steering	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Driveline (Axles / CV Shaft)	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Rear Differential Fluid Level & Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Exhaust System / Shocks & Struts	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

COMMENTS	
FB	8mm
RB	10mm

INSPECTOR: Jim DATE: 1/07/2023



Ridge Motors Auto Repair and Tires  
 Unit 8 - 20071 113B Avenue  
 Maple Ridge, BC V2X 0Z2  
 (604) 460-7142

# Invoice

Date	Invoice #
1/2/2023	3449

GST/HST No. 758148118

<b>Invoice To</b>
Cypress Auto Brokers 11919 Maple Meadowa Way Maple Ridge BC V2X3M7

<b>Vehicle Description</b>
2017 Chevy Express 2500

ODO IN	ODO OUT	Plate	VIN
74813 miles			1gcwgffa3b1152408

Quantity	Item	Description	Price Each	Amount	Tax
	I_Inspection_Gen...		80.00	80.00	G
	P_Filter	air filter	22.00	22.00	G
		GST on sales	5.00%	5.10	
<b>Sales Tax Total</b>				\$5.10	
<b>Total</b>				\$107.10	

I hereby authorize you and your employees to carry out the repair work described above and to purchase on my account any parts and materials necessary to carry out the repair work subject to the estimate described above. I hereby authorize you and your employees to operate the vehicle listed above in connect with the repair work, including operation for the purposes of testing, inspection or delivery. I HERBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repair work authorized hereby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repair work.

By signing below I acknowledge and agree to the terms and conditions above

Customer Signature \_\_\_\_\_