

Vehicle History Report (BC) #: 44642091 Report Date: March 7, 2023 | 7:13 PM EST

Report Status: Complete

Reference:

## 2021 LEXUS RX 350 F-SPORT

Sport utility vehicle | 6 Cylinders | Gas 2T2SZMDAXMC267307 Country of Assembly: Canada Last Reported Odometer: 46,903 KM

CARFAX



Accident/Damage Records Found



Last Registered In: **British Columbia (Normal)** 



7 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of March 07, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# **Vehicle History Report (BC)**



## Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
② 2023 Jan 26	British Columbia, Canada	
	Estimate: REAR CENTER   Estimate Date: n/a	\$3,523.95
	Claim: COLLISION REAR CENTER	\$3,397.57



### Registration

This vehicle has been registered in the province of British Columbia in Canada with Normal branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



### Service Records

DATE	ODOMETER	SOURCE	DETAILS
2020 Nov 20		OpenRoad Lexus Richmond	Vehicle serviced
		Richmond, British Columbia, Canada	<ul><li>Pre-delivery inspection completed</li><li>Vehicle washed/detailed</li></ul>
2021 Mar 19	6,185 KM	OpenRoad Lexus Richmond	Vehicle serviced
		Richmond, British Columbia, Canada	<ul> <li>5,000 mile service performed</li> </ul>
			<ul> <li>8,000 kilometer service performed</li> </ul>
			Vehicle washed/detailed
			Tire(s) replaced
			Tire condition and pressure checked
2021 Sep 15	17,078 KM	OpenRoad Lexus Richmond	Vehicle serviced
		Richmond, British Columbia, Canada	Oil and filter changed
			Vehicle washed/detailed
			<ul> <li>Tires rotated</li> </ul>
			Brakes checked
2022 Mar 4	27,063 KM	OpenRoad Lexus Richmond	Vehicle serviced
		Richmond, British Columbia, Canada	Vehicle washed/detailed
			Tires rotated
			Oil and filter changed
······································			Brakes checked
2022 Jun 30	35,389 KM	OpenRoad Lexus Richmond	Vehicle serviced
		Richmond, British Columbia, Canada	Oil and filter changed
			Vehicle washed/detailed
			Tires rotated
			Brakes checked

2022 Sep 13	40,681 KM	OpenRoad Lexus Richmond Richmond, British Columbia, Canada	Vehicle serviced  Vehicle washed/detailed  Tire repaired
2023 Feb 1	46,903 KM	OpenRoad Lexus Richmond Richmond, British Columbia, Canada	Vehicle serviced  • Vehicle washed/detailed



### Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and  $non\text{-}safety\ related\ recall\ campaigns,\ please\ contact\ LEXUS\ or\ visit\ Lexus's\ website.$ 



### Stolen Vehicle Check

This vehicle is not actively declared stolen.



### **Detailed History**

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2020 Oct 3		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
				Previous Use: Lease
2020 Nov 20		OpenRoad Lexus Richmond Richmond, British Columbia, Canada	Service Record	Vehicle serviced
2021 Mar 19	6,185 KM	OpenRoad Lexus Richmond Richmond, British Columbia, Canada	Service Record	Vehicle serviced
2021 Sep 15	17,078 KM	OpenRoad Lexus Richmond Richmond, British Columbia, Canada	Service Record	Vehicle serviced
2021 Sep 19		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2022 Mar 4	27,063 KM	OpenRoad Lexus Richmond Richmond, British Columbia, Canada	Service Record	Vehicle serviced
2022 Jun 30	35,389 KM	OpenRoad Lexus Richmond Richmond, British Columbia,	Service Record	Vehicle serviced

		Canada		
2022 Sep 13	40,681 KM	OpenRoad Lexus Richmond Richmond, British Columbia, Canada	Service Record	Vehicle serviced
2022 Sep 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2023 Jan 26		Insurance Records British Columbia, Canada	COLLISION	REAR CENTER
2023 Jan 26		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a REAR CENTER
2023 Feb 1	46,903 KM	OpenRoad Lexus Richmond Richmond, British Columbia, Canada	Service Record	Vehicle serviced
2023 Feb 2		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Lease



### Questions? We're here to help.

Visit us at support.carfax.ca

#### ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage

vehicles sold by insurance companies as salvage
 salvage vehicles which have been rebuilt, inspected, and relicensed
 wrecked vehicles that have been decommissioned and can only be resold for parts
 The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or or missions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

© 2023 CARFAX Canada ULC. All rights reserved.



#### 178 Point Inspection SATISFACTORY N **NORMAL WEAR** Inspected from head lights to tailpipe ADJUSTMENT OR SERVICE R This vehicle has been inspected by a factory trained technician on the date shown in this report. **NEEDS REPAIR NOT APPLICABLE** Tire and brake wear are approximate percentages remaining. MODEL: RW350 VIN:M (267307 MAKE: Lewis 46983 STOCK NO: 2067 307 DATE TESTED: 2/1 YEAR: 204 KMS: \_ **ENGINE** Pinion seal/gasket 122. Power steering hoses Oil change 62. Transfer case seal 123. Power steering operation Filter change Transfer case gasket 63 124 Rack & pinion steering Alternator belt **COOLING SYSTEM** 125. Bellows/bushing/bracket 4. Power steering belt 64 126. Wheel bearing, front, RH/LH Air conditioning belt 65. Pressure test 127. Wheel bearing, rear, RH/LH Valve cover, RH/LH 66. Radiator 128 Rear springs/shackles Radiator cap Cylinder head, intake 67. 129. Rear ball joint/control arm 8. Manifold, exterior 68 Water pump Axle housing 9 Rear seal area 69. Upper hose **ELECTRICAL & SAFETY SYSTEMS** 10 Oil pan/plug Lower hose 131. Horn 11 Front seal area 71 Heater hose 132 **Head lights** 12 Oil pressure sender 72 By-pass hose 133. Tail lights 13 PCV filter/valve/hose 73 Fan/clutch/shroud Brake lights 14 **Engine mounts** 74. Freeze plug 135. Parking lights 15 Engine noise **Expansion tank** 136. Marker lights 16. Valve train noise 76. Inverter/hybrid/aux coolant 137. **Emergency flashers** 17 Oil burning (visual) BRAKES 138. Turn signals 18 Blow-by 77. Master cylinder 139. License plate light 19 Cylinder power balance 78 Power assist 140. Neutral switch 20 Ignition system 79 Lines/hoses, front/rear 141. Wiper/washer/blade/arm **FUEL SYSTEM** Disc/drum, front 142 Heater/defroster/rear defogger 21 **Evaporator** canister 81. Disc/drum, rear 143. Starter operation EGR valve 82. Linings remaining, front approx. Battery/level/hold down/terminals nn 144 23. Air injector pump 83. Linings remaining, rear approx. % 145. Charging voltage vw 24. Carburetor 84 Parking brake 146. Air conditioning 25. Fuel injection 85. Calipers/wheel cylinders, front 147. Radio/tape/CD operation 26 Accelerator pedal 86. Calipers/wheel cylinders, rear 148 Bluetooth operation 27. Linkage/controls 87. Anti-lock brakes 149 **Navigation operation** Air cleaner/filter 88 Fluid level/condition 150. Cruise control 29. Pre-heat/fresh air ducts **WHEELS & TIRES** 151. Visible warning lights 30. Fuel lines 89. LF tire tread remaining, approx. 152. Rear entertainment Fuel pump/tank 31 RF tire tread remaining, approx. % 153. Keyless entry/start system **EXHAUST SYSTEM** LR tire tread remaining, approx 91 154 Start/stop system 32. **Exhaust manifold** RR tire tread remaining, approx. 92 155. Remote start 33 Exhaust pipes 93 156. SOS 34 Muffler 94 Inflation equipment (runs flat tire) 157 Blind spot monitors 35 Resonator Wheel rims/covers 158. Cross traffic alert 36. Catalytic converter 96 Studs/nuts 159. Parking sensors 37 Tail pipes 97. Wheel locks 160. Pre-collision 38. Hangers/clamps **STEERING & SUSPENSION** 161. Reverse camera/proximity camera 39. Heat riser 98 Alignment (visual) BODY DRIVELINE Control arms/track rod 162 Exterior body 40 Transmission fluid level Bushings, front, upper/lower 163 Paint Clutch/linkage 41 101. Bushings, rear, RH/LH 164 Underbody (visual only) 42. Shift indicator 102 Ball joints lower, RH/LH 165 Frame (visual only) 43 Shift linkage 103 Ball joints upper, RH/LH 166 Trunk/tailgate Transmission fluid pan 104 King pin bushings 167 Convertible top 45. Transmission front seal area Steering box/sector shaft 168 Moonroof/sunroof 46. Rear extension housing 106 Steering column/shaft/coupling 169. Mirrors, RH/LH/inside 47. Rear extension seal 107 Steering lash 170 Bumpers, front/rear 48 Speedometer drive 108 Tie rod ends, front, outer/inner 171 Mudflaps/wheel coverings Transmission mount 109 Tie rod ends, rear, outer/inner 172 Windshield/windows, front/rear 50. Cooler lines 110 Drag/center link Window winders 173 51. CV joint/boots 111. Idler arm/Pitman arm 174 **Hood latch** 52. U-joints, front/middle/rear 112. Springs/shackles/torsion bar 175 53 Slip yoke/joint 113 Steering damper 176 Seat belts 54. Axle bearing 114 MacPherson struts, front, RH/LH 177. Trunk remote latch Axle seal 115. MacPherson struts, rear, RH/LH 178 Fuel door remote latch 56. Differential seal/gasket 116 Shock aborbers/bushings, front **MISCELLANEOUS** 57 Differential lock, center 117 Shock absorbers/bushings, rear 179 58. Differential lock, FR/RR 118. Strut rod/bushings, RH/LH 180 59 4WD 119. Stabilizer/bushings, front, RH/LH 181 60. 120. Stabilizer bushings, rear, RH/LH 121 Power steering pump level 183

This inspection is visual only, aided by instruments. AIRBAGS: This vehicle may or may not be presently equipped with airbags. If the vehicle is equipped, or is supposed to be equipped, with one or more airbags, the dealership makes no warranty whatsoever about the existence or proper operation or deployment of any airbag.

#### RECONDITIONING

ITEM NO	R.O. NO		Ang may be
ITEM NO	R.O. NO	e e e e e e e e e e e e e e e e e e e	
ITEM NO	R.O. NO		
ITEM NO	R.O. NO		
ITEM NO	R.O. NO		A. Sarah
ITEM NO	R.O. NO		

DI EACE DI	
INSPECTED BY (TECHNICIAN): GRANGE	MAK
DEALERSHIP:	
CARFAX REPORT (DATE):	
OUT-OF-PROVINCE CHECK (DATE):	
I.C.B.C. DAMAGE CHECK (DATE):	
LIENS CLEARED (DATE):	



