

# 2015 CHEVROLET EXPRESS G2500

Van cargo | 8 Cylinders | Flexible  
1GCWGGFF1F1204058  
Country of Assembly: United States  
Last Reported Odometer: 111,999 KM

**NO REPORTED ACCIDENTS**

LIEN CHECK



No Lien Records Found



Glass Records found



Last Registered In:  
**British Columbia (Normal)**



6 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of March 06, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

## Vehicle History Report + Lien Check (BC)



Lien Check

No lien records found in **British Columbia**.

### How We Check for Liens

CARFAX Canada uses the VIN to search government records in each Canadian province and territory (excluding Northwest Territories) where the vehicle is currently registered and where it has historically been registered. We do not check for liens or title in any U.S. state.

If a VIN has no registration records in Canada, we cannot check for liens. We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty equipment.

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.

### CARFAX Canada Canadian Lien Guarantee



If for some reason our lien check fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian (\$5,000.00), whichever is lower.



## Accident/Damage



There are no police reported accidents, estimates, or claims reported on this vehicle, however, we found other damage records that are outlined below.

## Other Damage Records

RECORD DATE	DETAILS	AMOUNT
2016 Aug 26	British Columbia, Canada	
	Glass Record	\$845.99



## Registration



This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

*We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2015 Apr 20		Wood Wheaton Chevrolet Cadillac Hummer Prince George, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Pre-delivery inspection completed</li></ul>
2015 Dec 31		Go North Surrey GM Surrey, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>Oil and filter changed</li><li>Vehicle washed/detailed</li></ul>
2016 Feb 23		Go North Surrey GM Surrey, British Columbia, Canada	<b>Vehicle serviced</b>

	ODOMETER	SOURCE	DETAILS
2017 Oct 6	79,799 KM	Great Canadian Oil Change Coquitlam, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> </ul>
2019 May 16	99,998 KM	Great Canadian Oil Change Coquitlam, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> <li>Air filter checked</li> </ul>
2020 Feb 3	111,999 KM	Great Canadian Oil Change Coquitlam, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Maintenance inspection completed</li> <li>Oil and filter changed</li> </ul>

## Open Recalls

Recall #: N172086770 | Driver Side Window Switch Inoperative    Recall Date: 2018 May 03

### Recall Description


General Motors has decided that a defect which relates to motor vehicle safety exists in 2014 – 2017 Chevrolet Express and GMC Savana vehicles (built through 6/21/16 and 6/17/16 respectively) equipped with power windows. Under certain conditions, liquid can enter the power window switches in these vehicles and cause corrosion, leading to high electrical resistance. High electrical resistance can cause the switch to heat up, smoke or melt, increasing the risk of fire and injury. Occupants may notice that the power window is malfunctioning or inoperative. Smoke or an odor from smoke or melting may also come from the door panel.

### Remedy

Replace driver side door window switch.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact CHEVROLET or visit [GM's website](#).

## Stolen Vehicle Check

 This vehicle is not actively declared stolen.

## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 Apr 20		Wood Wheaton Chevrolet Cadillac Hummer Prince George, British Columbia, Canada	Service Record	Vehicle serviced
2015 May 2		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2015 Dec 5		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 Dec 31		Go North Surrey GM Surrey, British Columbia, Canada	Service Record	Vehicle serviced
2016 Feb 23		Go North Surrey GM Surrey, British Columbia, Canada	Service Record	Vehicle serviced
2016 Mar 5		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2016 Aug 26		Insurance Records British Columbia, Canada	Glass Record	\$845.99
2017 Feb 26		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Oct 6	79,799 KM	Great Canadian Oil Change Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced
2018 Feb 17		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 May 3		CHEVROLET	Recall	Manufacturer Recall Issued Recall # N172086770
2019 Mar 3		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 May 16	99,998 KM	Great Canadian Oil Change Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced
2020 Feb 3	111,999 KM	Great Canadian Oil Change Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced
2020 Feb 26		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2023 Feb 21		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported



Questions? We're here to help.

Visit us at [support.carfax.ca](http://support.carfax.ca)

#### ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registrations/veh/Limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

**CARFAX Canada No Reported Accidents™ Badge**

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)

© 2023 CARFAX Canada ULC. All rights reserved.





**CC Auto Repair**  
 #170 - 20170 Stewart Crescent  
 Maple Ridge, BC V2X0T4  
**604-460-6506**

**Invoice**

Bill To Cypress Auto Sales  
 Sales, Cypress Auto  
 11919 Maple Meadows Way  
 Maple Ridge, B.C. V2X 3M7  
 Canada

Plate BC 2015EXPRESS  
 Description 2015 Chevrolet Express 2500 Base V8 4.8L  
 294CID VIN F  
 VIN 1GCWGGFF1F1204058  
 Odometer 114,588

Home (604) 719-7615 Arin  
 Email

Invoice # 90  
 Work Order # 149  
 Service Advisor Corey Huber  
 Technician Corey Huber

Invoice Date 4/26/2023 12:55 PM  
 Appointment 4/25/2023 8:00 AM  
 Promised 4/25/2023 5:00 PM

**Inspection**

**Safety Inspection**

Full Vehicle Safety Inspection, Inspect Front End And Grease Components, Fluid Levels And Condition, Brake Measurements, Tire Condition And Tread Life. Perform Road Test And Torque Wheels.

Labor	0.6 Hour		\$84.00 *GP
		<b>Discount</b>	<b>(\$12.60)</b>
		<b>Sub</b>	<b>\$71.40</b>

**Service**

**Install Front Bumper**

Remove and Replace components as required to access and install materials, and/or perform needed service. Retest and verify repair as required. Perform final road test where applicable.

Labor	1 Hour		\$140.00 *GP
		<b>Discount</b>	<b>(\$21.00)</b>
		<b>Sub</b>	<b>\$119.00</b>

Total Parts	\$0.00
Total Labor	\$190.40
Total Before Taxes & Miscellaneous Charges	<u>\$190.40</u>

(*) Shop Supplies, Enviro Fees, Cleaners, Grease, Lubricant, Small Parts, Fasteners and any other items too small to Invoice	5 %	\$9.52 PG
(G) Canadian Goods and Services Tax (GST)	5 %	\$10.00
(P) BC Provincial Sales Tax (PST)*		\$0.00

Exemption #: 1014-2701

<b>Grand Total</b>	<b>\$209.92</b>
--------------------	-----------------

Total discounts applied is \$33.60

Cypress Auto Sales paid \$209.92 by Visa Card

Thanks for the Business!  
 I acknowledge receipt of the vehicle and the indebtedness indicated herein.

Customer Signature: \_\_\_\_\_

**Safety Inspection**

Full Vehicle Safety Inspection, Inspect Front End And Grease Components, Fluid Levels And Condition, Brake Measurements, Tire Condition And Tread Life. Perform Road Test And Torque Wheels.

Safety Inspection	O	S	M	R
Wiper Blade				
Windshield Washer				
Exterior Light				
Interior Light				
Rearview / Side View Mirror				
Horn(s)				
Fluid Leaks				
BRAKE FLUID				
POWER STEERING FLUID				
TRANSMISSION FLUID				
ANTI-FREEZE / COOLANT				
DIFFERENTIAL FLUID				
AIR FILTER / BREATHER FILTER				
DRIVE / SERPENTINE BELT				
Battery / Cables / Connections				
SHOCKS / STRUTS				
Exhaust				
Steering Linkage				
CV Joints / Boots / Axles				
Tires				LF_3_/32 RF_3_/32 6_/32 RR_6_/32 LR_
Brake Friction Front				LF/_6_MM RF/_6_MM
Brake Friction Rear				LR/_6_MM RR/_6_MM
Additional Notes & Observations:				

# Multi-Point Inspection Checklist Per Manufacturer's Recommendation

Customer Name: \_\_\_\_\_ Year/Model: 2015 Chevrolet Express Date: APR 01 2023  
 RO/Tag: F1204058 Mileage: 114400

**OKAY AT THIS TIME**      **MAY REQUIRE FUTURE ATTENTION**      **REQUIRES PROMPT ATTENTION**

Check Fluid Levels and Fill					
OK	FILL	OK	FILL	OK	FILL
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Engine Oil		Brake Reservoir		Power Steering	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Transmission		Window Washer		Coolant Recovery Reservoir	

Recommended Scheduled Maintenance Services	
<input type="checkbox"/> Oil Change	<input type="checkbox"/> Fuel Filter
<input type="checkbox"/> Oil Filter	<input type="checkbox"/> Cabin Air Filter
<input type="checkbox"/> Engine Air Filter	<input type="checkbox"/> Spark Plugs
<input type="checkbox"/> Engine Coolant	<input type="checkbox"/> Tire Rotation
<input type="checkbox"/> Transmission Fluid	<input type="checkbox"/> Seat Filter
<input type="checkbox"/> Transmission Filter	<input type="checkbox"/> Accessory Drive Belt(s)

Comments: \_\_\_\_\_

**Check Battery**

State of Health

Good       Bad  
 Battery Terminals (Clean if necessary)  
 Declined Battery

**Check Brakes**  
Measure Front / Rear Brakes Linings

LF        
 LR        
 RF        
 RR        
 Declined Brake

**Over 5 mm or 7/32" (Disc) or Over 2 mm or 3/32" (Drum)**  
**3 to 5 mm or 4/32" to 7/32" (Disc) or 1.01 to 2mm (Drum) or 2/32" to 3/32"**  
**Less than 3 mm or 4/32" (Disc) or 1 mm or 2/32" or Less (Drum)**

Brake Measurements Not Taken This Service Visit

Comments: Poor Winch missing (side door)

Service Advisor: \_\_\_\_\_  
 Technician: [Signature]

Check Following Systems / Components			Declined
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Operation of horn, interior lights, exterior lamps, turn signals, hazard and brake lamps	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Radiator, heater, and air-conditioning hoses for leaks and damage	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Windshield for cracks, chips and pitting	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Windshield washer spray, wiper operation and wiper blades	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Accessory drive belt(s)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Brake system (including lines, hoses, and parking Brake) and wheel end for end-play and bearing noise	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Clutch operation (if equipped)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Constant velocity (CV) drive axle boots (if equipped)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Drive shaft, transmission, u-joint and shift linkage (if equipped) and lubricate (as needed)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Engine Cooling system, hoses and clamps	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Exhaust system (leaks, damage, loose parts)	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Oil and / or fluid leaks	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Shocks/struts and other suspension components for leaks and/or damage	<input type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Steering and steering linkages	<input type="checkbox"/>

State Inspection Due (IF APPLICABLE) \_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_  
MO DAY YEAR

Comments: \_\_\_\_\_

**Check Tires**

TREAD DEPTH

LF  7/32" or Greater       4/32" to 6/32"       3/32" or less  
 RF  7/32" or Greater       4/32" to 6/32"       3/32" or less  
 LR  7/32" or Greater       4/32" to 6/32"       3/32" or less  
 RR  7/32" or Greater       4/32" to 6/32"       3/32" or less  
 Declined Tire

WEAR PATTERN / DAMAGE

LF      
 LR      
 RF      
 RR

Tire Wear Indicates:  Alignment Check Needed       Wheel Balance Needed

Comments: \_\_\_\_\_

Tire Pressure Set to Factory Recommended PSI

FRONT       REAR

Customer Signature: \_\_\_\_\_