

# 2017 MERCEDES-BENZ SPRINTER 2500


Van cargo | 6 Cylinders | Diesel  
WD3BE7CD2HP508808  
Country of Assembly: Germany  
Last Reported Odometer: 84,030 KM

ONE  
OWNER\*


LIEN CHECK



Lien Record(s) Found



Accident/Damage Records Found



Last Registered In:  
**British Columbia (Normal)**



9 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)



**This vehicle history report is based on information that was reported and available to CARFAX Canada as of April 04, 2022** (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# Vehicle History Report + Lien Check (BC)

## Lien Check

**!** Lien Record(s) found in **British Columbia**.

### How We Check for Liens

CARFAX Canada uses the VIN to search government records in each Canadian province and territory (excluding Northwest Territories) where the vehicle is currently registered and where it has historically been registered. We do not check for liens or title in any U.S. state.

If a VIN has no registration records in Canada, we cannot check for liens. We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty equipment.

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.

### CARFAX Canada Canadian Lien Guarantee



If for some reason our lien check fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian (\$5,000.00), whichever is lower.

## Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
<b>!</b> 2018 Nov 15	<b>British Columbia, Canada</b>	
	<b>Estimate:</b> RIGHT SIDE   Estimate Date: n/a	\$16,436.79
	<b>Claim:</b> COLLISION RIGHT SIDE	\$15,703.01
<b>!</b> 2020 Aug 15	<b>British Columbia, Canada</b>	
	<b>Estimate:</b> COLLISION   Estimate Date: n/a	\$0.00
	<b>Claim:</b> COLLISION	\$0.00

## Registration

**!** This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

**We checked for:** Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2017 Nov 24		Mercedes-Benz Boundary	Vehicle serviced

2018 Oct 31	23,722 KM	Mercedes-Benz Boundary Vancouver, British Columbia, Canada	<b>Vehicle serviced</b> • Oil and filter changed
2019 Apr 17	24,929 KM	Kal Tire 080 North Vancouver, British Columbia, Canada	<b>Vehicle serviced</b> • Four wheel alignment performed
2019 Apr 18		Service Facility	<b>Vehicle serviced</b>
2021 May 11	71,416 KM	Coastal Ford Sales Ltd Burnaby, British Columbia, Canada	<b>Vehicle serviced</b> • Maintenance inspection completed • 8,000 kilometer service performed • Brakes checked • Oil and filter changed • Tires rotated • Brakes serviced • Maintenance reminder reset • Tire condition and pressure checked
2021 Oct 7	80,945 KM	Coastal Ford Sales Ltd Burnaby, British Columbia, Canada	<b>Vehicle serviced</b> • Maintenance inspection completed • 8,000 kilometer service performed • Brakes checked • Oil and filter changed • Tires rotated • Electrical system checked • Air filter replaced • Cabin air filter replaced/cleaned • Front wiper blades/refills replaced • Starter replaced • Maintenance reminder reset • Tire condition and pressure checked
2021 Nov 20	84,030 KM	Coastal Ford Sales Ltd Burnaby, British Columbia, Canada	<b>Vehicle serviced</b> • Four tires replaced



## Open Recalls

- No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact MERCEDES-BENZ or visit [Mercedes Benz's website](#).



## Stolen Vehicle Check

- This vehicle is not actively declared stolen.



## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2017 Nov 24		Mercedes-Benz Boundary Vancouver, British Columbia, Canada	Service Record	Vehicle serviced

2018 Aug 24	18,770 KM	Kal Tire - Surrey Surrey, British Columbia, Canada	Service Record	Vehicle serviced
2018 Oct 31	23,722 KM	Mercedes-Benz Boundary Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2018 Nov 15		Insurance Records British Columbia, Canada	COLLISION	RIGHT SIDE
2018 Nov 15		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a RIGHT SIDE
2019 Apr 17	24,929 KM	Kal Tire 080 North Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2019 Apr 18		Service Facility	Service Record	Vehicle serviced
2019 Jun 3		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2020 Jun 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2020 Aug 15		Insurance Records British Columbia, Canada	COLLISION	
2020 Aug 15		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a COLLISION
2021 May 11	71,416 KM	Coastal Ford Sales Ltd Burnaby, British Columbia, Canada	Service Record	Vehicle serviced
2021 May 30		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2021 Oct 7	80,945 KM	Coastal Ford Sales Ltd Burnaby, British Columbia, Canada	Service Record	Vehicle serviced
2021 Nov 20	84,030 KM	Coastal Ford Sales Ltd Burnaby, British Columbia, Canada	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)

**ICBC Disclaimer**

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. Conditions of Use

© Copyright 2005 - 2022 CARFAX Canada ULC. All rights reserved.





UNIT #8 - 20071 113B AVENUE  
 MAPLE RIDGE, BC V2X 0Z2  
 O: 604 460 7142  
 C: 604 721 1432  
 RIDGEMOTORSAUTOREPAIR@GMAIL.COM

**MULTI-POINT INSPECTION**

Name: Cypress Autobedcar Year/Make/Model: 2014 Mercedes Sprint KMs: 87264

RO#: 3032 VIN: WD3BETCD2HP508808 License: \_\_\_\_\_

■ CHECKED AND OK      ■ FUTURE ATTENTION      ■ IMMEDIATE ATTENTION

INTERIOR/EXTERIOR	
NOTE ANY EXISTING BODY DAMAGE	
Lights (Head, Brake, Turn, Parking)	<span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>
Windshield / Glass	<span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>
Wipers	<span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>
Horn / Interior Lights	<span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>

TIRES			
TREAD DEPTH			
<span style="color: green;">■</span> 7/32" or greater	<span style="color: yellow;">■</span> 3/32" to 6/32"	<span style="color: red;">■</span> 2/32" or less	
LF <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> 12/32"	RF <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> 12/32"		
LR <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> 14/32"	RR <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span> 14/32"		
	Wear Pattern/Damage	Air Pressure	Based on Mileage and Wear:
	LF <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>	<span style="color: red;">■</span>	<input type="checkbox"/> Alignment
	RF <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>	BEFORE SHOULD BE	<input type="checkbox"/> Balance
	LR <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>	LF <input type="text" value="49"/>	<input type="checkbox"/> Rotation
	RR <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>	RF <input type="text" value="70"/>	<input type="checkbox"/> New Tire

BATTERY	
<span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>	

BRAKES	
BRAKE PADS / SHOES	
<span style="color: green;">■</span> Over 5 mm (Disk) or 2 mm (Drum)	
<span style="color: yellow;">■</span> 3-5 mm (Disk) or 1.01-2 mm (Drum)	
<span style="color: red;">■</span> Less than 3 mm (Disk) or 1 mm (Drum)	
LF <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>	
RF <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>	
LR <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>	
RR <span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>	

UNDERHOOD	
Oil Condition	<span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>
Transmission Fluid	<span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>
Power Steering / Brake Fluid	<span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>
Coolant / Antifreeze	<span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>
Air Filter	<span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>
Cabin Filter	<span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>
Belts	<span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>

UNDER VEHICLE	
Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	<span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>
Suspension & Steering	<span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>
Driveline (Axles / CV Shaft)	<span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>
Rear Differential Fluid Level & Condition	<span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>
Exhaust System / Shocks & Struts	<span style="color: green;">■</span> <span style="color: yellow;">■</span> <span style="color: red;">■</span>

COMMENTS
F PAOS 12
R PAOS 12

INSPECTOR: Jim      DATE: 6/25/2022

# Invoice

Ridge Motors Auto Repair and Tires  
 Unit 8 - 20071 113B Avenue  
 Maple Ridge, BC V2X 0Z2  
 (604) 460-7142

Date	Invoice #
6/25/2022	3032

GST/HST No. 758148118

Invoice To
Cypress Auto Brokers 11919 Maple Meadowa Way Maple Ridge BC V2X3M7

Vehicle Description
2018 Mercedes Sprinter van

ODO IN	ODO OUT	Plate	VIN
87264			wd3be7cd2hp508808

Quantity	Item	Description	Price Each	Amount	Tax
	I_Inspection_Gen...	GST on sales	80.00 5.00%	80.00 4.00	G
<b>Sales Tax Total</b>				\$4.00	
<b>Total</b>				\$84.00	

I hereby authorize you and your employees to carry out the repair work described above and to purchase on my account any parts and materials necessary to carry out the repair work subject to the estimate described above. I hereby authorize you and your employees to operate the vehicle listed above in connect with the repair work, including operation for the purposes of testing, inspection or delivery. I HERBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repair work authorized hereby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repair work.

By signing below I acknowledge and agree to the terms and conditions above

Customer Signature \_\_\_\_\_



**CC Auto Repair**  
 #170 - 20170 Stewart Crescent  
 Maple Ridge, BC V2X0T4  
**604-460-6506**

**Invoice**

Bill To Cypress Auto Sales  
 Sales, Cypress Auto  
 11919 Maple Meadows Way  
 Maple Ridge, B.C. V2X 3M7  
 Canada

Plate BC NA  
 Description 2017 Mercedes-Benz Sprinter 2500 Base V6  
 3.0L 2987CC  
 VIN WD3BE7CD2HP508808  
 Odometer 87,887

Home (604) 719-7615 Arin  
 Email

Invoice # 168  
 Work Order # 219  
 Service Advisor Matt Preston  
 Technician Tomas Sadler Rucht

Invoice Date 5/26/2023 4:24 PM  
 Appointment 5/10/2023 1:35 PM  
 Promised 5/10/2023 5:00 PM

**Service**

**EGR Cleaning**

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Retest and verify repair as required. Perform final road test where applicable.

Labor	1 Hour		\$140.00 *GP
		<b>Discount</b>	<b>(\$140.00)</b>
		<b>Sub</b>	<b>\$0.00</b>

**Upstream NOx Sensor**

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Retest and verify repair as required. Perform final road test where applicable.

Upstream NOx Sensor	1 Unit	\$923.64 / Unit	\$923.64 GP
NOx Programing	1 Unit	\$420.00 / Unit	\$420.00 GP
Labor	1 Hour		\$140.00 *GP
		<b>Discount</b>	<b>(\$274.36)</b>
		<b>Sub</b>	<b>\$1,209.28</b>

Total Parts	\$1,209.28
Total Labor	\$0.00
Total Before Taxes & Miscellaneous Charges	\$1,209.28

(G) Canadian Goods and Services Tax (GST)	5 %	\$60.47
(P) BC Provincial Sales Tax (PST)*		\$0.00

**Grand Total** \$1,269.75

Total discounts applied is \$414.36

Cypress Auto Sales paid \$1,269.75 by Visa Card

Thanks for the Business!  
 I acknowledge receipt of the vehicle and the indebtedness indicated herein.

**Customer Signature:** \_\_\_\_\_