



Vehicle History Report (BC) #: 48318509
Report Date: September 7, 2023 | 1:43 PM EDT
Report Status: Complete


2011 VOLKSWAGEN CC SPORT

Sedan | 4 Cylinders | Gas
WVWMN9AN0BE736959
Country of Assembly: Germany
Last Reported Odometer: 125,284 KM

NO REPORTED
ACCIDENTS



No Accident/Damage Records
Found



Last Registered In:
British Columbia (Normal)



12 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on [information](https://www.carfax.ca/vehicle-history-data) (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of September 07, 2023 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report (BC)



Accident/Damage

✓ There are no accidents/damage reported on this vehicle.



Registration

✓ This vehicle has been registered in the following locations in **Canada** (listed oldest to newest):

- In the province of **Alberta** with **Normal** branding.
- In the province of **British Columbia** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2014 Apr 17	48,799 KM	Service Facility Calgary, Alberta, Canada	Vehicle serviced
2014 Oct 2	53,445 KM	Service Facility Calgary, Alberta, Canada	Vehicle serviced
2015 Mar 2	59,324 KM	Service Facility Calgary, Alberta, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Fluids checked • Oil and filter changed • Tire condition and pressure checked
2015 Aug 7		Tramtec Holdings Ltd. Langley, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed
2015 Sep 11	65,774 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed
2016 Feb 3	70,813 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed • Tire condition and pressure checked • Body lubricated
2016 Jun 2	76,391 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Spark plug(s) replaced • Drivability/performance checked • Oil and filter changed • Tires rotated • Brake fluid flushed/changed • Ignition coil(s) replaced • Emissions or safety inspection performed
2016 Sep 26	82,619 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Vehicle serviced
2016 Nov 7	84,013 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> • Maintenance inspection completed • Oil and filter changed • Tire condition and pressure checked • Body lubricated

WWW.N9AN0BE736959

	ODOMETER	SOURCE	DETAILS
2022 Aug 23	121,079 KM	Volkswagen of Richmond Richmond, British Columbia, Canada	Vehicle serviced • Airbag replaced
2023 Mar 20	125,247 KM	NAPA AUTOPRO Highway 33 Napa Autopro Kelowna, British Columbia, Canada	Vehicle serviced
2023 May 12	125,284 KM	Turner Volkswagen Kelowna, British Columbia, Canada	Vehicle serviced



Open Recalls

✓ No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact VOLKSWAGEN or visit [Volkswagen's website](#).



Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2011 Jun 27		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Lease
2012 Mar 22		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2012 Jul 30		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2013 Jul 19		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2014 Apr 17	48,799 KM	Service Facility Calgary, Alberta, Canada	Service Record	Vehicle serviced
2014 Jul 31		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2014 Oct 2	53,445 KM	Service Facility Calgary, Alberta, Canada	Service Record	Vehicle serviced
2015 Mar 2	59,324 KM	Service Facility Calgary, Alberta, Canada	Service Record	Vehicle serviced
2015 Aug 6	65,008 KM	Auto Auction	Auction Announcement	Vehicle sold

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2015 Aug 7		Tramtec Holdings Ltd. Langley, British Columbia, Canada	Service Record	Vehicle serviced
2015 Aug 15		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2015 Sep 11	65,774 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Service Record	Vehicle serviced
2015 Sep 12		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2016 Feb 3	70,813 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Service Record	Vehicle serviced
2016 Feb 27		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Jun 2	76,391 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Service Record	Vehicle serviced
2016 Sep 26	82,619 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Service Record	Vehicle serviced
2016 Nov 7	84,013 KM	Abbotsford Volkswagen Abbotsford, British Columbia, Canada	Service Record	Vehicle serviced
2017 Oct 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 Mar 3		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Mar 10		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2019 Aug 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Mar 5		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 Oct 20		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2022 Aug 23	121,079 KM	Volkswagen of Richmond Richmond, British Columbia, Canada	Service Record	Vehicle serviced
2022 Oct 16		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed

WWW.N9AN0BE736959

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2023 Mar 4		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2023 Mar 13		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2023 Mar 20	125,247 KM	NAPA AUTOPRO Highway 33 Napa Autopro Kelowna, British Columbia, Canada	Service Record	Vehicle serviced
2023 May 4		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2023 May 12	125,284 KM	Turner Volkswagen Kelowna, British Columbia, Canada	Service Record	Vehicle serviced
2023 May 24		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/Limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

CARFAX Canada No Reported Accidents™ Badge

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)

© 2023 CARFAX Canada ULC. All rights reserved.





UNIT #8 - 20071 113B AVENUE
 MAPLE RIDGE, BC V2X 0Z2
 O: 604 460 7142
 C: 604 721 1432
 RIDGEMOTORSAUTOREPAIR@GMAIL.COM

Cyprus MULTI-POINT INSPECTION

Name: Auto Broker Year/Make/Model: 2011 VW CC KMs: 125313

RO#: 4016 VIN: WWMN9AN0BE736959 License: _____

☒ CHECKED AND OK ☐ FUTURE ATTENTION ☐ IMMEDIATE ATTENTION

INTERIOR/EXTERIOR	
NOTE ANY EXISTING BODY DAMAGE	
Lights (Head, Brake, Turn, Parking)	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Windshield / Glass	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Wipers	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Horn / Interior Lights	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

BATTERY	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

UNDERHOOD	
Oil Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Transmission Fluid	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Power Steering / Brake Fluid	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Coolant / Antifreeze	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Air Filter	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Cabin Filter	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Belts	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

UNDER VEHICLE	
Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Suspension & Steering	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Driveline (Axles / CV Shaft)	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Rear Differential Fluid Level & Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Exhaust System / Shocks & Struts	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

TIRES																		
TREAD DEPTH																		
<input checked="" type="checkbox"/> 7/32" or greater	<input type="checkbox"/> 3/32" to 6/32" <input type="checkbox"/> 2/32" or less																	
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 8/32"	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 8/32"																	
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 9/32"	RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 9/32"																	
	<table border="1"> <thead> <tr> <th colspan="2">Wear Pattern/ Damage</th> <th colspan="2">Air Pressure</th> <th rowspan="4">Based on Mileage and Wear:</th> </tr> <tr> <th>LF</th> <th>RF</th> <th>BEFORE</th> <th>SHOULD BE</th> </tr> </thead> <tbody> <tr> <td><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/></td> <td><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/></td> <td>32</td> <td>32</td> </tr> <tr> <td><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/></td> <td><input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/></td> <td>32</td> <td>32</td> </tr> </tbody> </table>	Wear Pattern/ Damage		Air Pressure		Based on Mileage and Wear:	LF	RF	BEFORE	SHOULD BE	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	32	32	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	32	32
Wear Pattern/ Damage		Air Pressure		Based on Mileage and Wear:														
LF	RF	BEFORE	SHOULD BE															
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	32	32															
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	32	32															

BRAKES	
BRAKE PADS / SHOES	
<input checked="" type="checkbox"/> Over 5 mm (Disk) or 2 mm (Drum)	
<input type="checkbox"/> 3-5 mm (Disk) or 1.01-2 mm (Drum)	
<input type="checkbox"/> Less than 3 mm (Disk) or 1 mm (Drum)	
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	
RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

COMMENTS	
Front Pads 9mm	
Rear Pads 5mm	

INSPECTOR: JLM DATE: 9/27/2023

Ridge Motors Auto Repair and Tires
Unit 8 - 20071 113B Avenue
Maple Ridge, BC V2X 0Z2
(604) 460-7142

Invoice

Date	Invoice #
9/27/2023	4016

GST/HST No. 758148118

Invoice To
Cypress Auto Brokers

Vehicle Description
2011 vw cc

ODO IN	ODO OUT	Plate	VIN
125313			wwwmn9an0be736959

Quantity	Item	Description	Price Each	Amount	Tax
	I_Inspection_Gen...	GST on sales	80.00 5.00%	80.00 4.00	G
Sales Tax Total				\$4.00	
Total				\$84.00	

I herby authorize you and your employees to carry out the repair work described above and to purchase on my account any parts and materials necessary to carry out the repair work subject to the estimate described above. I herby authorize you and your employees to operate the vehicle listed above in connect with the repair work, including operation for the purposes of testing, inspection or delivery. I HERBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repair work authorized herby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repair work.

By signing below I acknowledge and agree to the terms and conditions above

Customer Signature _____