



**Vehicle History Report (BC) #:** 51272368  
**Report Date:** February 9, 2024 | 2:56 PM EST  
**Report Status:** Complete  
**Reference:**


## 2022 NISSAN LEAF SL PLUS

Hatchback | Unknown Cylinders | Electric  
1N4BZ1DV1NC552340  
Country of Assembly: United States  
Last Reported Odometer: 18,752 KM

**NO REPORTED ACCIDENTS\***




No Accident/Damage Records Found



Last Registered In:  
**British Columbia (Normal)**



1 Service Record Found



U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



Import Record Found

Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)



**This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of February 09, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.**

# Vehicle History Report (BC)



## Accident/Damage

There are no accidents/damage reported on this vehicle.



## Registration

This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

*We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*

This vehicle has been registered in the state of **Idaho** in the **United States**. No major title problems were reported.

*We checked for: Salvage, Junk, Rebuilt, Fire, Flood, Hail and Lemon.*



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2024 Jan 9		West Coast Nissan Pitt Meadows, British Columbia, Canada	Vehicle serviced



## Open Recalls

Recall #: R23D7 | LEAF RRVW CMEA NO REPAIR AVL Recall Date: 2024 Feb 06

### Recall Description

Over time, the rear view camera harness within the affected vehicles could become damaged from harness movement and vibration during vehicle or manual hatch operation


### Remedy

Nissan is currently developing a remedy plan.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit Nissan's website.







## Stolen Vehicle Check

 This vehicle is not actively declared stolen.



## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
 2021 Nov 8		Motor Vehicle Dept. California, United States	Previous use	Personal lease
 2021 Dec 6		Motor Vehicle Dept. Idaho, United States	DMV Record Adjustment	Registration Issued or Renewed Loan or lien reported Vehicle colour noted as gray
 2022 Apr 12		Motor Vehicle Dept. Idaho, United States	DMV Record Adjustment	Title issued or updated First Owner Reported Vehicle colour noted as gray
2023 Dec 13	18,752 KM	Auto Auction	Auction Announcement	Vehicle sold
2023 Dec 28		Motor Vehicle Dept. RV, Canada	Registration Records	Registered/Renewed
 2023 Dec 28		Motor Vehicle Dept. Canada	Import Record	<b>From:</b> United States <b>To:</b> Canada  This vehicle has been imported into Canada from the US. For more information than is set out below, please contact RIV ( <a href="http://www.riv.ca">www.riv.ca</a> ).  Imported Into Canada As: <b>Normal</b> Case/Dossier: <b>C099630</b> Import Date: <b>12/28/2023</b> Entered Customs: <b>12/28/2023</b> Inspection Date: <b>1/22/2024</b>
2024 Jan 9		West Coast Nissan Pitt Meadows, British Columbia, Canada	Service Record	Vehicle serviced
2024 Jan 22		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Vehicle colour noted as gray

# Vehicle History Report (BC)



## Accident/Damage

There are no accidents/damage reported on this vehicle.



## Registration

This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

*We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*

This vehicle has been registered in the state of **Idaho** in the **United States**. No major title problems were reported.

*We checked for: Salvage, Junk, Rebuilt, Fire, Flood, Hail and Lemon.*



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2024 Jan 9		West Coast Nissan Pitt Meadows, British Columbia, Canada	<b>Vehicle serviced</b>



## Open Recalls

Recall #: R23D7 | LEAF RRWV CMEA NO REPAIR AVL Recall Date: 2024 Feb 06

### Recall Description

Over time, the rear view camera harness within the affected vehicles could become damaged from harness movement and vibration during vehicle or manual hatch operation

### Remedy

Nissan is currently developing a remedy plan.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit [Nissan's website](#).



## Stolen Vehicle Check



# Private Vehicle Inspection Report

Decal Number: GB46184  
Decal Expiry Date: 2025-Jan-31  
Inspection Number: 20795728


Inspection Result:  
**PASS**

**FACILITY:** Kimberley J. Mak Holdings Inc. / S20114  
**INSPECTOR:** Chow, Normond Wai LEUNG / 112130  
**WORK ORDER #:** 91220  
**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 1 - Light Vehicle with LGVW 5500 kg or less  
**INSP. REASON:** New to BC  
**INSP. START:** 2024-Jan-22 10:30 AM PST  
**INSP. COMPLETE:** 2024-Jan-22 11:38 AM PST

**VEHICLE JURISDICTION:** California  
**REGISTRATION:** REGI:  
**PLATE #:** UNIT/FLEET#:  
**VIN:** 1N4BZ1DV1NC552340  
**OWNER/LESSEE NAME:** CYPRESS AUTO BROKERS, CYPRESS AUTO BROKERS  
**PERMITTED GVW(kg):** 4872  
**BODY STYLE:** 4-Door Vehicle  
**ADDRESS:** 11919 MAPLE MEADOWS WAY, 11919 MAPLE MEADOWS WAY  
**VEHICLE YEAR:** 2022  
**ODOMETER:** 18797 KM  
**MAKE:** NISSAN  
**HUB ODOMETER:** Maple Ridge, British Columbia  
**MODEL:** LEAF  
**BRAKE TYPE:** Hydraulic  
**FUEL TYPE:** Electric  
**V2X 3M7, Canada**

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3H - Hydraulic Brakes	Passed
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Passed

Tire Tread Depth (mm)						Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Outer L	Inner L	Inner R	Outer R	Steering	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	4.8			4.8	✓	Pad	9	9	Rotor	28.03	28.02
2	6.4			6.4		Pad	8	8	Rotor	16.01	16.03
Comment:						Comment:			Comment:		

**Inspection Comments:**  
**Has this Vehicle been road tested?** Yes  
**Road Test Date:** Before and After Inspection  
**Road Tester:** NORM CHOW  
**Inspector:** Chow, Normond Wai LEUNG  
**Signature:** 

This Inspection Report was submitted to CVSE on 2024-Jan-22 11:39 AM PST  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**  
The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

# Vehicle Inspection Form



**C09963056-8**

This form is no longer valid after the compliance date of: February 21, 2024

Section 1. Vehicle Information			
VIN:	1N4BZ1DV1NC552340	Odometer:	18,797 km
NISSAN / LEAF SL PLUS HATCHBACK 4D		Passenger Car	
Section 2. Statement Of Compliance Label Information			
Gross Vehicle Weight Ratings (in lbs.): 4872 lbs		Manufacture Date: 10/21	
Gross Axle Weight Ratings (in lbs) - <i>Please fill Below</i>			
Front:	2524 lbs	Next:	~
		Rear:	2392 lbs
Tire Pressure (in P.S.I.) Front:	36 psi	Rear:	36 psi
Section 3. Modifier Information			
Company/Individual that performed modifications (Please print):			
Section 4. Modifications required to conform to Canadian Vehicle Safety Standards			
<b>These Modifications are the responsibility of the importer. Inspector MUST confirm (x) the following:</b>			
<input checked="" type="checkbox"/> ELECTRONIC IMMOBILIZER SYSTEM [EIS]: verification of the presence of the EIS was completed using a <input checked="" type="checkbox"/> keyless drive <input type="checkbox"/> key validation machine <input type="checkbox"/> aluminium foil test <input type="checkbox"/> RIV approved OEM letter <input type="checkbox"/> Monroney label. Or EIS is not required because the vehicle <input type="checkbox"/> GVWR is greater than 10,000 lbs			
<input checked="" type="checkbox"/> DAY TIME RUNNING LIGHTS: When testing for DRL, the light switch was in the <input checked="" type="checkbox"/> OFF <input type="checkbox"/> AUTO with no OFF option <input type="checkbox"/> AUTO <input type="checkbox"/> ON position			
<input checked="" type="checkbox"/> FLOOD DAMAGE: please contact RIV immediately if there are any signs of water damage			
<input checked="" type="checkbox"/> Please contact RIV if this vehicle does not bear a Statement of Compliance label certifying the vehicle met all US Federal Motor Vehicle Safety Standards on the date of manufacture.			
<input type="checkbox"/> Clutch ignition interlock for manual transmission vehicles with GVWR is less than 10,000lbs: - the clutch pedal must be depressed or the drive train must be disengaged in order to start the vehicle, otherwise the vehicle will fail the inspection.			
<input checked="" type="checkbox"/> Air bag equipped vehicles are required to have functioning air bags at time of inspection.			
<input checked="" type="checkbox"/> This vehicle requires a French SRS Maintenance label if it is equipped with an airbag that requires periodic maintenance or replacement.			
<input checked="" type="checkbox"/> INSPECTION CENTRE: attach miles odometer label if required.			
<input checked="" type="checkbox"/> SPEEDOMETER: shall be calibrated in kilometers per hour or both kilometers per hour and miles per hour. Digital speedometers that switch between kilometers per hour and miles per hour are permitted if the unit of measure is identified			
<input checked="" type="checkbox"/> This vehicle requires an infant restraint kit, unless it is a convertible.			
Section 5. Declaration - Inspection Centre Only			
This vehicle as inspected		<i>Inspection Stamp here</i>	
<input checked="" type="checkbox"/> Pass <input type="checkbox"/> Fail			
Form 1 No.: C09963056-8 - this number must be the same as form 1			
No Form-1 required - paperless import			
JAN 22, 2024	NORM CHOW	481-C	
Date	Print Inspector's Name	Centre No.	Inspector's Signature
- Please transmit inspection result to RIV immediately -			



West Coast Nissan Ltd. d.b.a.  
**WEST COAST NISSAN**

19625 Lougheed Hwy., Pitt Meadows, B.C. V3Y 1Z2  
 Tel: 604-460-1333 Fax: 604-460-0332  
 www.westcoastautogroup.com

CELL: 604-719-7615

**OUT** INDEBTEDNESS IS HEREBY ACKNOWLEDGED IN THE SUM OF \$ \_\_\_\_\_ BEING ALL OF THE BALANCE OWING FOR REPAIRS, PARTS, & ACCESSORIES DESCRIBED IN THIS WORK ORDER.  
 DATE \_\_\_\_\_ SIGNATURE \_\_\_\_\_

ALL ITEMS ARE SUBJECT TO G.S.T.

CUSTOMER NO. <b>6965</b>	ADVISOR <b>NICOLE BEVERIDGE</b>	TAG NO. <b>596</b>	INVOICE DATE <b>01/09/24</b>	INVOICE NO. <b>NICS96576</b>
<b>CYPRESS AUTO BROKERS</b> 11919 MAPLE MEADOWS WAY MAPLE RIDGE, BC V2X 3M7	LABOUR RATE <b>159.95</b>	LICENSE NO.	KILOMETRES <b>11,677</b>	COLOUR <b>/</b>
	YEAR/MAKE/MODEL <b>22/NISSAN/LEAF/4DR HB SL PLUS</b>		DELIVERY DATE	DELIVERY KMS.
	VEHICLE I.D. NO. <b>1 N 4 B Z 1 D V 1 N C 5 5 2 3 4 0</b>		SELLING DEALER NO.	PRODUCTION DATE
<b>AARONYOUSOFI@HOTMAIL.COM</b>	F.T.E. NO. <b>1014-4575</b>	P.O. NO.	R.O. DATE <b>01/09/24</b>	IN SERVICE DATE
RESIDENCE PHONE	BUSINESS PHONE <b>604-719-7615</b>	COMMENTS	<b>MO: 11678</b>	

JOB# 1 CHARGES-----  
 LABOR-----  
 # 1 21NIZ RECALL HOURS: 0.50 TECH(S):5443 WARRANTY  
 COMPLAINT: R23A6LEAF VCM REPRO NTB23-057  
 CAUSE: AS OUTLINED ON NISSAN SERVICE CAMPAIGN BULLETIN  
 CORRECTION: COMPLETED RECALL AS PER CAMPAIGN INSTRUCTIONS

JOB# 1 TOTALS-----  
 JOB# 1 JOURNAL PREFIX NICS JOB# 1 TOTAL 0.00

COMMENTS-----  
 DELETED OPERATION(S)-----  
 55NIZT-ESMPI VEHICLE INSPECTION I 55NIZZ-WAS COMP WASH & VACUUM  
 55NIZT-MET METHOD OF CONTACT


TAX SUMMARY-----  
 PST 0.00 1000-8695 GST 0.00 R-860144484

TOTALS-----  
 \*\*\*\*\* Method of Payment \*\*\*\*\*  
 \* WCAG CARD [ ] REDEEMED [ ] \* TOTAL LABOR.... 0.00  
 \* Charge [ ] Interac [ ] \* TOTAL PARTS.... 0.00  
 \* Visa [ ] Mastercrd [ ] Amex [ ] \* TOTAL SUBLET... 0.00  
 \* Account#: \_\_\_\_\_ Other \_\_\_\_\_ \* TOTAL G.O.G.... 0.00  
 \* \_\_\_\_\_ \* TOTAL MISC CHG. 0.00  
 \* \_\_\_\_\_ \* TOTAL MISC DISC 0.00  
 \*\*\*\*\* \* TOTAL TAX..... 0.00

\*\*\*\*\* THANK YOU FOR YOU BUSINESS \*\*\*\*\* **TOTAL INVOICE \$ 0.00**

If you have questions, positive comments or concerns notify Sarah Hudon at 604.460.1333 or karissa@westcoastautogroup.com. To receive Special Offers only available via email visit our website at www.westcoastnissan.ca

CUSTOMER SIGNATURE



**SERVICE**  
 HOURS OF OPERATION  
 MON-FRI  
 8:00 am - 5:30 pm  
 SAT  
 8:30 am - 5:00 pm

**PARTS**  
 HOURS OF OPERATION  
 MON-FRI  
 8:00 am - 5:30 pm  
 SAT  
 8:30 am - 5:00 pm

**PARTS DIRECT**  
 604-460-1334

**TOLL FREE**  
 1-888-460-1333

PLEASE VISIT US ONLINE  
 www.westcoastautogroup.com

*Thank You  
 for allowing us to  
 care for your vehicle*