

Vehicle History Report (BC) #: 52003540 Report Date: March 15, 2024 | 2:03 PM EDT

Report Status: Complete

Reference:

## 2006 ISUZU NPR

Straight truck | 4 Cylinders | Diesel JALB4B16467015790

Country of Assembly: United States Last Reported Odometer: 42,466 MI



Glass Records found



Last Registered In: British Columbia (Normal)



1 Service Record Found



U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca

This vehicle history report is based on information (https://www.carfax.ca/vehicle-history-data) that was reported and available to CARFAX Canada as of March 15, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. There may be other information about this vehicle that has not been reported to CARFAX Canada. When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History

Report, along with a vehicle inspection and test drive, to make an informed decision.

# **Vehicle History Report (BC)**



## Accident/Damage



There are no police reported accidents, estimates, or claims reported on this vehicle, however, we found other damage records that are outlined below.

#### Other Damage Records

RECORD DATE	DETAILS	AMOUNT
① 2014 Sep 10	British Columbia, Canada	
	Glass Record	\$652.59
2015 Nov 13	British Columbia, Canada	•
	Glass Record	\$664.93



#### Registration

This vehicle has been registered in the province of British Columbia in Canada with Normal branding.

**We checked for:** Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.

This vehicle has been registered in the state of Oregon in the United States. No major title problems were reported.

**We checked for:** Salvage, Junk, Rebuilt, Fire, Flood, Hail and Lemon.



#### Service Records

DATE	ODOMETER	SOURCE	DETAILS
2011 Aug 24	42,466 MI	DSU - Peterbilt & GMC Truck Portland, Oregon, United States	Vehicle serviced  • Maintenance inspection completed



### **Open Recalls**

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact ISUZU or visit Isuzu's website.



This vehicle is not actively declared stolen.



# Detailed History

	DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
<b>X</b>	2006 Jan 31		Motor Vehicle Dept.	DMV Record	Title issued or updated
	2000 Jan 31		Oregon, United States	Adjustment	Loan or lien reported
			Oregon, ornica states		First Owner Reported
					•
	2007 Jan 31		Motor Vehicle Dept.	DMV Record	Registration Issued or
			Oregon, United States	Adjustment	Renewed
					Previous Use: Commercial
				DMV Record	Registration Issued or
**=	2008 Nov 24		Motor Vehicle Dept.		Renewed
			Oregon, United States	Adjustment	
					Previous Use: Commercial
	2009 Mar 11		Motor Vehicle Dept.	DMV Record	Registration Issued or
***	2009 Mar 11		Oregon, United States	Adjustment	Renewed
			Oregon, Ornited States	Adjustinent	Previous Use: Commercial
	1				
<b>#</b>	2010 Sep 13		Motor Vehicle Dept.	DMV Record	Registration Issued or
	2010 Sep 13		Oregon, United States	Adjustment	Renewed
					Previous Use: Commercial
				DMV Pocord	Title issued or updated
<b>##</b>	2011 Jul 29		Motor Vehicle Dept.	DMV Record	
			Oregon, United States	Adjustment	New Owner reported
	2011 Aug 15	68,317 KM	Auto Auction	Auction Announcement	Listed as a Dealer Vehicle
		<u>.</u>			Vehicle sold
	2011 A 24	42,466 MI	DSU - Peterbilt & GMC Truck	Service Record	Vehicle serviced
	2011 Aug 24	42,400 WII	Portland, Oregon, United	Service Record	
			States		
	2011 Aug 31		Motor Vehicle Dept.	DMV Record	Registration Issued or
			Oregon, United States	Adjustment	Renewed
					Previous Use: Commercial
***************************************	2014.5		Motor Vohicle Dest	Registration Records	Registered/Renewed
	2011 Sep 1		Motor Vehicle Dept. RV, Canada	Registration Records	Registered/Reflewed
					F U.s.ita -1 Ctt
Ca	2011 Sep 1		Motor Vehicle Dept.	Import Record	From: United States
7			Canada		To: Canada
					This yahisla has hasn
					This vehicle has been
					imported into Canada from
					the US. For more

information than is set out below, please contact RIV (www.riv.ca).

Imported Into Canada As:
Normal

Case/Dossier: M026316 Import Date: 9/1/2011 Entered Customs: 9/1/2011 Inspection Date: 9/6/2011

Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
Insurance Records British Columbia, Canada	Glass Record	\$652.59
Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
Insurance Records British Columbia, Canada	Glass Record	\$664.93
Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as gray
	Motor Vehicle Dept. British Columbia, Canada  Insurance Records British Columbia, Canada  Motor Vehicle Dept. British Columbia, Canada  Insurance Records British Columbia, Canada  Motor Vehicle Dept. British Columbia, Canada	British Columbia, Canada  Motor Vehicle Dept. British Columbia, Canada  Insurance Records British Columbia, Canada  Motor Vehicle Dept. British Columbia, Canada  Insurance Records British Columbia, Canada  Motor Vehicle Dept. British Columbia, Canada  Canadian Renewal  Insurance Records British Columbia, Canada  Motor Vehicle Dept. British Columbia, Canada

Registration Issued or
Renewed
Vehicle colour noted as
gray
 Registration Issued or
Renewed
Nellow 4
Previous Use: Commercial
Vehicle colour noted as
grav

Canadian Renewal

Canadian Renewal



## Questions? We're here to help.

Visit us at support.carfax.ca

#### **ICBC** Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

Motor Vehicle Dept.

Motor Vehicle Dept.

British Columbia, Canada

British Columbia, Canada

vehicles sold by insurance companies as salvage

2022 Jun 27

2023 Jul 1

- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at http://apps.icbc.com/registration/vchr/Limitation.html.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this evhicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

CARFAX



ACILITY:

#### **Commercial Vehicle Inspection Report**

INSP. TYPE:

**DEWDNEY AUTOMOTIVE / \$6758** 

**Decal Number: Decal Expiry Date:** Inspection Number:

**GB33393** 2025-Apr-30 20877029

INSP. START:

Inspection Result:

2024-Apr-03 10:00 AM PDT

INSP. COMPLETE: 2024-Apr-04 03:24 PM PDT Class 2 - Heavy Vehicle with LGVW OUELLETTE, ERNEST JOHN / INSP. CLASS: ISPECTOR: 5501 kg or more 107330 **VORK ORDER #:** 29994 INSP. REASON: Annual JALB4B16467015790 VIN-REGI: 10331273 British Columbia EHICLE JUR: DEERWOOD LANDSCAPING LTD. OWNER/LESSEE NAME: UNIT/FLEET#: EJ6310 LATE #: DEERWOOD LANDSCAPING LTD 825-1ST ST W **BODY STYLE: Dump Truck** ADDRESS: ICENCED GVW(kg): 6495 North Vancouver, British Columbia 150233 KM ODOMETER: 2006 EHICLE YEAR: V7P1A4, Canada **HUB ODOMETER:** ISUZU IAKE: Hydraulic **BRAKE TYPE:** ODEL: NPR **FUEL TYPE:** Diesel Passed Vehicle Identification (VIN) repaired warning light in dash Repaired (same day) Section 1 - Power Train Passed Section 2 - Suspension Passed Section 3 - Brake System Section 3H - Hydraulic Brakes Passed Passed Section 4 - Steering Section 5 - Instruments and Auxiliary replaced back up alarm and repaired wiring Repaired (same day) Equipment Repaired (same day) repaired rear marker light Section 6 - Lamps Passed Section 7 - Electrical System Section 8 - Frame and Body Passed replaced front tires and left rear tires Repaired (same day) Section 9A - Tires Passed Section 9B - Wheels

Complete

Axles	Outer L	Inner L	Inner R	Outer R	Steering
1	10			10	V
2	10	10	7.5	7.5	

Brake Lining/Pad (mm) Right Left Lining/Pad 5.5 5.5 Pad 6 6 Lining (Shoe) Comment:

Rotor Thickness or Drum Inside Diameter (mm) Rotor/Drum Right Rotor 39.90 39.90 321.60 321.60 Drum

Comment:

Road Tester:

nspection Comments:

nspector:

Section 10 - Coupling Devices

Section 11 - Other Vehicle Components

Has this Vehicle been road tested?

No **OUELLETTE, ERNEST JOHN** 

**Road Test Date:** Signature:

Not Applicable

Not Applicable

This Inspection Report was submitted to CVSE on 2024-Apr-04 03:24 PM PD/

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCIVIP at the Commercial Vehicle Safety Enforcement

4/4/2024 3:24:30 PM PDT

CVSE0014

#### **DEWDNEY AUTOMOTIVE REPAIRS LTD.**

102-11517 KINGSTON ST Maple Ridge, BC. V2X0Z5

Phone: 604-460-1066 Fax: 604-460-1570

GST#836400325RT0001

INVOICE

Printed Date: 04/05/2024

Work Completed: 04/05/2024

**CYPRESS AUTO BROKERS - ARRON** 

11919 MAPLE MEADOWS WAY

MAPLE RIDGE, BC V2X3M7

Home 604-465-3313 -- Office 604-719-7615

2006 Isuzu - NPR - 5.2L

Lic#:

Odometer In: 150233

INVOICE

29994

VIN #: JALB4B164 67015790

Home 604-465-3313 Office 604-719-7615				VIII # . JALD4D 104 070 13730			
Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Ext	
OIL FILTER	1.00	48.74	48.74	COMMERCIAL VEHICLE INSPECTION	2.00	290.00	
PG5495 ENGINE OIL	12.00	9.28	111 36	OIL & FILTER CHANGE AND INSPECTION - DIESEL	0.93	135.00	
15/40	12.00			Oil and filter changed steering parts and driveling Complete inspect, includes brakes, steering, exh	e lubed wher aust system	re able. , and	
AIR FILTER PA5639	1.00	76.87	76.87	drivetrain for fluid leaks. All lights belts hoses an checked. See notes for report.	d fluid levels	all	
BACK-UP ALARM 73040	1.00	47.65	47.65	INSTALL BACK UP BEEPER AND REPAIR WIRING	0.50	72.50	
GROMMET	1.00	3.90	3.90	REPLACE FUEL FILTER	0.50	72.50	
92120				INSTALL 4 TIRES	1.00	145.00	
MARKER LIGHT	1.00	5.86	5.86		to specs.		
45822				A/F GOOD TO -45C.			
FUEL FILTER  PF941	1.00	34.10	34.10	Hazardous Materials		4.00	
TIRE ENVIROMENTAL CHG - CAR	4.00	6.50	26.00				
TIRE ECCT500							
235/85R16 LOAD RANGE E FRD86	4.00	210.77	843.08				
Shop Supplies			32.00				
				18			

Org. Estimate 2,045.99 Revisions 0.00 **Current Estimate** 2,045.99

Labor: 715.00 Parts: 1,229.56

HazMat:

1,948.56

4.00

SubTotal: Tax:

97.43

Total:

2,045.99

Bal Due:

\$0.00

Thank You! We really do appreciate your business.

Vehicle Received: 4/5/2024

[ Payments - VISA - \$2,045.99 ]

Customer Number: 3708

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 20,000KMS whichever comes first. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE. ANY TIME WHEELS HAVE BEEN REMOVED VEHICLES MUST RETURN WITHIN 5 DAYS TO HAVE WHEELS RE TORQUED.

Signature

Date