



Vehicle History Report (BC) #: 52985243
Report Date: April 29, 2024 | 4:47 PM EDT
Report Status: Complete

2015 GMC SAVANA G2500

Van cargo | 8 Cylinders | Flexible
1GTW7FCF1F1140750
Country of Assembly: United States
Last Reported Odometer: 66,884 KM




Accident/Damage Records Found



Last Registered In:
British Columbia (Normal)




3 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of April 29, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report (BC)



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2016 Dec 3	British Columbia, Canada	
	Claim: COLLISION	\$0.00



Registration

This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2014 Dec 24		Humberview Chevrolet Buick GMC Etobicoke, Ontario, Canada	Vehicle serviced <ul style="list-style-type: none"> Pre-delivery inspection completed
2017 Aug 30	57,964 KM	Great Canadian Oil Change Coquitlam, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed
2017 Dec 18	66,884 KM	Great Canadian Oil Change Coquitlam, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Recommended maintenance performed Oil and filter changed Rear differential fluid flushed/changed Automatic transmission serviced



Open Recalls

Recall #: N172086770 | Driver Side Window Switch Inoperative Recall Date: 2018 May 03

Recall Description

General Motors has decided that a defect which relates to motor vehicle safety exists in 2014 – 2017 Chevrolet Express and GMC Savana vehicles (built through 6/21/16 and 6/17/16 respectively) equipped with power windows. Under certain conditions, liquid can enter the power window switches in these vehicles and cause corrosion, leading to high electrical resistance. High electrical resistance can cause the switch to heat up, smoke or melt, increasing the risk of fire and injury. Occupants may notice that the power window is malfunctioning or inoperative. Smoke or an odor from smoke or melting may also come from the door panel.

Remedy

Replace driver side door window switch.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact GMC or visit [GM's website](#).



Stolen Vehicle Check

☒ This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2014 Dec 13		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported
2014 Dec 24		Humberview Chevrolet Buick GMC Etobicoke, Ontario, Canada	Service Record	Vehicle serviced
2015 Feb 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Mar 5		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2016 Nov 26		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2016 Dec 3		Insurance Records British Columbia, Canada	COLLISION	
2017 Aug 30	57,964 KM	Great Canadian Oil Change Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced
2017 Oct 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2017 Dec 18	66,884 KM	Great Canadian Oil Change Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced
2018 Feb 17		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2018 May 3		GMC	Recall	Manufacturer Recall Issued Recall # N172086770
2019 Feb 24		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2020 Feb 21		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed

1GTW7FCF1F1140750

ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Feb 21	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed
2021 May 5	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Vehicle colour noted as white
2022 May 1	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as white
2023 Apr 9	Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as white



Questions? We're here to help.
Visit us at support.carfax.ca

ICBC Disclaimer
The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/Limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

[AS1] WGAT Courtesy Check

[AS1] WGAT Courtesy Check	O	S	M	R	
Inside vehicle and test drive					
CEL					
ABS/TRAC/EST					
Cooling system					
Oil change					
Charging					
Outside Vehicle					
Headlights					
Front signal light					
Wiper/arm					
Brake light					
Rear signal light					
Tail light					
License light					
Insurance decal					
Body condition					
Under Hood					
Accessory/drive belts					
Transmission fluid					
Power steering fluid					
Coolant					
Radiator and hoses					
Heater hoses/clamps					
Air conditioning lines and hoses					
Engine oil					
Brake fluid					
Engine air filter					
Battery and terminals					
Battery/cables/clamps					
Under Vehicle					
Steering components					
Front suspension components					
Rack and pinion pump, hoses, fluids					
Front struts/shocks					
Check for engine oil leaks					
Check for transmission fluid leaks					
Rear axle shafts & boots / U-Joint					
Rear shocks/struts					
Rear differential					
Muffler, exhaust pipes & hangers					Repaired flange at muffler. Other
Brakes					
Front brakes					Left Front 7mm /Right Front 7mm
Front rotors					
Front brake hydraulic system					
Front brake lines/hoses					
Rear brake pads/shoes					Left Rear 6mm /Right Rear 6mm

[AS1] WGAT Courtesy Check	O	S	M	R	
Rear brake rotors					
Rear brake hydraulic system					
Rear brake lines/hoses					
Tires					
Front tire condition					Observations: Front driver side tread depth: 9/32nd inches Front passenger side tread depth: 9/32nd inches
Alignment (4 wheel)					
Front tire pressure					
Rotation and balance check					
Rear tire condition					Observations: Rear driver side tread depth: 10/32nd inches Rear passenger side tread depth: 10/32nd inches
Rear tire pressure					



CC Auto Repair
#170 - 20170 Stewart Crescent
Maple Ridge, BC V2X0T4
604-460-6506

Invoice

Bill To Cypress Auto Brokers
Brokers, Cypress Auto
11919 Maple Meadows Way
Maple Ridge, B.C. V2X 3M7
Canada

Home (604) 719-7615 Arin
Email

Invoice # 1176
Work Order # 1734
Service Advisor Matt Preston
Technician Corey Huber

Plate BC GMCSAV
Description 2015 GMC Savana 2500 Base V8 4.8L 294CID
VIN F
VIN 1GTW7FCF1F1140750
Odometer 138,792

Invoice Date 4/29/2024 1:34 PM
Appointment 4/26/2024 9:00 AM
Promised 4/26/2024 5:00 PM

Concern

Check Engine Light On

Concern // Light is on - possibly exhaust issue as vehicle needs exhaust work done - please check and advise// **Had Codes P0171/ P0174 (Bank 1 and 2 lean codes) smoke checked intake system and found a leak from one of the breather hoses, repaired hose and cleaned mass air flow sensor (sensor was dirty and reading incorrectly).**

Labor	0.5 Hour		\$75.00 *GP
		Discount	(\$7.50)
		Sub	\$67.50

Inspection

[AS1] WGAT Courtesy Check

Labor	0.5 Hour		\$75.00 *GP
		Discount	(\$7.50)
		Sub	\$67.50

Service

Exhaust General Service

Remove and Replace components as required to access and install materials, and/or perform needed service, adjustments as required. Retest and verify repair as required. Perform final road test where applicable.

Exhaust Pipe Flange Gasket	1 Unit	\$29.07 / Unit	\$29.07 GP
Labor	0.3 Hour		\$45.00 *GP
		Discount	(\$7.41)
		Sub	\$66.66

Total Parts	\$26.16
Total Labor	\$175.50
Total Before Taxes & Miscellaneous Charges	\$201.66

(*) Shop Supplies, Enviro Fees, Cleaners, Grease, Lubricant, Small Parts, Fasteners and any other items too small to Invoice	5 %	\$8.78 PG
(G) Canadian Goods and Services Tax (GST)	5 %	\$10.53
(P) BC Provincial Sales Tax (PST)*		\$0.00
Exemption #: 1014-2701		
Grand Total		\$220.97

Total discounts applied is \$22.41

Cypress Auto Brokers paid \$220.97 by Visa
4/29/2024 1:34 PM Card #: XXXXXXXXXXXX7313 Entry Method: Chip Type: Sale Amount: 220.97
Terminal: 84208 Transaction: 610180f9-0668-4fc5-bfb8-ccc223c9c72a Authorization: 02899I Result: Approved
AID: A0000000031010 TC: ARQC: 1CEEFA7BC45DF7B4 TVR: 0080008000 TSI: E800

Buyer agrees to pay total amount above according to cardholder's agreement with issuer.

Thanks for the Business!

I acknowledge receipt of the vehicle and the indebtedness indicated herein.