

2018 FORD TRANSIT CONNECT XL

Van cargo | 4 Cylinders | Gas
NM0LS7E7XJ1365672
Country of Assembly: Spain
Last Reported Odometer: 113,137 KM


LIEN CHECK



Lien Record(s) Found



Accident/Damage Records Found



Last Registered In:
British Columbia (Normal)



10 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at support.carfax.ca



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of March 13, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

Vehicle History Report + Lien Check (BC)



Lien Check

1 Lien Record(s) found in **British Columbia**.

2 No lien records found in **Ontario**.

How We Check for Liens

CARFAX Canada uses the VIN to search government records in each Canadian province and territory (excluding Northwest Territories) where the vehicle is currently registered and where it has historically been registered. We do not check for liens or title in any U.S. state.

If a VIN has no registration records in Canada, we cannot check for liens. We cannot guarantee lien checks on trailers, recreational vehicles or heavy-duty equipment.

Purchasers should always get written confirmation from vendors that there is no lien on the vehicle.

CARFAX Canada Canadian Lien Guarantee



If for some reason our lien check fails to accurately reflect the Canadian enforceable lien status of a vehicle at the time of the search, CARFAX Canada will reimburse the party that purchased the report and relied on it to their detriment to a maximum amount of (1) the value of the car (2) the value of the lien (3) Five Thousand Dollars Canadian (\$5,000.00), whichever is lower.



Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
1 2020 Dec 8	Ontario, Canada	
	Police Reported Accident: Accident reported: severe damage with another motor vehicle Damage to right side	
	Claim: Other Damage	\$2,529.00



Registration

2 This vehicle has been registered in the following locations in **Canada** (listed oldest to newest):

- In the province of **Ontario** with **Normal** branding.
- In the province of **British Columbia** with **Normal** branding.

We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



Service Records

DATE	ODOMETER	SOURCE	DETAILS
2022 Nov 15	58,458 KM	Granville & Avery Automotive Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none">• Maintenance reminder reset• Oil and filter changed• Tie rod end(s) replaced• Drivability/performance checked• Brake pads replaced• Front brake rotor(s) replaced• Brake rotor(s) replaced• Decals/letters/name plates replaced• Brakes checked• Front brake pads replaced

ODOMETER		SOURCE	DETAILS
2022 Dec 27		Granville & Avery Automotive Vancouver, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Tires rotated
2023 Feb 16	68,531 KM	Great Canadian Oil Change Prince George, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Air filter checked
2023 Mar 3	71,638 KM	Great Canadian Oil Change Prince George, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed
2023 May 1	82,060 KM	Great Canadian Oil Change Prince George, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed
2023 May 6	82,656 KM	Kal Tire 096 Prince George, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Four wheel alignment performed One tire mounted One tire balanced
2023 Jun 26	92,965 KM	Great Canadian Oil Change Prince George, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Air filter checked
2023 Jul 21	97,887 KM	Great Canadian Oil Change Prince George, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Oil and filter changed Air filter checked
2023 Aug 29	105,583 KM	Great Canadian Oil Change Prince George, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Maintenance inspection completed Fluids checked Oil and filter changed Automatic transmission serviced Transmission fluid changed
2023 Dec 12	113,137 KM	Carter GM Burnaby Burnaby, British Columbia, Canada	Vehicle serviced <ul style="list-style-type: none"> Oil and filter changed



Open Recalls

- No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact FORD or visit [Ford's website](#).



Stolen Vehicle Check

- This vehicle is not actively declared stolen.



Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Feb 2		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Commercial Vehicle colour noted as white
2020 Dec 8		Police Reported Accident Ontario, Canada	Police Report	Accident Reported: <ul style="list-style-type: none"> • severe damage • with another motor vehicle • Damage to right side
2020 Dec 8		Insurance Records Ontario, Canada		
2021 Apr 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Commercial Vehicle colour noted as white
2021 Apr 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2022 Mar 16		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as white
2022 Nov 15	58,458 KM	Granville & Avery Automotive Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2022 Nov 20		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as white
2022 Dec 6	58,501 KM	Independent Source Vancouver, British Columbia, Canada	Odometer reading	
2022 Dec 27		Granville & Avery Automotive Vancouver, British Columbia, Canada	Service Record	Vehicle serviced
2022 Dec 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Vehicle colour noted as white
2023 Feb 16	68,531 KM	Great Canadian Oil Change Prince George, British Columbia, Canada	Service Record	Vehicle serviced
2023 Mar 3	71,638 KM	Great Canadian Oil Change Prince George, British Columbia, Canada	Service Record	Vehicle serviced
2023 May 1	82,060 KM	Great Canadian Oil Change Prince George, British Columbia, Canada	Service Record	Vehicle serviced
2023 May 6	82,656 KM	Kal Tire 096 Prince George, British Columbia, Canada	Service Record	Vehicle serviced

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2023 Jun 26	92,965 KM	Great Canadian Oil Change Prince George, British Columbia, Canada	Service Record	Vehicle serviced
2023 Jul 21	97,887 KM	Great Canadian Oil Change Prince George, British Columbia, Canada	Service Record	Vehicle serviced
2023 Aug 29	105,583 KM	Great Canadian Oil Change Prince George, British Columbia, Canada	Service Record	Vehicle serviced
2023 Oct 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Vehicle colour noted as white
2023 Nov 6		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as white
2023 Nov 30		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as white
2023 Dec 12	113,137 KM	Carter GM Burnaby Burnaby, British Columbia, Canada	Service Record	Vehicle serviced
2024 Jan 18		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as white
2024 Feb 12		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as white
2024 Mar 8		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as white



Questions? We're here to help.

Visit us at support.carfax.ca

ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. [Conditions of Use](#)





UNIT #8 - 20071 113B AVENUE

MAPLE RIDGE, BC V2X 0Z2

O: 604 460 7142

C: 604 721 1432

RIDGEMOTORSAUTOREPAIR@GMAIL.COM

MULTI-POINT INSPECTION

Name: Cypress Auto Year/Make/Model: 2018 Ford Transit Connect KMs: 113358

RO#: 4454 VIN: NMDL57E7XJ1365672 License: _____

CHECKED AND OK

FUTURE ATTENTION

IMMEDIATE ATTENTION

INTERIOR/EXTERIOR	
NOTE ANY EXISTING BODY DAMAGE	
Lights (Head, Brake, Turn, Parking)	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Windshield / Glass	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Wipers	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Horn / Interior Lights	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

TIRES	
TREAD DEPTH	
<input checked="" type="checkbox"/> 7/32" or greater	<input type="checkbox"/> 3/32" to 6/32" <input type="checkbox"/> 2/32" or less
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 8/32"	RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 8/32"
LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 8/32"	RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> 8/32"
	Wear Pattern / Damage LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
	Air Pressure <input type="checkbox"/> BEFORE SHOULD BE LF <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> RF <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> LR <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> RR <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
	Based on Mileage and Wear: <input type="checkbox"/> Alignment <input type="checkbox"/> Balance <input type="checkbox"/> Rotation <input type="checkbox"/> New Tire
	LF <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> RF <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> LR <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> RR <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

BATTERY	
<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

BRAKES	
BRAKE PADS / SHOES	
<input checked="" type="checkbox"/> Over 5 mm (Disk) or 2 mm (Drum)	
<input type="checkbox"/> 3-5 mm (Disk) or 1.01-2 mm (Drum)	
<input type="checkbox"/> Less than 3 mm (Disk) or 1 mm (Drum)	
LF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> RF <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> LR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> RR <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

UNDERHOOD	
Oil Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Transmission Fluid	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Power Steering / Brake Fluid	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Coolant / Antifreeze	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Air Filter	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Cabin Filter	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Belts	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

UNDER VEHICLE	
Brake Lines / Brake Hoses / Brake Cables / Fuel Lines	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Suspension & Steering	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Driveline (Axles / CV Shaft)	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Rear Differential Fluid Level & Condition	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Exhaust System / Shocks & Struts	<input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>

COMMENTS	
Front Brake	11mm
Rear Brake	8mm

INSPECTOR: Jim DATE: _____

Invoice

Ridge Motors Auto Repair and Tires
 Unit 8 - 20071 113B Avenue
 Maple Ridge, BC V2X 0Z2
 (604) 460-7142

Date	Invoice #
4/11/2024	4454

GST/HST No. 758148118

Invoice To
Cypress Auto Brokers moc

Vehicle Description
2018 Ford Transit connect

ODO IN	ODO OUT	Plate	VIN
113358			nm0ls7e7xj1365672

Quantity	Item	Description	Price Each	Amount	Tax
1.5	I_Inspection_Gen...		80.00	80.00	G
	L_Brakes_Pads_R...		80.00	120.00	G
1	P_Pads_Front		65.00	65.00	G
2	P_Rotors_Front		95.00	190.00	G
	P_Misc_Brakes	Partsource#103574 103577 front brake hardware	22.59	22.59	G
	S_Misc_Shop_M...	top up coolant and washers	20.00	20.00	G
		GST on sales	5.00%	24.88	
Sales Tax Total				\$24.88	
Total				\$522.47	

I hereby authorize you and your employees to carry out the repair work described above and to purchase on my account any parts and materials necessary to carry out the repair work subject to the estimate described above. I hereby authorize you and your employees to operate the vehicle listed above in connect with the repair work, including operation for the purposes of testing, inspection or delivery. I HERBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repair work authorized hereby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repair work.

By signing below I acknowledge and agree to the terms and conditions above

Customer Signature _____