

Vehicle History Report (BC) #: 54783442  
Report Date: July 12, 2024 | 3:51 PM EDT  
Report Status: Complete




# 2019 RAM 1500 CLASSIC TRADESMAN

Pickup | 8 Cylinders | Gas  
3C6JR7DT5KG506730  
Country of Assembly: Mexico  
Last Reported Odometer: 64,770 KM

One Owner




Accident/Damage Records Found



Last Registered In:  
**British Columbia (Normal)**



10 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)



This vehicle history report is based on information (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of July 12, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# Vehicle History Report (BC)



## Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2019 Mar 1	<b>British Columbia, Canada</b>	
	<b>Estimate:</b> RIGHT SIDE   Estimate Date: n/a	\$4,175.71
	<b>Claim:</b> COLLISION RIGHT SIDE	\$3,771.03



## Registration

This vehicle has been registered in the province of **British Columbia** in **Canada** with **Normal** branding.

*We checked for: Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2018 Dec 20		Coquitlam Chrysler Coquitlam, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Pre-delivery inspection completed</li> <li>Windshield washer checked</li> </ul>
2019 Sep 19	9,505 KM	Service Facility	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> </ul>
2020 May 8	16,785 KM	Service Facility	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> </ul>
2021 Feb 10	24,724 KM	Service Facility	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>A/C system checked</li> <li>Oil and filter changed</li> <li>Cabin air filter replaced/cleaned</li> </ul>
2021 Aug 12	35,610 KM	Service Facility	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> </ul>
2022 Jun 16	49,623 KM	Service Facility	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Air filter replaced</li> <li>Air filter checked</li> <li>Oil and filter changed</li> </ul>
2022 Sep 23	52,374 KM	Kal Tire 075 Coquitlam, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>One tire mounted</li> <li>One tire balanced</li> <li>Tire valve stem(s)/core(s) replaced</li> <li>Tire(s) replaced</li> <li>Tire condition and pressure checked</li> </ul>

3C6JR7DT5KG506730

	ODOMETER	SOURCE	DETAILS
2022 Dec 30	54,919 KM	Kal Tire 075 Coquitlam, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Headlight bulb(s) replaced</li> <li>Headlight(s) replaced</li> <li>Brakes serviced</li> <li>Tail light assembly replaced</li> <li>Rear brake rotor(s) replaced</li> <li>Rear brake pads replaced</li> <li>Brakes checked</li> <li>Tire repaired</li> <li>Front brake pads replaced</li> </ul>
2023 Jun 19	58,955 KM	Service Facility	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> </ul>
2024 Jan 24	64,770 KM	Service Facility	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>Oil and filter changed</li> </ul>



### Open Recalls

No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact RAM or visit Ram's website. (<https://www.mopar.com/en-ca/my-vehicle/recalls/search.html>)



### Stolen Vehicle Check

This vehicle is not actively declared stolen.



### Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2018 Dec 20		Coquitlam Chrysler Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced
2018 Dec 23		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Lease
2019 Mar 1		Insurance Records British Columbia, Canada	COLLISION	RIGHT SIDE
2019 Mar 1		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a RIGHT SIDE
2019 Jul 28		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2019 Sep 19	9,505 KM	Service Facility	Service Record	Vehicle serviced
2020 May 8	16,785 KM	Service Facility	Service Record	Vehicle serviced

3C6JR7D15KG506730

	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2020 Sep 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease
2021 Feb 10	24,724 KM	Service Facility	Service Record	Vehicle serviced
2021 Jul 25		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease Vehicle colour noted as white
2021 Aug 12	35,610 KM	Service Facility	Service Record	Vehicle serviced
2022 Jun 16	49,623 KM	Service Facility	Service Record	Vehicle serviced
2022 Jul 24		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease Vehicle colour noted as white
2022 Sep 23	52,374 KM	Kal Tire 075 Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced
2022 Dec 30	54,919 KM	Kal Tire 075 Coquitlam, British Columbia, Canada	Service Record	Vehicle serviced
2023 Jun 19	58,955 KM	Service Facility	Service Record	Vehicle serviced
2023 Aug 6		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Lease Vehicle colour noted as white
2024 Jan 24	64,770 KM	Service Facility	Service Record	Vehicle serviced



Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)

#### ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registrations/vctr/Limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

#### CARFAX Canada One Owner™ Badge

The CARFAX Canada One Owner™ badge that is based on the registration information reported to CARFAX Canada. The badge is available for personal and commercial vehicles that have only been registered in the provinces of British Columbia, Alberta, Saskatchewan, Manitoba, Ontario, Quebec, Nova Scotia, New Brunswick, or PEI.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. <https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2024 CARFAX Canada ULC. All rights reserved.



# Vehicle Inspection Report

Date: Aug 16 2024

Page: 1/2

RepairOrder 20048100095366

CYPRESS AUTO BROKERS



2019 DODGE-RAM TRUCK RAM 1500 CLASSIC V8-345 5.7L

Odometer In: 67049

Odometer Out: 67049

VIN: 3C6JR7DT5KG506730

Plate: kkkkkkkkk

## VEHICLE WALK AROUND

### Comments

Exterior Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Headlights	<input type="checkbox"/> Brake Lights	<input type="checkbox"/> Turn Signals	
Wiper Blades	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Torn	<input type="checkbox"/> Streaks	<input type="checkbox"/> Rear	
Horn	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> No Sound			
Dash Warning Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Check Engine	<input type="checkbox"/> TRAC	<input type="checkbox"/> ABS	
Oil Light Reset	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> N/A	<input type="checkbox"/> Reset	<input type="checkbox"/> Oil Change Required	

## UNDER HOOD

### Comments

Battery Test	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> CCA Fail	<input type="checkbox"/> Recharge	<input type="checkbox"/> N/A	
Belt(s)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Cracked	<input type="checkbox"/> Loose	<input type="checkbox"/> Noise	
Air Filter	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Restricted	<input checked="" type="checkbox"/> Mileage	<input type="checkbox"/> N/A	
<b>Suggest:</b> Part is close to end of useful life							
Cabin Air Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Restricted	<input type="checkbox"/> Mileage	<input checked="" type="checkbox"/> N/A	
Coolant	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Low	<input type="checkbox"/> Freeze point	<input type="checkbox"/> PH Level	
Windshield Fluid	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Low	<input checked="" type="checkbox"/> Topped Up	<input type="checkbox"/> N/A	
Brake Fluid(visual)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Low	<input type="checkbox"/> Dark	<input type="checkbox"/> N/A	

## UNDER VEHICLE

### Comments

Fluid Leaks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Engine Oil	<input type="checkbox"/> Power Steering	<input type="checkbox"/> Coolant	
CV Boots	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Cracked	<input type="checkbox"/> Leaking	<input type="checkbox"/> N/A	

## AROUND THE WHEELS - FRONT

### Comments

Tire Pressure: Driver Side	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Under Inflated	<input type="checkbox"/> Over Inflated	<input checked="" type="checkbox"/> Filled Up	
Tire Pressure: Passenger Side	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Under Inflated	<input type="checkbox"/> Over Inflated	<input checked="" type="checkbox"/> Filled Up	
Tire Tread: Driver Side	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Sugg.(-5/32)	<input type="checkbox"/> Req.(-2/32)	<input type="checkbox"/> Puncture	
Tire Tread: Passenger Side	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Sugg.(-5/32)	<input type="checkbox"/> Req.(-2/32)	<input type="checkbox"/> Puncture	
Steering & Suspension	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Loose	<input type="checkbox"/> Leaking	<input type="checkbox"/> Mileage	
Brakes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Sugg.(-4mm)	<input type="checkbox"/> Req.(-3mm)	<input checked="" type="checkbox"/> N/A	

#### Reason Codes

##### Required:

- A - Part no longer performs intended function
- B - Part does not meet a design specification (regardless of performance)
- C - Part is missing

##### Suggested:

- 1 - Part is close to end of useful life (just above discard specifications, or weak, failure likely to occur soon, etc.)
- 2 - Address a customer need, convenience, or request (to stiffen ride, enhance performance, eliminate noise, etc.)
- 3 - To comply with maintenance recommended by the vehicle Original Equipment Manufacturer
- 4 - Technician's recommendation based on substantial and informed experience

# Vehicle Inspection Report

Date: Aug 16 2024

Page: 2/2

RepairOrder 20048100095366

CYPRESS AUTO BROKERS



2019 DODGE-RAM TRUCK RAM 1500 CLASSIC V8-345 5.7L

Odometer In: 67049

Odometer Out: 67049

VIN: 3C6JR7DT5KG506730

Plate: kkkkkkkkk

NOTE: Brake inspection may only be performed during a service that includes removal of tires and wheels.

## AROUND THE WHEELS - REAR

### Comments

Tire Pressure: Driver Side	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Under Inflated	<input type="checkbox"/> Over Inflated	<input checked="" type="checkbox"/> Filled Up
Tire Pressure: Passenger Side	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Under Inflated	<input type="checkbox"/> Over Inflated	<input checked="" type="checkbox"/> Filled Up
Tire Tread: Driver Side	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Sugg.(-5/32)	<input type="checkbox"/> Req.(-2/32)	<input type="checkbox"/> Puncture
Tire Tread: Passenger Side	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Sugg.(-5/32)	<input type="checkbox"/> Req.(-2/32)	<input type="checkbox"/> Puncture
Steering & Suspension	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Loose	<input type="checkbox"/> Leaking	<input type="checkbox"/> Mileage
Brakes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Sugg.(-4mm)	<input type="checkbox"/> Req.(-3mm)	<input checked="" type="checkbox"/> N/A

NOTE: Brake inspection may only be performed during a service that includes removal of tires and wheels.

## ADDITIONAL FINDINGS

### Comments

See Comments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/> N/A
--------------	-------------------------------------	--------------------------	--------------------------	---

#### Reason Codes

##### Required:

- A - Part no longer performs intended function
- B - Part does not meet a design specification (regardless of performance)
- C - Part is missing

##### Suggested:

- 1 - Part is close to end of useful life (just above discard specifications, or weak, failure likely to occur soon, etc.)
- 2 - Address a customer need, convenience, or request (to stiffen ride, enhance performance, eliminate noise, etc.)
- 3 - To comply with maintenance recommended by the vehicle Original Equipment Manufacturer
- 4 - Technician's recommendation based on substantial and informed experience







Canadian Tire Associate Store 0481  
 KIMBERLEY J. MAK HOLDINGS INC.  
 11969 - 200TH STREET

PAGE: 2  
 DATE: Aug 16 24



**INVOICE**  
**20048100095366**

Maple Ridge, BC V2X 3M7  
 Phone: 604-460-4664 Fax: 604-460-4665  
 e-mail:

GST REG#: 778156117  
 PST REG#: 1107-5287

**SOLD TO:**  
**9104864.0481**  
**CYPRESS AUTO BROKERS**  
**11919 MAPLE MEADOWS WAY**  
**MAPLE RIDGE BC V2X 3M7**

2505521817- AMARDEEP  
 MOBILE : 604 780-4270 HOME: 604 465-3313  
 BUSINESS: 604 465-3313 FAX :  
 EMAIL :

<b>COLOUR</b>	<b>VEHICLE DESCRIPTION</b>	<b>PLATE</b>	<b>UNIT#</b>	<b>TAG</b>	<b>ODO IN</b>
white	2019 DODGE-RAM TRUCK RAM 1500 CLASSIC V8-345 5.7L	kkkkkkkkk			67049
<b>VIN</b>	<b>VEHICLE OPTIONS</b>			<b>ADV</b>	<b>ODO AUTH</b>
3C6JR7DT5KG506730				IM01	67049
<b>TIME IN</b>	<b>PROMISED</b>	<b>TERMS</b>	<b>GST EXEMPT#</b>	<b>P.O.</b>	<b>ODO OUT</b>
3:30 PM	5:00 PM	Cash			67049

QTY	ITEM	DESCRIPTION	WARR	NET	EXT.PRICE
		<p>QUESTIONS OR CONCERNS--GREAT SERVICE=HAPPY PEOPLE</p> <p>*** Warranty Code Legend ***</p> <p>M1: See Service Manager for details</p> <p>A1: 1 YEAR OR 20,000KM exchange warranty for part only when installed in Canadian Tire service. Or 1YEAR exchange for Do IT yourself</p> <p>*** Global Warranty Message ***</p> <p>Installed parts warranties applicable only when product is installed at a Canadian Tire Automotive Service Centre, otherwise warranties may vary. Warranty not available for commercial use. A minimum labour warranty of 100 days / 5500 km applies to installed parts unless otherwise stated above. Installed parts warranty starts on the completion date shown on the customer invoice. Please see auto parts staff for cash &amp; carry parts warranties.</p> <p>***Wheel Retorque***</p> <p>Canadian Tire checks every tire after installation and retorques to the manufacturer's recommended values. It is recommended to have your wheels retorqued after driving for a short distance to account for any settling that can happen from continuous contact with the road. For added protection, kindly return to this location for a free wheel retorque after driving your vehicle between 50km and 100km.</p> <p>***PRIVACY TERMS***</p> <p>Canadian Tire Corporation, Limited, its affiliates, Associate Dealers, and service providers ("CTC" or "our") collect and use the personal information provided by you to fulfill this contract. CTC may also collect and use your information to administer the delivery of and market warranties, products, services, and loyalty programs to you, and to analyze your relationship with us. Please visit <a href="http://www.canadiantire.ca">www.canadiantire.ca</a> for details on CTC's privacy policy. If you do not wish for your information to be kept in our database, please contact CTC's Corporate Customer Relations at 1-866-846-5841 or via email at <a href="https://www.ctfs.com/ContactUs/">https://www.ctfs.com/ContactUs/</a>.</p> <p>***Tire Storage Terms***</p> <p>Storage term: (applicable only to customers who have purchased tire storage) Tires will be stored up to a maximum of 8 months from Invoice date OR until customer requests to have Tires removed from the storage location for any reason, at which point the storage term will end. Canadian Tire is not responsible for unclaimed tires at expiration of storage term. Tires left beyond 30 days of term expiration date will be disposed of without any liability or</p>			

INVOICE TO:

I hereby authorize you and your employees to carry out the repairwork described above and to purchase on my account any parts and materials necessary to carry out the repairwork subject to the estimate described above. I hereby authorize you and your employees to operate the vehicle listed above in connection with the repairwork, including operation for the purposes of testing, inspection or delivery. I HEREBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repairwork authorized hereby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repairwork. By signing below I acknowledge and agree to the terms and conditions above and to those printed on the reverse side of this form.

Customer Signature: \_\_\_\_\_

PARTS:	
LABOUR:	
OTHER:	
SUB-TOTAL:	
GST/HST:	
PST:	
<b>TOTAL:</b>	<b>Cont'd</b>



Canadian Tire Associate Store 0481  
 KIMBERLEY J. MAK HOLDINGS INC.  
 11969 - 200TH STREET

Maple Ridge, BC V2X 3M7  
 Phone: 604-460-4664 Fax: 604-460-4665  
 e-mail:

PAGE: 3  
 DATE: Aug 16 24



**INVOICE**

**20048100095366**

GST REG#: 778156117  
 PST REG#: 1107-5287

**SOLD TO:**  
**9104864.0481**  
**CYPRESS AUTO BROKERS**  
**11919 MAPLE MEADOWS WAY**  
  
**MAPLE RIDGE BC V2X 3M7**

2505521817- AMARDEEP  
 MOBILE : 604 780-4270 HOME: 604 465-3313  
 BUSINESS: 604 465-3313 FAX :  
 EMAIL :

COLOUR	VEHICLE DESCRIPTION	PLATE	UNIT#	TAG	ODO IN
white	2019 DODGE-RAM TRUCK RAM 1500 CLASSIC V8-345 5.7L	kkkkkkkkk			67049
VIN	VEHICLE OPTIONS			ADV	ODO AUTH
3C6JR7DT5KG506730				IM01	67049
TIME IN	PROMISED	TERMS	GST EXEMPT#	P.O.	ODO OUT
3:30 PM	5:00 PM	Cash			67049

QTY	ITEM	DESCRIPTION	WARR	NET	EXT.PRICE
		obligation to customer. Payment for Tire Storage is deemed to be acceptance of these terms by customer.			

INVOICE TO:

I hereby authorize you and your employees to carry out the repairwork described above and to purchase on my account any parts and materials necessary to carry out the repairwork subject to the estimate described above. I hereby authorize you and your employees to operate the vehicle listed above in connection with the repairwork, including operation for the purposes of testing, inspection or delivery. I HEREBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repairwork authorized hereby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repairwork. By signing below I acknowledge and agree to the terms and conditions above and to those printed on the reverse side of this form.

Customer Signature: \_\_\_\_\_

PARTS :	56.28
LABOUR :	43.46
OTHER :	4.09
SUB-TOTAL :	103.83
GST/HST :	5.19
PST :	N/C
<b>TOTAL :</b>	<b>109.02</b>