



# 2021 FORD TRANSIT T-350

Van passenger | 6 Cylinders | Gas  
1FBAX9C82MKA35742  
Country of Assembly: United States  
Last Reported Odometer: 28,044 KM



Accident/Damage Records Found



Last Registered In:  
British Columbia (Normal)



8 Service Records Found



No U.S. History Found



No Open Recalls Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)



This vehicle history report is based on **information** (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of November 06, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.



# Vehicle History Report (BC)



## Accident/Damage

INCIDENT DATE	DETAILS	AMOUNT
2022 Nov 18	<b>British Columbia, Canada</b>	
	<b>Estimate:</b> FRONT CENTER   Estimate Date: n/a	\$42,484.80
	<b>Claim:</b> ANIMAL COLLISION FRONT CENTER	\$39,834.93



## Registration

This vehicle has been registered in the following locations in **Canada** (listed oldest to newest):

- In the province of **Alberta** with **Normal** branding.
- In the province of **British Columbia** with **Normal** branding.

**We checked for:** Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2021 Apr 13		Koch Ford Lincoln Edmonton, Alberta, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Pre-delivery inspection completed</li> </ul>
2021 Apr 28		Koch Ford Lincoln Edmonton, Alberta, Canada	<b>Vehicle serviced</b>
2022 Feb 15	9,551 KM	Northstar Ford Fort McMurray Fort McMurray, Alberta, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Maintenance inspection completed</li> </ul>
2022 Nov 1	11,362 KM	Windsor Motors 1975 Ltd Grande Prairie, Alberta, Canada	<b>Vehicle serviced</b>
2023 May 30	11,840 KM	Bannister Ford - Dawson Creek. Dawson Creek, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Valve cover(s) replaced</li> </ul>
2023 Aug 4	11,850 KM	Bannister Ford - Dawson Creek. Dawson Creek, British Columbia, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• A/C and heating system checked</li> </ul>
2023 Oct 17	12,085 KM	Windsor Motors 1975 Ltd Grande Prairie, Alberta, Canada	<b>Vehicle serviced</b>
2024 Jul 29	28,044 KM	Team Ford Sales Ltd Edmonton, Alberta, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"> <li>• Interior cleaned</li> <li>• Four tires balanced</li> <li>• Four tires mounted</li> </ul>

1FBAX9C82MKA3574Z



ODOMETER	SOURCE	DETAILS
		<ul style="list-style-type: none"> <li>• Safety inspection performed</li> <li>• Outside mirror replaced/repared</li> <li>• Brakes serviced</li> <li>• Four tires replaced</li> <li>• Brakes checked</li> </ul>



## Open Recalls

- ✓ No safety recall information available as of the date/time that this report was generated. For additional safety recall information and non-safety related recall campaigns, please contact FORD or visit [Ford's website](https://www.ford.com/support/recalls/). (https://www.ford.com/support/recalls/)



## Stolen Vehicle Check

- ✓ This vehicle is not actively declared stolen.



## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2021 Apr 13		Koch Ford Lincoln Edmonton, Alberta, Canada	Service Record	Vehicle serviced
2021 Apr 28		Koch Ford Lincoln Edmonton, Alberta, Canada	Service Record	Vehicle serviced
2021 May 17		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Vehicle colour noted as white
2021 Dec 7		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as white
2022 Jan 13		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Rental Vehicle colour noted as white
2022 Feb 15	9,551 KM	Northstar Ford Fort McMurray Fort McMurray, Alberta, Canada	Service Record	Vehicle serviced
2022 Mar 23		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Rental Vehicle colour noted as white
2022 Aug 29		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as white
2022 Nov 1	11,362 KM	Windsor Motors 1975 Ltd Grande Prairie, Alberta, Canada	Service Record	Vehicle serviced

1FBAX9C82MKA35742



	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2022 Nov 3		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as white
2022 Nov 18		Insurance Records British Columbia, Canada	ANIMAL COLLISION	FRONT CENTER
2022 Nov 18		Insurance Records British Columbia, Canada	Estimate	Estimate Date: n/a FRONT CENTER
2023 May 30	11,840 KM	Bannister Ford - Dawson Creek. Dawson Creek, British Columbia, Canada	Service Record	Vehicle serviced
2023 Aug 4	11,850 KM	Bannister Ford - Dawson Creek. Dawson Creek, British Columbia, Canada	Service Record	Vehicle serviced
2023 Sep 13		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as white
2023 Oct 17	12,085 KM	Windsor Motors 1975 Ltd Grande Prairie, Alberta, Canada	Service Record	Vehicle serviced
2024 Feb 7		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported
2024 May 13		Motor Vehicle Dept. Alberta, Canada	Canadian Renewal	Registration Issued or Renewed New Owner reported Previous Use: Rental Vehicle colour noted as white
2024 Jul 29	28,044 KM	Team Ford Sales Ltd Edmonton, Alberta, Canada	Service Record	Vehicle serviced
2024 Aug 1		Motor Vehicle Dept. British Columbia, Canada	Canadian Renewal	Registration Issued or Renewed Vehicle colour noted as white





# Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)

## ICBC Disclaimer

The information supplied by ICBC is a report of the vehicle's status and the vehicle's claims history. Vehicle status shows whether a vehicle is qualified to be licensed and is used to track:

- vehicles sold by insurance companies as salvage
- salvage vehicles which have been rebuilt, inspected, and relicensed
- wrecked vehicles that have been decommissioned and can only be resold for parts

The vehicle status may not represent the vehicle accurately for a number of reasons, including a written-off vehicle that hasn't been reported to the B.C. vehicle registry or a vehicle with major damage that was repaired by its owner. The vehicle claims history is a report of vehicle damage and includes repairs paid by ICBC and outstanding damage estimates. It may be incomplete for various reasons, including the owner did not make a claim to ICBC or ICBC has denied the claim. In addition, the estimate information may not necessarily reflect the actual cost of repairs, list the area of the vehicle that sustained the greatest force of impact, or indicate the primary area of damage.

Consumers are encouraged to read ICBC's full statement of limitations at <http://apps.icbc.com/registration/vchr/Limitation.html>.

ICBC recommends the vehicle be inspected by a qualified mechanic to obtain a more complete assessment of the vehicle's condition.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User Licence Agreements as each may be amended from time to time by CARFAX Canada.

<https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2024 CARFAX Canada ULC. All rights reserved.





# Vehicle Inspection Report

Date: Dec 03 2024

Page: 1/2

RepairOrder 20048100098001

CYPRESS AUTO BROKERS



2021 FORD TRUCK TRANSIT VAN T350 V6-3496 3.5L DOHC

Odometer In: 32019

VIN: 1FBAX9C82MKA35742

Odometer Out: 32019

Plate: FGFFGF

## VEHICLE WALK AROUND

### Comments

Exterior Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Headlights	<input type="checkbox"/> Brake Lights	<input type="checkbox"/> Turn Signals	
Wiper Blades	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Torn	<input type="checkbox"/> Streaks	<input type="checkbox"/> Rear	
Horn	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> No Sound			
Dash Warning Lights	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Check Engine	<input type="checkbox"/> TRAC	<input type="checkbox"/> ABS	
Oil Light Reset	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> N/A	<input checked="" type="checkbox"/> Reset	<input type="checkbox"/> Oil Change Required	

## UNDER HOOD

### Comments

Battery Test	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> CCA Fail	<input type="checkbox"/> Recharge	<input checked="" type="checkbox"/> N/A	
Belt(s)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Cracked	<input type="checkbox"/> Loose	<input type="checkbox"/> Noise	
Air Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Restricted	<input type="checkbox"/> Mileage	<input type="checkbox"/> N/A	NEW
Cabin Air Filter	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Restricted	<input type="checkbox"/> Mileage	<input type="checkbox"/> N/A	NEW
Coolant	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Low	<input type="checkbox"/> Freeze point	<input type="checkbox"/> PH Level	TOPPED UP
Windshield Fluid	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Low	<input checked="" type="checkbox"/> Topped Up	<input type="checkbox"/> N/A	
Brake Fluid(visual)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Low	<input type="checkbox"/> Dark	<input type="checkbox"/> N/A	

## UNDER VEHICLE

### Comments

Fluid Leaks	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Engine Oil	<input type="checkbox"/> Power Steering	<input type="checkbox"/> Coolant	
CV Boots	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Cracked	<input type="checkbox"/> Leaking	<input type="checkbox"/> N/A	

## AROUND THE WHEELS - FRONT

### Comments

Tire Pressure: Driver Side	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Under Inflated	<input type="checkbox"/> Over Inflated	<input checked="" type="checkbox"/> Filled Up	57 PSI
Tire Pressure: Passenger Side	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Under Inflated	<input type="checkbox"/> Over Inflated	<input checked="" type="checkbox"/> Filled Up	
Tire Tread: Driver Side	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Sugg.(-5/32)	<input type="checkbox"/> Req.(-2/32)	<input type="checkbox"/> Puncture	
Tire Tread: Passenger Side	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Sugg.(-5/32)	<input type="checkbox"/> Req.(-2/32)	<input type="checkbox"/> Puncture	FRONT TIRES @ 15 32/MS
Steering & Suspension	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Loose	<input type="checkbox"/> Leaking	<input type="checkbox"/> Mileage	
Brakes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Sugg.(-4mm)	<input type="checkbox"/> Req.(-3mm)	<input type="checkbox"/> N/A	FRONT PADS @ 9MM

NOTE: Brake inspection may only be performed during a service that includes removal of tires and wheels.

#### Reason Codes

#### Required:

- A - Part no longer performs intended function
- B - Part does not meet a design specification (regardless of performance)
- C - Part is missing

#### Suggested:

- 1 - Part is close to end of useful life (just above discard specifications, or weak, failure likely to occur soon, etc.)
- 2 - Address a customer need, convenience, or request (to stiffen ride, enhance performance, eliminate noise, etc.)
- 3 - To comply with maintenance recommended by the vehicle Original Equipment Manufacturer
- 4 - Technician's recommendation based on substantial and informed experience



# Vehicle Inspection Report

Date: Dec 03 2024

Page: 2/2

RepairOrder 20048100098001

CYPRESS AUTO BROKERS



2021 FORD TRUCK TRANSIT VAN T350 V6-3496 3.5L DOHC

Odometer In: 32019

Odometer Out: 32019

VIN: 1FBAX9C82MKA35742

Plate: FGFFGF

## AROUND THE WHEELS - REAR

### Comments

Tire Pressure: Driver Side	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Under Inflated	<input type="checkbox"/> Over Inflated	<input checked="" type="checkbox"/> Filled Up	75 PSI
Tire Pressure: Passenger Side	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Under Inflated	<input type="checkbox"/> Over Inflated	<input checked="" type="checkbox"/> Filled Up	
Tire Tread: Driver Side	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Sugg.(-5/32)	<input type="checkbox"/> Req.(-2/32)	<input type="checkbox"/> Puncture	
Tire Tread: Passenger Side	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Sugg.(-5/32)	<input type="checkbox"/> Req.(-2/32)	<input type="checkbox"/> Puncture	REAR TIRES @ 15 32/MS
Steering & Suspension	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Loose	<input type="checkbox"/> Leaking	<input type="checkbox"/> Mileage	
Brakes	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Sugg.(-4mm)	<input type="checkbox"/> Req.(-3mm)	<input type="checkbox"/> N/A	REAR PADS @ 9MM

NOTE: Brake inspection may only be performed during a service that includes removal of tires and wheels.

## ADDITIONAL FINDINGS

### Comments

See Comments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/> N/A	
--------------	-------------------------------------	--------------------------	--------------------------	---	--

### Reason Codes

Required:

- A - Part no longer performs intended function
- B - Part does not meet a design specification (regardless of performance)
- C - Part is missing

Suggested:

- 1 - Part is close to end of useful life (just above discard specifications, or weak, failure likely to occur soon, etc.)
- 2 - Address a customer need, convenience, or request (to stiffen ride, enhance performance, eliminate noise, etc.)
- 3 - To comply with maintenance recommended by the vehicle Original Equipment Manufacturer
- 4 - Technician's recommendation based on substantial and informed experience



# AUTOMOTIVE TECHNOLOGIES INC.

## PRESALE INSPECTION FORM

UNIT #: ABK9599

YEAR: 2021

MAKE/MODEL: FORD TRANSIT AWD

VIN: 1FBAX9C82MKA35742

KM: 31,036 KM

### TIRES

BRAND: Falken Wildpeak A/T SIZE: 235/65 R16C

### LIST OF VERIFIED PROBLEMS/FAULTS/POWERTRAIN ONLY

1. FRAME INSPECTION – CRACKED? BENT? ALTERED IN ANY WAY? DESCRIBE FAULT IF ANY

OK

2. ENGINE – ABNORMAL NOISES, MISFIRE OR HESITATION – OK OR NEEDS ATTENTION

OK

3. TRANSMISSION – SHIFTS THROUGH ALL RANGES & GEAR NOISE OR OPERATION

OK

4. TRANSFER CASE – NOISE & OPERATION OR N/A – OPERATIONAL OR NEEDS ATTENTION

OK

5. FRONT DIFFERENTIAL – NOISE & OPERATION OR N/A – OPERATIONAL OR NEEDS ATTENTION

OK

6. REAR DIFFERENTIAL – NOISE & OPERATION OR N/A – OPERATIONAL OR NEEDS ATTENTION

OK

7. MALFUNCTION INDICATOR LIGHTS ON C.E.L., SES LIGHT, ABS LIGHT, BRAKE LIGHT, TPMS, MAINTENANCE LIGHT – PLEASE CIRCLE ONE OR N/A – NOTES BELOW

N/A

**\*NOTE\* THIS INSPECTION DOES NOT COVER LEAKS, SAFETY, INTERIOR, OR MAINTENANCE ITEMS AND ALL SERVICE LIGHTS WILL ONLY BE NOTED FOR THE PURCHASER AND NOT DIAGNOSED.**





Canadian Tire Associate Store 0481  
 KIMBERLEY J. MAK HOLDINGS INC.  
 11969 - 200TH STREET

PAGE: 1  
 DATE: Dec 03 24



**INVOICE**  
**20048100098001**

Maple Ridge, BC V2X 3M7  
 Phone: 604-460-4664 Fax: 604-460-4665  
 e-mail:

GST REG#: 778156117  
 PST REG#: 1107-5287

**SOLD TO:**  
**9104864.0481**  
**CYPRESS AUTO BROKERS**  
**11919 MAPLE MEADOWS WAY**  
  
**MAPLE RIDGE BC V2X 3M7**

2505521817- AMARDEEP  
 MOBILE : 604 780-4270 HOME: 604 465-3313  
 BUSINESS: 604 465-3313 FAX :  
 EMAIL :

COLOUR	VEHICLE DESCRIPTION	PLATE	UNIT#	TAG	ODO IN
WHITE	2021 FORD TRUCK TRANSIT VAN T350 V6-3496 3.5L DOHC	FGFFGF			32019
VIN	VEHICLE OPTIONS			ADV	ODO AUTH
1FBAX9C82MKA35742				IM01	32019
TIME IN	PROMISED	TERMS	GST EXEMPT#	P.O.	ODO OUT
3:00 PM		Cash			32019

QTY	ITEM	DESCRIPTION	WARR	NET	EXT.PRICE
		PST Exemption 10142701			
1	OCCAB10	FORD TRANSIT 350-LOF, CHECK DIFF FLUID , CHECK BRAKES , TIRES ETC		85.95	85.95
0.3h	--FTOIL	Castrol Edge SPT 5W20 Oil Change up to 5 L			Included
5	--0289615	<b>OIL CHANGE LABOUR 80 Dec 03 24</b> Castrol EDGE SPT5W20 208.2L Castrol EDGE Synthetic 208.2L Drum, 5W20	A1		Included
1	--0174515	FRAM MPH10575 OIL FILTER MPH10575 MotoMaster Oil Filter	A1		Included
1	3985339	EHC		.65	.65
5	3985234	EHC		.08	.40
	<b>R SROCS</b>	<b>Reminder: Oil Change (Synthetic) Jun 03 25</b> A reminder will be sent to you on the date above.			
1	SUR	Upgrade package 0174515 FRAM MPH10575 OIL FILTER MPH10575 MotoMaster Oil Filter Engine Oil Capacity Liters 5.70 INCLUDES FILTER CAPACITY Recommended Viscosity 5W-20 NATURALLY ASPIRATED; SYNTHETIC BLEND OIL; MEETING WSS-M2C960-A1 SPECIFICATION Vehicle Inspection Report OK -- UNDER HOOD: Air Filter -- UNDER HOOD: Cabin Air Filter -- UNDER HOOD: Coolant -- AROUND THE WHEELS - FRONT: Tire Pressure: Driver Side -- AROUND THE WHEELS - FRONT: Tire Tread: Passenger Side -- AROUND THE WHEELS - FRONT: Brakes -- AROUND THE WHEELS - REAR: Tire Pressure: Driver Side -- AROUND THE WHEELS - REAR: Tire Tread: Passenger Side -- AROUND THE WHEELS - REAR: Brakes Subtotals Tax out 0.00 Tax in 0.00		2.49	2.49

INVOICE TO:

I hereby authorize you and your employees to carry out the repair work described above and to purchase on my account any parts and materials necessary to carry out the repair work subject to the estimate described above. I hereby authorize you and your employees to operate the vehicle listed above in connection with the repair work, including operation for the purposes of testing, inspection or delivery. I HEREBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repair work authorized hereby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repair work. By signing below I acknowledge and agree to the terms and conditions above and to those printed on the reverse side of this form.

Customer Signature: \_\_\_\_\_

PARTS:	
LABOUR:	
OTHER:	
SUB-TOTAL:	39.95
GST/HST:	41.00
PST:	
<b>TOTAL:</b>	<b>Cont'd</b>





Canadian Tire Associate Store 0481  
 KIMBERLEY J. MAK HOLDINGS INC.  
 11969 - 200TH STREET

Maple Ridge, BC V2X 3M7  
 Phone: 604-460-4664 Fax: 604-460-4665  
 e-mail:

PAGE: 2  
 DATE: Dec 03 24



**INVOICE**  
**20048100098001**

GST REG#: 778156117  
 PST REG#: 1107-5287

**SOLD TO:**  
**9104864.0481**  
**CYPRESS AUTO BROKERS**  
**11919 MAPLE MEADOWS WAY**  
  
**MAPLE RIDGE BC V2X 3M7**

2505521817- AMARDEEP  
 MOBILE : 604 780-4270 HOME: 604 465-3313  
 BUSINESS: 604 465-3313 FAX :  
 EMAIL :

COLOUR	VEHICLE DESCRIPTION	PLATE	UNIT#	TAG	ODO IN	
WHITE	2021 FORD TRUCK TRANSIT VAN T350 V6-3496 3.5L DOHC	FGFFGF			32019	
VIN	VEHICLE OPTIONS				ADV	ODO AUTH
1FBAX9C82MKA35742					IM01	32019
TIME IN	PROMISED	TERMS	GST EXEMPT#	P.O.	ODO OUT	
3:00 PM		Cash			32019	

QTY	ITEM	DESCRIPTION	WARR	NET	EXT.PRICE
1	SS	Technician Comments Subtotals Tax out 0.00 Tax in 0.00 Shop Supplies  <b>Authorized on: Dec 03 2024</b>  THANK YOU FOR YOUR PATRONAGE. PLEASE FEEL FREE TO CONTACT US WITH ANY QUESTIONS OR CONCERNS-GREAT SERVICE=HAPPY PEOPLE  *** Warranty Code Legend ***  A1: 1 YEAR OR 20,000KM exchange warranty for part only when installed in Canadian Tire service. Or 1YEAR exchange for Do IT yourself  *** Global Warranty Message ***  Installed parts warranties applicable only when product is installed at a Canadian Tire Automotive Service Centre, otherwise warranties may vary. Warranty not available for commercial use. A minimum labour warranty of 100 days / 5500 km applies to installed parts unless otherwise stated above. Installed parts warranty starts on the completion date shown on the customer invoice. Please see auto parts staff for cash & carry parts warranties. ***Wheel Retorque*** Canadian Tire checks every tire after installation and retorques to the manufacturer's recommended values. It is recommended to have your wheels retorqued after driving for a short distance to account for any settling that can happen from continuous contact with the road. For added protection, kindly return to this location for a free wheel retorque after driving your vehicle between 50km and 100km. ***PRIVACY TERMS*** Canadian Tire Corporation, Limited, its affiliates, Associate Dealers, and service providers ("CTC" or "our") collect and use the personal information provided by you to fulfill this contract. CTC may also collect and use your information to administer the delivery of and market warranties, products, services, and loyalty programs to you, and to analyze your relationship with us. Please visit <a href="http://www.canadiantire.ca">www.canadiantire.ca</a> for details on CTC's privacy policy. If you do not wish for your information to be kept in our database, please contact CTC's Corporate Customer Relations at 1-866-846-5841 or via email at <a href="https://www.ctfs.com/ContactUs/">https://www.ctfs.com/ContactUs/</a> .		N/C	N/C

INVOICE TO:

I hereby authorize you and your employees to carry out the repairwork described above and to purchase on my account any parts and materials necessary to carry out the repairwork subject to the estimate described above. I hereby authorize you and your employees to operate the vehicle listed above in connection with the repairwork, including operation for the purposes of testing, inspection or delivery. I HEREBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repairwork authorized hereby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repairwork. By signing below I acknowledge and agree to the terms and conditions above and to those printed on the reverse side of this form.

Customer Signature: \_\_\_\_\_

PARTS:	
LABOUR:	
OTHER:	
SUB-TOTAL:	
GST/HST:	
PST:	
<b>TOTAL:</b>	<b>Cont'd</b>





Canadian Tire Associate Store 0481  
 KIMBERLEY J. MAK HOLDINGS INC.  
 11969 - 200TH STREET

PAGE: 3  
 DATE: Dec 03 24



Maple Ridge, BC V2X 3M7  
 Phone: 604-460-4664 Fax: 604-460-4665  
 e-mail:

**INVOICE**  
**20048100098001**

GST REG#: 778156117  
 PST REG#: 1107-5287

SOLD TO:  
 9104864.0481  
**CYPRESS AUTO BROKERS**  
**11919 MAPLE MEADOWS WAY**  
  
**MAPLE RIDGE BC V2X 3M7**

2505521817- AMARDEEP  
 MOBILE : 604 780-4270 HOME: 604 465-3313  
 BUSINESS: 604 465-3313 FAX :  
 EMAIL :

COLOUR	VEHICLE DESCRIPTION	PLATE	UNIT#	TAG	ODO IN
WHITE	2021 FORD TRUCK TRANSIT VAN T350 V6-3496 3.5L DOHC	FGFFGF			32019
VIN	VEHICLE OPTIONS			ADV	ODO AUTH
1FBAX9C82MKA35742				IM01	32019
TIME IN	PROMISED	TERMS	GST EXEMPT#	P.O.	ODO OUT
3:00 PM		Cash			32019

QTY	ITEM	DESCRIPTION	WARR	NET	EXT.PRICE
	***Tire Storage Terms***	Storage term: (applicable only to customers who have purchased tire storage) Tires will be stored up to a maximum of 8 months from Invoice date OR until customer requests to have Tires removed from the storage location for any reason, at which point the storage term will end. Canadian Tire is not responsible for unclaimed tires at expiration of storage term. Tires left beyond 30 days of term expiration date will be disposed of without any liability or obligation to customer. Payment for Tire Storage is deemed to be acceptance of these terms by customer.			

INVOICE TO:

I hereby authorize you and your employees to carry out the repairwork described above and to purchase on my account any parts and materials necessary to carry out the repairwork subject to the estimate described above. I hereby authorize you and your employees to operate the vehicle listed above in connection with the repairwork, including operation for the purposes of testing, inspection or delivery. I HEREBY RELEASE AND FOREVER DISCHARGE YOU AND EACH OF YOUR EMPLOYEES FROM ANY LOSSES I MAY SUFFER RELATING TO DAMAGE TO OR LOSS OF MY VEHICLE AND/OR ANY ITEMS CONTAINED THEREIN THAT ARE CAUSED BY CIRCUMSTANCES BEYOND YOUR CONTROL. I acknowledge that, upon the completion of the repairwork authorized hereby, you will have a lien pursuant to applicable repair and storage lien legislation and that you may register that lien and seize, at your discretion and at my sole cost and expense, the vehicle for non-payment of any invoice issued for such repairwork. By signing below I acknowledge and agree to the terms and conditions above and to those printed on the reverse side of this form.

PARTS :	44.95
LABOUR :	41.00
OTHER :	3.54
SUB-TOTAL :	89.49
GST/HST :	4.47
PST :	N/C
<b>TOTAL :</b>	<b>93.96</b>

Customer Signature: \_\_\_\_\_