

# 2016 NISSAN ROGUE S

Sport utility vehicle | 4 Cylinders | Gas  
5N1AT2MV1GC841374  
Country of Assembly: United States  
Last Reported Odometer: 105,789 KM

No Reported Accidents 



No Accident/Damage Records Found



Last Registered In: Ontario (Normal)



7 Service Records Found



No U.S. History Found



1 Open Recall Found



Not Actively Declared Stolen



No Import Record Found

Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)

5N1AT2MV1GC841374



This vehicle history report is based on **information** (<https://www.carfax.ca/vehicle-history-data>) that was reported and available to CARFAX Canada as of July 10, 2024 (or once all the data was collected from our data sources and the report was complete). CARFAX Canada draws on billions of data records from thousands of sources across North America, and we receive new historical data records every day. **There may be other information**

**about this vehicle that has not been reported to CARFAX Canada.** When buying a used vehicle, we always recommend using a CARFAX Canada Vehicle History Report, along with a vehicle inspection and test drive, to make an informed decision.

# Vehicle History Report



## Accident/Damage

✓ There are no accidents/damage reported on this vehicle.



## Registration

✓ This vehicle has been registered in the province of **Ontario** in **Canada** with **Normal** branding.

**We checked for:** *Inspection Required, Normal, Non-repairable, Rebuilt, Salvage and Stolen.*



## Service Records

DATE	ODOMETER	SOURCE	DETAILS
2022 Apr 26	71,035 KM	Klingenberg Auto Repair Woodstock, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>• Recommended maintenance performed</li><li>• Maintenance inspection completed</li><li>• Wiper(s) replaced</li><li>• Tire condition and pressure checked</li><li>• Fluids checked</li><li>• Windshield washer checked</li><li>• Oil and filter changed</li><li>• Air filter replaced</li><li>• Tires rotated</li><li>• Exterior light bulb(s) replaced</li><li>• Heat shield secured</li><li>• Cabin air filter replaced/cleaned</li><li>• Lights checked</li></ul>
2022 Aug 24	76,922 KM	3 Bay Sales and Service Waterloo, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>• Camshaft adjuster solenoid replaced</li></ul>
2022 Oct 7	79,518 KM	Jiffy Lube Kitchener, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>• Oil and filter changed</li></ul>
2023 May 8	89,396 KM	3 Bay Sales and Service Waterloo, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>• Oil and filter changed</li><li>• Tire(s) mounted</li></ul>
2023 Jun 23	91,535 KM	3 Bay Sales and Service Waterloo, Ontario, Canada	<b>Vehicle serviced</b> <ul style="list-style-type: none"><li>• Evaporative emissions vent purge valve replaced</li></ul>

- Engine/powertrain computer/module checked

2023 Dec 1 102,052 KM 3 Bay Sales and Service  
Waterloo, Ontario, Canada

**Vehicle serviced**

- Oil and filter changed
- Four tires mounted

2024 Apr 16 105,789 KM 3 Bay Sales and Service  
Waterloo, Ontario, Canada

**Vehicle serviced**

- Recommended maintenance performed
- A/C refrigerant recharged
- A/C condenser replaced
- Tire(s) mounted
- A/C system checked



## Open Recalls

Recall #: R21B9 | ROUGE WIRE HARNESS NTB22-076 Recall Date: 2022 Jan 25

**Recall Description**

IN AFFECTED VEHICLES, IF WATER AND SALT COLLECT IN THE DRIVER S SIDE FOOT WELL, IT MAY WICK UP THE DASH SIDE HARNESS TAPE AND ENTER THE CONNECTOR. IF THIS OCCURS, THE DASH SIDE HARNESS CONNECTOR MAY CORRODE AND POSSIBLY CAUSE ISSUES SUCH AS DRIVER S POWER WINDOW OR POWER SEAT INOPERATIVE, ALL-WHEEL DRIVE (AWD) WARNING LIGHT ON, BATTERY DISCHARGE, AND/OR THERMAL DAMAGE TO THE CONNECTOR. IN RARE CASES, THE CORROSION COULD POTENTIALLY LEAD TO A FIRE, WHICH MAY INCREASE RISK OF INJURY.

**Remedy**

YOUR NISSAN DEALER WILL INSPECT YOUR VEHICLE AND PERFORM THE APPROPRIATE REPAIR 1) IF CORROSION IS PRESENT ON EITHER THE MAIN HARNESS OR THE BODY HARNESS CONNECTORS, THE DEALER WILL REMOVE THE HARNESS TAPE AND HARNESS COVERING, REPLACE BOTH CONNECTORS AND APPLY WHITE LITHIUM GREASE TO THE CONNECTORS 2) IF CORROSION IS NOT PRESENT ON EITHER OF THE CONNECTORS, THE DEALER WILL REMOVE THE HARNESS TAPE AND HARNESS COVERING AND APPLY WHITE LITHIUM GREASE TO THE CONNECTORS. THIS SERVICE WILL BE CONDUCTED AT NO CHARGE TO YOU FOR PARTS AND LABOR, AND MAY TAKE UP TO TWO (2) HOURS TO COMPLETE IF YOUR HARNESS CONNECTORS REQUIRE REPLACEMENT. HOWEVER, YOUR NISSAN DEALER MAY REQUIRE YOUR VEHICLE FOR A LONGER PERIOD OF TIME BASED UPON THEIR WORK SCHEDULE.

This recall was open as of the date/time that this report was generated. For more information, or to find out if the recall has been closed, please contact NISSAN or visit [Nissan's website](https://www.nissanusa.com/recalls-vin.html). (https://www.nissanusa.com/recalls-vin.html)



## Stolen Vehicle Check

✓ This vehicle is not actively declared stolen.



## Detailed History

DATE	ODOMETER	SOURCE	RECORD TYPE	DETAILS
2016 Sep 1		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed First Owner Reported Previous Use: Personal Vehicle colour noted as silver
2017 Jan 10		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2019 Jan 10		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2020 Feb 27		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal
2020 Sep 18	53,000 KM	Independent Source Guelph, Ontario, Canada	Odometer reading	
2020 Sep 23		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner Reported
2020 Dec 8		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	New Owner reported Vehicle colour noted as silver
2022 Jan 25		NISSAN	Recall	Manufacturer Recall Issued Recall # R21B9
2022 Apr 26	71,035 KM	Klingenberg Auto Repair Woodstock, Ontario, Canada	Service Record	Vehicle serviced
2022 Aug 13		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed

				Previous Use: Personal Vehicle colour noted as silver
2022 Aug 24	76,922 KM	3 Bay Sales and Service Waterloo, Ontario, Canada	Service Record	Vehicle serviced
2022 Oct 7	79,518 KM	Jiffy Lube Kitchener, Ontario, Canada	Service Record	Vehicle serviced
2023 May 8	89,396 KM	3 Bay Sales and Service Waterloo, Ontario, Canada	Service Record	Vehicle serviced
2023 Jun 23	91,535 KM	3 Bay Sales and Service Waterloo, Ontario, Canada	Service Record	Vehicle serviced
2023 Dec 1	102,052 KM	3 Bay Sales and Service Waterloo, Ontario, Canada	Service Record	Vehicle serviced
2024 Apr 16	105,789 KM	3 Bay Sales and Service Waterloo, Ontario, Canada	Service Record	Vehicle serviced
2024 Jul 4		Motor Vehicle Dept. Ontario, Canada	Canadian Renewal	Registration Issued or Renewed Previous Use: Personal



Questions? We're here to help.

Visit us at [support.carfax.ca](https://support.carfax.ca)

**CARFAX Canada No Reported Accidents™ Badge**

The CARFAX Canada No Reported Accidents™ badge is based on the damage records and/or branding information reported to CARFAX Canada. The badge is available for personal vehicles that have only been registered in Canada, and were not, at the time this report was generated, declared stolen.

This vehicle history report is compiled from multiple data sources. It is not always possible for CARFAX Canada ULC or its source data providers to obtain complete information on any one vehicle. For example, there may be other title, brands, registrations, declarations, accident information, service records, recall information, odometer readings or other information where discrepancies that apply to this vehicle are not reflected in this report. CARFAX Canada and its source data providers receive data and information from external sources believed to be reliable, but no responsibility is assumed by CARFAX Canada, its source data providers or its agents for any errors, inaccuracies or omissions. The reports are provided strictly on an as-is where-is basis, and CARFAX Canada and its source data providers further expressly disclaim all warranties, express or implied, including any warranties of timeliness, accuracy, merchantability, merchantable quality or fitness for a particular purpose regarding this report or its contents. Neither CARFAX Canada nor any of its source data providers shall be liable for any losses, expenses or damages in connection with any report or any information contained within a report, including the accuracy thereof or any delay or failure to provide a report or any information. Other information about the vehicle that is the subject matter of this vehicle history report, including problems, may not have been reported to CARFAX Canada. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car. By obtaining, reviewing and/or using this vehicle history report, you agree to be bound by all of the terms and conditions in CARFAX Canada's Conditions of Use and any CARFAX Canada End User License Agreements as each may be amended from time to time by CARFAX Canada. <https://www.carfax.ca/about-carfax/privacy-legal/conditions-of-use>

© 2024 CARFAX Canada ULC. All rights reserved.

